

Headlamp Components



1962-79 Headlamn Bulh

Replacement sealed headlamp bulbs. 6014

1962-78 Tungsten 7" round 11.99 ea 1962-78 Halogen 7" round.... 11.99 ea Halogen rectangular 14.99 ea H6054 1979



Diamond Cut Headlamn

Unique looking Halogen diamond cut headlamps for increased visibility, safety and a unique custom look. These headlamps install much like a standard sealed beam unit, but allow the use of an H4 Halogen bulb in your choice of color. The diamond cut reflector concentrates the beam on the road in front of you. Sold separately. For 2 headlamp system.

Note: For your conversion, we recommend using our wiring harness upgrade kit sold separately.

MX09137 7" round MX09124 5-1/2" x 8" rectangular 21.99 ea





Round Crystal Headlamp

Replace your burnt out or missing headlamps with these crystal headlamps. Features reinforced multi-surfaced. aluminum reflector, rugged anti-vibration construction. Includes a 12V 65/55W Halogen bulb. Sold individually. CP500126 7". 38 99 ca





Halogen Headlamps with Adjustment Knubs

Replacement Halogen headlamps with adjusting knubs for various models equipped with 7" round headlamps. Manufactured to offer superior modern light distribution while providing appearance correct lamps. Both lamps feature small knubs that were used to aim the light emitted by the lamps. Uses H4 series bulbs. Bulbs not included. 7" round

HEADLAMP PARTS





CP500122

7" Crystal Headlamp Bulb w/Auxiliary LEDs

These crystal headlamps with auxiliary LEDs give your classic ride a modern look. The aluminum reflector is a reinforced, multi-faceted design for maximum vibration resistance. A HB2/9003 65/55W 12V Halogen bulb replaces H6017/H6024 bulbs to meet DOT/SAE standards, Choose from 10 or 34 I FD auxiliary lighting

10 LED Bulb	amber LEDs	44.00 -
34 LED Bulb	amber LEDs	44.99 e
	amber LEDswhite LEDs	
	winte LEDs	02.99 0





7" High Power 11 LED Crystal Headlamp

This 7" crystal headlamp uses eleven high power LED to improve visibility, providing a white light similar to daylight. An impact resistant polycarbonate lens provides unparalleled protection from road hazards, while the solid state design resists shock and vibration. Meets SAE/DOT FMVSS108 standards.

316 99 69





Tri-Rar Custom Headlamn

Add a new look to your classic car with these custom headlamps. Manufactured with a metal housing and glass lens to meet high-quality standards. The 7' features an inner 1 piece chrome glare shield with black chrome-plated center dot, and flat style lens. Dust boot and clear Halogen bulb included with each lamp. flat glass 69 99 ca













Projector Style Headlamps

Embody the classic look while substantially upgrading the quality and spread of light! The unique hi-low switch design provides a clean and safe light cutoff design, eliminating the issue of "headlight dazing" on the roads. Each unit features a 42mm Bi-Xenon projector (high and low beams) with adjustable light focus and flat light distribution to prevent blinding of oncoming traffic. Available with a traditional chron housing or with a black housing and city light built into the unit. Bulbs and wiring included.

7" round chrome housing... 269.99 pr 152828 7" round 7" x 6" 7" x 6" black housing... 274.99 pr chrome housing... 269.99 pr 152830 152831 black housing 274.99 pr



IFN Powered Headlamns

Powerful LED CREE® technology combined with Delta Tech's Prismatic lens and flawless parabola delivers unmatched power, clarity and near daylight illumination at 1900 Lumen at both high and low beam, while drawing only 2 amps per light. Each unit features an additional LED bulb that can be wired as a driving light, turn signal, park lamp, or even as a mood light.

Available in your choice of classic looking convex lens or modern style flat lens. Applications to fit two or four headlamp systems.


7" Classic Convex Lens High/Low Beam for 2 Headlamp System with amber blinker...

153109 309.99 pr with white blinker " Modern Style Flat Lens High/Low Beam for 2 Headlamp System

309.99 pr 153110 with amber blinker with white blinker 281 99 pr

309.99 pr

Headlamp Components









Round Headlamps with LED Halo

RedLine LumTronix headlamps allow 50% more light to shine through thanks to their crystal clear lenses and a special side lens that extends past the retaining ring. This side lens is a true safety innovation and was designed to provide additional side light and increase visibility. Each headlamp features a Euro style diamond cut reflective base, diamond crystal glass, and a heat resistant composite housing. Even though no paint or tint is applied to the glass or reflector, the Black Illusion headlamps look blacked out when off thanks to the halo and lamp shields that are painted black. Headlamps are available with or without a halo, either single color halo (white) or multi-color halo (with 16 selectable colors plus the ability to adjust brightness), with or without turn signals and your choice of clear or blue H4 halogen bulbs or H4 LED bulbs. The halo or "Angel Eyes" can also be wired as a daytime running lamp and features 23 low temp LEDs with a 100.000+ hour life, along with "fade", "flash", "strobe", and "smooth" modes that you can choose with the included wireless remote. Headlamps plug directly into your stock harness for a simple and easy installation. Each pair includes: 2 headlights, 2 bulbs, dust boots, ceramic tip pigtail harness adapter, and instructions. Multi-color halo sets also include the RGB harness and wireless remote

portant: Will fit most vehicles (cars, trucks, motorcycles and motor homes) made from 1936 to 1979, as well as many vehicles made after 1979 that use a universal round style headlight. Note: Blue Halogen bulbs are blue in color when off, and bright white when on (no blue tint). Clear Halogen bulbs are clear in color when off and bright white when on. LED bulbs

include colored film to change the look and temperature color of your lights.					
7" Round White Diamond Headlamps					
Without Hal	o Ring				
H4100101	7"	with blue H4 Halogen bulbs	89.99 pr		
H4100102	7"	with H4 NovaStar LED bulbs	249.99 pr		
		hite) Halo Ring			
H4103201	7"	with blue H4 Halogen bulbs			
H4103202	7"	with H4 NovaStar LED bulbs	334.99 pr		
With Single	Color (W	hite) Halo Ring and Turn Signals			
H4103204	7"	with blue H4 Halogen bulbs	244.99 pr		
With Multi-0	Color Ha	lo Ring			
H4103001	7"		249.99 pr		
H4103002	7"	with H4 NovaStar LED bulbs	389.99 pr		
With Multi-0	Color Ha	lo Ring and Turn Signals			
H4103004	7"	with blue H4 Halogen bulbs	299.99 pr		
Black Illusio H4103203	n White 7"	Diamond Headlamps w/Single Color (White) H with clear H4 Halogen bulbs	alo Ring 244.99 pr		
DIL III	W.L.	D:			

with clear H4 Halogen bulbs







LED Projector Headlamps with Perimeter Halo

Dapper lighting LED projector headlamps provide the classic look while substantially upgrading the quality and spread of light. These replacement bulbs feature glass lenses, Bi-LED projectors, and a slim flat base design. These features eliminate the extra wiring and bucket modifications associated with HID lighting. They offer a quick and clean install and a significant increase in performance, reliability, and safety. Available with clear or black lenses and with or without halos. The halos are available in solid, dashed, and HDR styles.

DL700		black	with HDR halo	579.99	pr
DL700		black chrome	with dashed halo with HDR halo		
DL700		black chrome	with solid halo with dashed halo		
DL700		chrome	with solid halo	479.99	pr
DL700)1B	black	without halo		
7" LE.	D Head	lamp chrome	without halo	399 99	nr







Oracle 7" Hain Headlamn

Quality glass lens sealed beam with composite reflector housing. Accepts H4 bulbs (sold separately). SMD (LED) halo pre-installed. Easy installation, wire directly to 12 Volt source. No external inverter or regulator required. Available in white, amber, green, blue, and red. Sold individually.

7" SMD Halo HL70001A		113.99 e
HL70001B	blue	124 99 c
HL70001C	red	124.99 e
HL70001D	green	124.99 e
HL70001E	amber	124.99 e





H4 LED Headlight Bulbs

Upgrade your stock Halogen bulbs with a pair of premium LED headlight bulbs from Redline Lumtronix. With a 50,000 hour lifespan, you won't have to change the bulbs as frequently, meaning you'll spend more time on the road than in the garage. Each bulb is 300% brighter than your stock Halogen bulbs as well as a direct-fit, "Plug and Play" upgrade that requires no modification to your electrical wiring. LED bulbs include colored film to change the look and temperature color of your lights. H4100602 NovaStar GT H4 LED bulbs.














PAINI ESS

30803



Headlamp Components

AUTHORIZED

1969-79 Headlamn Socket/Wiring 🔔

A molded plastic socket used to connect the headlamp bulb. The socket has wire leads and connects the bulb to the power source. Fits 1969-79 Nova models. WE303 1969-79 3 prong 2.99 ea

WE311 1969-79 2 prong 6.99 ea

Auxiliary Light Relay Set

Install extra driving or fog lights easily and properly with our auxiliary light relay set. Switch can be wired

to turn lights on per state law requirements; low beams and auxiliary lamps, high beams and auxiliary lamps,

Auxiliary lamp operation only. Set includes: lighted

switch, wiring harness, 30 amp relay, and terminals.

PAINLESS



HID HeadLamp Bulbs

HID headlamp bulbs are much brighter than conventional Halogen bulbs, while providing tight light focus for better light distribution. They require
35 watts and use an external regulator, but will plug into the existing light plug. The H4 series bulb features a bright white HID low beam and a Halogen high beam function

Important: Not for use on public roads. LHH4 H4 6000k - white 49.99 set



Ultra Bright Halogen Headlamp Bulbs

Upgrade your lighting to Ultra Bright Halogen bulbs and enjoy a light that simulates daylight and reduces glare, fatigue, and eye strain. Available in a variety of bulb types and wattages to fit your specific needs wattage than rade harness

stock, we rec sold separate	ommend inst	talling our upgrad	ie harness
MX01108		high/low	12.99 ea
9006 Series . MX01113		low	12.99 pr
9005 Series MX01110 MX01109	65W	highhigh	

9007 Series	Bulb		
MX01112	65/55W	high/low	6.99 ea
H4 Series B			
542212	60/55W	high/low	13.99 pr
MX01106	100/80W	high/low	15.99 pr

Halogen Headlamp Harness

To get maximum power from your headlights, it is recommended to have the shortest possible distance between the power source and the bulbs. Resistance in small gauge wire or in the switch will lower the output at the lamp. Our headlamp harnesses draw power directly from the battery, through a relay, to the headlamps, providing full power to your H4 conversion headlamps or Halogen sealed beams. They are made with TXL high temp wire, weather resistant 30 amp fuse, and two 40 amp weather resistant relays capable

	r " c .		
30816	Headlamp System for 9004/9007 bulbs	109.99 ca	
	Headlann System	10).)) си	



H4 Xenon Hyper White Headlamp Bulbs

Upgrade your lighting to Hyper White Xenon Bulbs and enjoy a light that simulates daylight and reduces glare, fatigue, and eye strain. These Xenon replacement bulbs light up the night to increase driving safety and night time visibility. Sold as a pair.

9006 Serie. MX01111	s Bulb 80W		24.99 pr		
H4 Series Bulb					
542212X	60/55W	high/low	19.99 pr		
545812X	100/80W	high/low	22.99 pr		
546912	130/90W	high/low	24.99 pr		

Relay and Fuse Assembly

Protect your investment with this 5 prong 30 amp relay and 20 amp fuse set with 14 gauge wire leads 200011 relay/fuse.. . 7.99 ea

authorized

Headlamp Wiring Harness Upgrade 🔥 Our wiring harness set upgrades the thin stock headlamp

wiring on your vehicle, providing your new bulbs with maximum power and decreasing the chance of overloading (and possibly melting) your stock wiring and headlamp connectors. Power will be drawn directly from your battery, eliminating voltage drops and ensuring headlamp system reliability. Two 30 amp relays provide added protection for your headlamp switch and wiring harness.

MX01131	for 4 bulb system	24.99 set
H4 MX01132		
MX01133	for 4 headlamp system	24.99 set

Chrome Headlamn Half Shields

Keep your headlamps clean while adding a custom chrome appearance. The chrome headlamp shields attach to the upper portion of the headlamp and offer a custom look. For round 7-1/2" diameter headlamps. T9512



1962-78 Headlamp Retaining Ring OER® reproduction of the original stamped steel

headlamp retaining rings for 1962-78 Chevy II/Nova models. Each headlight ring is designed to hold the sealed beam into the mounting bucket. Triple chromeplating protects against corrosion while providing a brilliant shine. Sold individually. Use as required. 5950248 1962-74 LH or RH 12.99 ea 5964574 1975-78 I.H or RH 24 99 ca

Headjamp Components



1979 Headlamp Retaining Ring

Genuine GM headlamp bulb retaining ring, which is used to hold the headlamp bulb to the mounting bucket. The rings are a current service replacement part and may differ cosmetically from the original. G8971 1979 LH or RH 63.99 ea







1962-79 Ream Retaining Ring Screw Zinc 8-32 x 3/8" headlamp retaining ring screws are

used to hold the headlamp bulb to the mounting bucket. Use as required. Replaces GM #924552 and 5959530

A9400115 1962-79 6 piece 3.99 set



1962-79 Headlamo Adjusters The correct hardware will make your installation easier, and give your classic a finished look. We offer

replacementheadlampadjustersets for 1962-79 Chevy II/ Nova models. All sets include adjusters for both right and left sides. C1403 6 99 set 6.99 set

C1402 1969-79







1962-68 Headlamn Adjusting Screw/Nut

Original style self-retaining nylon nut and 1/4"-28 x 1" screw assembly used for headlamp beam adjustment on 1962-68 Chevy II/Nova models. This nut and screw mounts directly to the headlamp housing to enable the headlamp beam to be aimed correctly. Snaps into the rectangular hole in the sheet metal. Sold individually, use as required. 4 required per vehicle.

Adjuster	Screw and Nut	
A5789	1962-68	1.99 ca
Adjuster	Nut	



1962-74 Headlamo Beam Adjusting Spring

Adjusting spring for headlamps. These headlamp springs allow your headlight beams to pivot for the proper alignment. 5953168 1962-67 LH or RH 2.79 ca LH 2.79 ea 5953168 1968-74



1969 Headlamo Washer Nozzle Set

This is a high-quality triple chrome-plated reproduction headlamp washer nozzles. These nozzles are used to wash the headlamp lens when the windshield wash switch is activated. Mounting hardware not included. 1969 4 piece...... 29.99 set









1969 Headlamn Washer Nozzle Hardware

This set includes the correct polished chrome washers and chrome nuts which, when installed, will look virtually the same as if the factory installed it. Includes 4 polished washers and 4 polished nuts. KW158A 1969...



1966-79 Headlamp Bezel Nvlon Anchor Nut Attachment nut for 1966-79 Chevy II/Nova headlamp

bezels. Use as required. Attachment nut for headlamp bezels, grill, or side marker. For #8 screw size, 5/16* square hole, panel range 1/16" - 5/32".

347347 1966-79 nvlon anchor nut 1.99 ea





Headlamo Bezel Screw

Correct hardware can make any installation job easier. Replace your missing or damaged hardware with this quality reproduction of these headlamp bezel screws. These screw are designed for Chevy II/Nova models. Used to mount the bezel to the body.

#0 X 1/2	wun #0 rreaa	
2027	chrome	.79
#8 x 3/4"	with #6 Head	
SW500	black	.49





1962-64 Chevy II/Nova Headlamp Bezels

OER® headlamp bezels for 1962-64 Chevy II/Nova models. Each bezel is correctly stamped in bright finished aluminum to factory specifications and features the correct contours for an original fit and appearance. 3790349 1962-64 LH... 70 00 00 2700250 1962-64 RH 79 99 ca



1965 Chevy II/Nova Headlamp Bezel Reproduction of the original headlamp bezel designed

for use on all 1965 Chevy II/Nova models. This aluminum headlamp bezel is manufactured to factory specifications for an original appearance and fit. Sold individually. 2 required per vehicle. 14378 1965 2 required ... 61 99 ca

GM Restoration Parts



1966 Chevy II/Nova Headlamn Bezels OER® headlamp bezels for 1966 Chevy II/Nova models

Each bezel is correctly stamped in bright finished aluminum to factory specifications and features the correct contours for an original fit and appearance. 79.99 ea 3866885 1966 LH or RH.....





YOO E

COMPONENTS

1967 Headlamp Bezels OER® headlamp bezels for 1967 Chevy II/Nova

models. These chrome-plated die-cast bezels are manufactured to factory specifications for an authentic fit and original appearance. Features correct black painted details as original. Made in USA. 3892281 IH

1967 ... 129.99 ea 3892282 1967 RH 129 99 ca













Headlamp Bezels







1968 Headlamp Bezels OER® headlamp bezels for 1968 Chevy II/Nova

models. These chrome-plated die-cast bezels are manufactured to factory specifications for an authentic fit and original appearance. Features correct black painted details as original. Chrome Face

1968 exc. Super Sport...... 119.99 pr Black Face 16129 1968 Super Sport...... 119.99 pr



11111111

1969-72 Headlamp Bezels OER® made in USA, Restorer's Choice™, and

standard replacement headlamp bezels for 1969-72 Nova models. These chrome-plated die-cast bezels are manufactured to factory specifications for an authentic fit and original appearance. Features correct black

painted details as original. ote: Not for use on 1969 models originally equipped with adlight washers.

OER® - M	lade in USA			
3949789	1969-72	LH	119.99	ca
3949790	1969-72	RH	119.99	ea
OER® Res	storer's Cho.	ice TM		
C1671	1969-72	LH and RH	139.99	pr
	Replacemen	t I H and R H	94 99	nr

1968-72



1975-78 Headlamp Bezels OER® headlamp bezels for 1975-78 Nova models.

Each reproduction headlamp bezel is injection molded to factory specifications with correct contours for an original appearance and fit.

Silver Face with Bright Silver Edge 1975-78 LH standard...... 89.99 ea 1975-78 RH standard...... 89.99 ea 360627 360628 Black Face with Bright Silver Edge 360607 1975-78 LH Super Sport., 99,99 ea 1975-78 Super Sport... 99.99 ea Rally...... 99.99 ea 360608 RH 360607 1976-78 LH 360608 1976-78 RH Rally. ... 99.99 ca Chrome 1976 IН Concours 99.99 ea Concours 99.99 ea

368112 1976 RH



1966 Headlamp Bucket Housing

Reproduction headlamp bucket housings for 1966 models. These housings attach to the radiator support and hold the headlamp components in place. N62103 1966 LH 88.99 ea N62102 1966 RH...... 88.99 ea



1967 Headlamn Bucket Housing

	tion head						
	hese hous					opo	rt
and hold	the headla	mp com	ponents	s in plac	e.		
N62105	1967	LH			88.9	9 e	а
N62104	1967	RH			88.9	9 e	a



1966-74 Headlamp Mounting Bucket 🔥 Reproduction headlamp mounting buckets which

are designed to secure the headlamp sealed beam in position. These buckets attach to the headlamp housing using adjustment screw and nut assemblies. 1966-67 LH...... 24.99 ea

Á			
K893	1968-74	LH	24.99 ea
K892	1968-74		24.99 ea



1975-79 Headlamo Mounting Bucket 🔥

These headlamp mounting buckets are designed to secure the headlamp sealed beam in position. These buckets attach to the headlamp housing using adjustment screw and nut assemblies

5964577 1975-78 LH or RH - repro.... 18.99 ea G5251 1979 LH or RH - GM..... 74.99 ea



1962-65 Headlamo Bucket Shields 🔥 Replace your commonly rusted metal headlamp bucket

shields with these excellent plastic reproductions. They can be painted any color to match your classic Chevy II/

Nova. Sold in pairs only. C2605 1962-65 LH and RH 46.99 pr



1966-67 Headlamp Filler Panels

Reproduction headlamp filler panels (headlamp mud caps). These reproductions will replace the original aluminum style filler panels which are commonly bent, corroded or missing. Installs directly on either side of the radiator support assembly covering and protecting the area directly behind the headlamp assemblies. A26004 1966-67 LH and RH ...

7 99 set

à

Park Lamps





1962-64 Park Lamp Assemblies 🔥 OER® park lamp assemblies for 1962-64 Chevy II/ Nova models. Each park lamp includes the housing, injection molded acrylic lens, socket connector, and

bulb. Rea	dy-to-instal	1!		
926327	1962	LH	clear	
926328	1962	RH	clear	
897286	1963-64	LH	amber	39.99 ca
897287	1963-64	RH	amber	39.99 ca



1965 Park Lamp Assembly Reproduction park lamp assembly for 1965 models.

Each park lamp includes the housing, lens, and wiring. 2 required per vehicle. A26005 1965 LH

A20000	1905	KH	amber 52.99 ea
		8	A26007

1966-67 Park Lamp Assembly

Reproduction park lamp assembly for 1966-67 models. Each park lamp includes the housing, lens, and wiring. 2 required per vehicle. A26007 1966-67 LH. 1966-67 RH

A26007 A26008	1966-67	RH	54.99 ca
	ſ		63
GN Restora Parts	tion		
7		HOT	
_ (
•			

1968-69 Park Lamp Assembly

Reproduction park lamp assembly for 1968-69 models. Each park lamp includes the housing, lens. and wiring. 2 required per vehicle. 1968-69 916211 59 99 ca



1970 Park Lamp Assembly

Reproduction park lamp assembly for 1970 models. Each park lamp includes the housing, lens, and wiring. 2 required per vehicle. A 26000 1970 I.H or RH..... 49.99 са

Assessment of the last	
	9

1971-72 Park Lamp Assembly

Reproduction park lamp assembly for 1971-72 models. Each park lamp includes the housing, lens, and wiring. 2 required per vehicle.





1973-74 Park Lamp Assembly Reproduction amber park lamp assembly for 1973-74

Nova models. Includes the housing, lens with original style "Guide" markings, socket with wiring pigtail, and bulb. Fits LH or RH side, 2 required. 897087 1973-74 LH or RH... 40 00 00



1975 Nova Park Lamp Assembly OER® reproduction park lamp assemblies for 1975

Nova models. The amber lens assembly is for standard Nova models and the clear lens assembly is for super sport and luxury models. Socket bulb and wiring not included. Fits LH or RH side 2 required per vehicle. amber lens...... 24.99 ea 011970 912008 24 99 ca clear lens

1976-77 Park Lamp Assembly

Manufactured by OER®, these install into the front grill area of 1976 and 1977 1st design Nova models. Each lens features a painted white Bow Tie logo on the lens and correct stamped SAE. Guide and GM part number markings in the proper locations. Choose from the lens and housing assembly only or the full assembly which



LH

RH

1976-77 1977-78 Park Lamp Assembly

Manufactured by OER®. these install into the front grill area of 1977 2nd design and 1978 Nova models Each lens features a Bow Tie logo on the lens and correct stamped SAE, Guide and GM part number markings in the proper locations. Choose from the lens and housing assembly only or the full assembly which includes the lens

944333

944332



31.99 ca

housing, bulb, socket with pigtail, and hardware. Note: Not for use with Rally models. I one and Housing Only

913401	1977-78	LH		
913402	1977-78	RH	24.99 c	ėa
	r use with Rali	ly models. Socket wiri	ng requir	ne:
	the factory wi			
944331	1977-78	LH		
944330	1977-78	RH	31.99	à



1976-78 Nova Rally Park Lamp Assembly Reproduction park lamp assembly for 1976 Nova SS and 1977-78 Nova Rally models equipped with

diamond grill. Each park lamp assembly is reproduced in injection molded plastic to exact GM factory specifications with correct SAE and Guide markings for complete authenticity. Sold individually. 912324 1976-78 2 required.









NE:

BODY



Park Lamps



1962 Park Lamp Lenses

Reproduction of the park lamp lenses for 1962 Chevy II/ Nova models. This reproduction features correct Guide markings as original. Sold in pairs.

1962. K416



1963-64 Park Lamp Lenses

Reproduction of the park lamp lenses for 1963-64 Chevy II/Nova models. This reproduction features correct Guide markings as original. Sold in pairs. K417 1963-64 19.99 pr



1965 Park Lamp Lenses

Reproduction of the park lamp lens for 1965 Chevy II/ Nova models. This reproduction is manufactured in the USA and features correct Guide markings as original. Sold in pairs. CMA3045 1965...



1966-67 Park Lamp Lenses

PARK LAMP LENSES

Reproduction of the park lamplens for 1966-67 Chevy II/ Nova models. This reproduction features correct Guide markings as original. Sold in pairs. 1966-67 K418



1968-69 Park Lamp Lenses

Reproduction of the park lamp lens for 1968-69 Chevy II/ Nova models. This reproduction is manufactured in the USA and features correct *Guide* markings as original. Sold in pairs.

CM3055 1968-69



1970 Park Lamp Lenses

Reproduction of the park lamp lens for 1970 Nova models. These reproductions are manufactured to factory specifications and feature correct Guide markings as original. Sold in pairs. CM30644 1970



1971-72 Park Lamp Lenses

Reproduction of the park lamp lens for 1971-72 Nova models. This reproduction features correct Guide markings as original. Sold in pairs. CM3061A 1971-72. 32.99 pr



1973-74 Park Lamo Chrome Bezel 🔥 Replace your dented and faded originals with these

reproductions of the park lamp chrome bezels for 1973-74 Nova models. These bezels are manufactured to be just like original for a perfect fit. 1973-74 2 required





1963-64 Park Lamp Bezels OER® park lamp bezels for 1963-64 Chevy II/Nova models. Manufactured from bright finished aluminum to factory specifications. Can also be installed on 1962 models

K116 1963-64

LH and RH...... 44.99 pr



1962-64 Park Lamp Bezel Moldings 🔥

Reproduction of the park lamp bezels for 1962-64 models. Each bezel is manufactured in aluminum and designed to replace the original exactly. Sold in pairs. K513 1962-64 LH and RH..... 72.99 pr



1968-69 Vigilite Fiber Ontic Lamp Bezel While most of today's vehicles have a lamp monitoring

system, during the late 60's and early 70's Chevrolet offered this system as optional accessory. This system included a chrome bezel, which was attached to the ton of each front fender. This chrome bezel housed a fiber optic cable with a lens that indicated whether or not your headlamps or turn signals were lit and operating properly. This ultra rare option was found on very few 1968-69 models. This is the outer chrome bezel assembly that was used with this system, which can be used on either fender

Note: The Vigilite system was also used on s 1968-70 GM passenger cars, including Buicks and Olds. C172391 1968-69

Park Lamp Components



1966-72 LED Park Lamos

This is the latest in park lamp technology! These direct replacement LEDs for your factory park lamps exceed the requirements for brightness using very high intensity, wide angle LEDs. An exceptional way to increase visibility and add a cool aesthetic touch to your Nova! The LEDs are arranged to compliment the original lens facets and provide the best light output. Diffusion material is added for an even distribution of light and to help eliminate or minimize the spottiness that happens with LED lighting to give you a smoother. more natural look.

500862 500867	1966-67	109.99 99.99	
500868	1970-72	99.99	
_/	,		
((

Note: Lens and housing are not included.

1962-64 Park Lamp Wiring/Socket

This reproduction socket is just what you need to get your Chevy II/Nova front lighting back in order. This wiring pigtail includes a correct socket.

37019 1962-64 park light socket 13.99 ea



1962-65 Park Lamp Socket Boot

This reproduction rubber park light socket boot helps to keep moisture and dirt out of your park lamp sockets. Correct for 1962-65 Chevy II/Nova models.

N730455 1962-65



1973-74 Park/Turn Signal Pigtail

A molded plastic connector used to hold park/turn signal bulbs in their housing. The socket has lugs that lock into the lamp body and wiring to connect the bulb to the power source. 1973-74 A11154 7 99 ca



1975-79 Park/Turn Signal Pigtail

A molded plastic connector used to hold park/turn signal bulbs in their housing. The socket has lugs that lock into the lamp body and wiring to connect the bulb to the power source. Fits 1975-79 models.

WE341 1975-79...



1962-64 Park Lamp Lens Gaskets 🔥

Reproduction of the original style park lamp lens gaskets designed for use on 1962-64 Chevy II/Nova models. These factory style replacement park lamp gaskets are die-cut to factory specifications to correctly replace the originals. Sold in pairs.

W4150 1962-64 ...

1965-67 Park Lamp Lens Gaskets 🔥

Correct replacement gaskets for 1965-67 Chevy II/ Nova models. Sold in pairs.

K4151 1965-67

1968-69 Park Lamp Lens Gaskets

Reproduction of the original style park lamp lens gaskets designed for use on various 1968-69 Chevy II/ Nova models. These factory style replacement park lamp gaskets are die-cut to factory specifications to correctly replace the originals. Sold in pairs. W4157

1968-69...



1970-72 Park Lamp Lens Gaskets Reproduction of the original style park lamp lens gaskets designed for use on 1970-72 Nova models.

These factory style replacement tail lamp gaskets are die-cut to factory specifications to correctly replace the originals. Designed to replace the old or worn out originals. Sold in pairs.

W4160 1970-72

1970-76 Park Lamp Lens Screws

Correct replacement screw for 1970-76 models. Use two for each lens. Reproduction of the original shouldered lens screw for 1970-76 Nova models. Each screw is chrome-plated stainless steel for superior corrosion resistance and an outstanding appearance. Common uses include turn signal lenses, park lamp lenses, and tail lamp lenses. Measures: #8-32 x 1" with 5/8" shoulder Individual

5961225	1970-76	standard	1.69	ca
Buy the Sea				
K5241		rews		
K5242	set of 6 sc	rews	7.99	set







B11488 R10403 R10550 5962696



Chrome Lens Screws

Replacement lens screws used on various GM vehicles. Available in standard or shouldered. Most 1964 and

newer vehicles used the shouldered type.				
	Standa	ard Lens Screws		
Chrome-F	lated Stai	inless Steel – 4 Piece Se	ets	
		13/16"		
B11620	#8-32 x	1"	7.99	set

Chrome-1	Chrome-Plated Stainless Steel - 4 Piece Sets						
B11489	#8-32 x 5/8", 11/32" shoulder						
B11108	#8-32 x 11/16", 3/8" shoulder						
B11493	#8-32 x 11/16", 5/16" shoulder	7.99	set				
B11495	#8-32 x 3/4", 7/16" shoulder						
B11488	#8-32 x 7/8", 1/2" shoulder						
B10402	#8-32 x 7/8", 9/16" shoulder	7.99	set				
B10403	#8_32 v 1_1/8" 5/8" shoulder	7.00	cet				

B10550

Chrome-P	lated – 4 Piece Sets	
C104	#8-32 x 5/8", 3/8" shoulder	6.99 set
5960939	#8-32 x 11/16", 3/8" shoulder	5.99 set
A9400119	#8-32 x 15/16", 5/8" shoulder	4.99 set

#8-32 x 1-5/16", 15/16" shoulder 7.99 set

5962696 #8-32 x 15/16", 1/2" shoulder... 9 99 set













めし マロマロム Т BODY

Side Marker Lamps



1968 Side Marker Lamn Kit Replace your front and rear side marker lamp

assemblies with this easy to install kit which provides a set of side marker lamp assemblies. Each kit includes: 4 side marker lenses, 2 rear side marker lamp bezels, and 2 reproduction front side marker bezels which feature the engine size. Note: The R5012 includes standard front chrome bezels

which do not feature an engine size designation.

N5023 1968 with 327 153.99 N5024 1968 with 350 153.99 N5025 1968 with 396 153.99	
N5025 1968 with 396 153.99	kit
	kit
N5026 1968 with 427 153.99	kit
R5012 1968 without engine size 71.99	kit




1969 Side Marker Lamn Kit Replace your front and rear side marker lamp assemblies with this easy-to-install kit which provides

a set of side marker lamp assemblies. Each kit includes: 4 side marker lenses, 2 rear side marker lamp bezels, and 2 reproduction front side marker bezels which feature the engine size.

ote: The R5012A includes standard front chrome bezels which do not feature an engine size designation.

N5022A	1969	with 307	150.99	kit
N5023A	1969			
N5024A	1969	with 350	150.99	kit
N5025A	1969	with 396	150.99	kit
N5026A	1969	with 427	128.99	kit
250124	1060	without angina cira	70.00	Lie



1968-69 Front Marker Lamp Bezels 📤

Reproduction of the chrome side marker bezels for the front fender. Bezel inserts directly over the lens assembly. I pair required per vehicle.

CM4525	1968-69	502	79.99 pr
CM4524	1968-69	427	
CM4523	1968-69	396	84.99 pr
CM4522	1968-69	350	84.99 pr
CM4521	1968-69	327	84.99 pr
CM4520	1968-69	307	84.99 pr





CM4525S 1968-69 SS Front Marker Lamp Bezels

Custom SS chrome front fender side marker lamp bezels. Installs directly over the lens assembly. I pair required per vehicle. CM4523S 1968-69 109.99 pr SS 396. SS 427

109.99 pr

109 99 pr

1068-60 Front Sid	o Monk
K70	

1968-69 Front Side Marker Lens 🔥

CMA3071

Front side marker assemblies for 1968-69 Chevy II/ Nova models. Each side marker lens and housing is manufactured to OE specifications with an injection molded UV stable acrylic lens for an original fit and appearance.

K70 CMA3071	1968 1969		
----------------	--------------	--	--





1970-79 Front Side Marker Lenses 🔥

This is a correct reproduction for the front fenders. These side marker lamps include an amber lens assembly attached to the housing. Sold in pairs.

911283	1970-74	amber	39.99 pi
912100	1975-79		24.99 ea







912099

1968-79 Rear Side Marker Lenses 🗥

Reproduction rear quarter panel side marker lamps. These lamps include a red lens assembly attached to the housing. Classic Industries® maintains the highest standards of quality.

Note: Gaskets sold separately.				
K71	1968-69	red		
917441	1970-74	red		
912099	1975-79	red	24.99 ca	

CM4524S 1968-69

CM4525S 1968-69

Side Marker Components



1970-74 Side Marker Lamp Kit Replace your front and rear side marker lamp assemblies with this easy-to-install kit. Each kit

includes the lens and the housing, along with all 4 high polished chrome bezels.

N5028 1970-74 143 99 kit



(lens and bezel sold separately)

1968-69 Side Marker Medallions

Laser cut from mirror polished stainless steel, these Bow Tie medallions mount with double sided tape between the side marker lens and the bezel for a cool, custom look. Includes medallions only. 2 pair required per vehicle.

Note: Bezel and lens not included. 14439

1968-69 21.99 pr



1970-74 Side Marker Medallions Laser cut from mirror polished stainless steel, each

medallion mounts with double sided tape between the side marker lens and the bezel for a custom appearance. Medallions only. 2 pair required per vehicle. Note: Rezel and lens not included

14440 1970-74 24 99 pr



1968-69 Side Marker Bezel

Reproduction of the correct chrome side marker bezel for the front fender without an engine size. K72 1968-69...



1970-79 Chrome Side Marker Bezel 🗥

3962933

front side m	arker bezel for	ruse on 1970-79 No	vamodels
3962933	1970-74	front	
3962934	1975-79	front	19.99 ca
3962934	1970-79	rear	19.99 ca





CPS0020A CPS0020R CPS0020D CPS0020F CPS0020 3 LED Mini Clearance/Marker Light 🔥

These 3 LED mini clearance/marker lights add a custom touch to your classic ride. Requires a 13/16" hole for installation.

Note: Fabrication may be required for installation CP50029A amber LEDs w/amber lens .. 8.99 ea CP50029B red LEDs with red lens...... 8.99 ca CP50029C amber LEDs w/clear lens.... 9.99 ca red LEDs with clear lens CP50029D 8 99 ca CP50029E blue LEDs with clear lens.... 11.99 ea CP50029F white LEDs with clear lens.. 10.99 ea



1968-79 Side Marker Lamp Socket 🔥

Replacement side marker lamp socket with wire pigtail. Fits front or rear marker lamps on all 1968-79 Chevy II/ Nova models A13558 1968-79



1968-69 Front Side Marker Rezel Gaskets

Reproduction side marker bezel gaskets for 1968-69 Nova models. Mounts between the bezel and the body on the front side markers bezels with engine size designation. K4166 1968-69

1968-69 Side Marker Lens Gaskets 🔥

Reproduction of the gaskets used to seal the side marker lens assemblies to the body. N3013 1968-69 front 3 99 nr



1968-69 Side Marker Bezel Gaskets 🔥

Correct replacement gaskets for the front or rear side marker lamp bezels. Will eliminate leakage due to rain, car washing, or other elements. Note: Gaskets are for front bezels without engine size

designation and all rear bezels K837 1968-69 rear. 6.99 pr



1970-79 Side Marker Lamp Gaskets

Correct reproduction side marker gaskets for 1970-79 Nova models. These OEM style gaskets are stamped from rubber and include the correct contour, 4 piece set. 3962935 1970-79 4 piece... 10 99 set









ō

BODY

228

Lamps



1962-67 Tail Lamn Assemblies

OER® tail lamp assemblies for 1962-67 Chevy II/ Nova models. Includes: bright finished aluminum bezel/housing with threaded studs, red and clear acrylic lenses, tail lamp, back-up lamp, (reflector, 1962-64), lens gaskets, body seals, aluminum lens divider, (retainer bracket 1962-64) and lens screws. Note: *Not for station wagon models

899439*	1962-64	LH or RH	89.99	c
910970	1966-67	LH or RH	109.99	c



1968-69 Tail Lamp Assembly

Reproduction tail lamp assembly for 1968-69 Chevy II/ Nova models. Each tail lamp assembly includes the correct lenses with Guide markings as original. Assemblies include the correct aluminum bezel and gasket.

A26 A26	1968-69 1968-69	RH	






1970-72 Tail Lamp Assemblies

OER® tail lamp assemblies for 1970-72 Nova models. Includes: bright finished aluminum bezel/housing with threaded studs, red and clear acrylic lenses, lens gaskets, body seals, and lens screws

ote: GM made a design change mid-1971: *1st design the (small 15/16" tall) back-un lens is

**2nd design	featured the (le	urge 2-5/16") back-up	lens insert.
5964171*	1970-71	LH	124.99 ca
5964172*	1970-71	RH	124.99 ea
A26026**	1971-72	LH	99.99 ca
A26025**	1971-72	RH	99.99 ca



1973-74 Tail Lamp Set

Reproduction 6 piece set that includes: taillight lenses. housings, and gaskets for 1973-74 Nova models. The lenses are manufactured in quality acrylic material, each lens will duplicate the factory original in appearance and fit

N17374 1973-74 6 piece.... ... 328.99 set





1975-79 Tail Lamp Assemblies

OER® tail lamp assemblies for 1975-79 Nova standard models. Includes: chrome bezel, injection molded ABS housing, red and clear acrylic lenses, and lens gasket,

Note: Bezels can be painted black for SS and Rally models. Except L/N and Concourse Models 1975-79 199 99 ca LH 1975-79 N1446 RH 199.99 ca





1976-78 Tail Lamp Retainer Nut 🔥

Replacement U-clip nuts used on 1976-78 Chevy II/ Nova models. Black phosphate coated. Quantities vary by model. Use as needed. This is the correct nut used to install the rear tail lamp to the body. Can be used to install the rear side marker lamp portion of the tail

lamp assembly. 3982098 WARNING: Cancer and Reproductive Harm-www.P65Warnings.ca.gov



1962-64 Tail Lamp/Back-up Lens Set 🔥

OER® tail lamp lenses for 1962-64 Chevy II/Nova models. Each lens is manufactured in quality injection molded UV stable red and clear acrylic plastic to OE specifications. Available with correct SAE and Guide lettering and without.

Note: Not for station wagon models. Replacement without Guide Lettering

5953465A 1962-64 LH and RH. 22.99 pr OE Style with SAE and Guide Lettering 5953465B 1962-64 LH and RH..... .. 29.99 pr







1965 Tail Lamp Lenses Reproduction tail lamp lens for 1965 Chevy II/Nova

models. These lenses have all of the correct Guide and SAE markings for an authentic appearance. A3050 1965 N9001 1965



5957440 K1040

1966-69 Tail Lamp Lenses Replace your faded or cracked 1966-69 Chevy II/Nova



UV stable red acrylic plastic to factory specifications. Lenses feature Guide markings as original. 5957440 1966-67 LH or RH..... 18.99 ea

Hd:

Tail Lamps







1970-79 Nova Tail Lamp Lenses

OER® tail lamp lenses for 1970-79 Nova models, Each lens is manufactured in quality injection molded UV stable red and clear acrylic plastic to OE specifications. Features the correct incorporated back-up light lens and correct SAE and Guide lettering.

Note: GM made a design change mid-1971: *1st design featured the (small 15/16" tall) back-up lens insert. 2nd design featured the (large 2-5/16") back-up lens insert.

All Models			
N5503*	1970-71	LH	39.99 ea
N5504*	1970-71	RH	39.99 ea
5964513**	1971-72	LH	
5964514**	1971-72	RH	39.99 ea
5965743	1973-74	LH	89.99 ca
5965744	1973-74	RH	89.99 ea
Except L/N	and Concor	ırse Models	
5966237	1975-79	LH	69.99 ca
5966238	1975-79	RH	69 99 ca



1965 Back-Un Lamo Lenses

Reproduction back-up lens for 1965 Chevy II/ Nova models. Features correct markings. Not for station wagons. A3051 except wagon

1965

5957441



1966-69 Back-Up Lamp Lens

OER® back-up lamp lenses for 1966-69 Chevy II/ Nova models. Each lens is manufactured in quality injection molded UV stable clear acrylic plastic to OE specifications. Features the correct SAE and Guide lettering. 5057441 1966-67 LH or RH 15.99 ca

7-h		
-		5965741
	7	•

1973-79 Nova Tail Lamp Housings 🔥

5066235

OER® tail lamp housings for 1973-79 Nova models. These injection molded ABS plastic housings are manufactured to factory specifications for an authentic fit and original appearance. Features original style mounting points and pre-cut bulb openings.

5965741	1973-74	LH	
5965742	1973-74		79.99 c
5966235	1975-79		84.99 c
5966236	1975-79	RH	84.99 c



1975-79 Tail Lamn Bezels

Reproduction of the original tail lamp bezel designed for use on 1975-79 Nova standard models. Manufactured in quality die-cast zinc replicating the original bezel in fitment and design. Features a bright polished chrome finish and is manufactured in the original shape and configuration with correct mounting studs. Includes installation hardware.

344395 344396	1975-79 1975-79	LHRH	



1966-67 Tail Lamp Filler Plate Gaskets

This molded rubber seal attaches between the body and the filler plate that is below the tail lamps on all 1966-67 Nova station wagon models. Sold in pairs. 14405 1966-67 station wagon 15.99 pr

🎎 1962-64 Tail Lamp Gasket Set Reproduction tail lamp gasket set for 1962-64 Nova

models. Manufactured to factory specifications featuring correct contours, and pre-cut mounting slots. Set includes 2 rubber housing to body gaskets, and 2 foam lens to housing gaskets. 881367 1962-64 except wagon

5953464 W4159



1962-74 Tail Lamp/Back-Up Lens Gaskets

High-quality replacement gaskets for 1962-74 Chevy II/ Nova models. Manufactured with OEM equivalent materials, you can replace your originals and reseal your lenses to prevent damage. Gaskets seal the area between the lens and tail lamp/back-up housings. Tail Lamp Lens Gaskets

5953464	1962-64		4.99	pr
W4153	1965	exc. wagon - 4 pc	44.99	
N3009	1965	wagon	6.99	pr
W4154	1966-67		5.99	pr
W4158	1968-69		5.99	pr
W4159	1970			
W41591	1971-72		6.99	
5950233	1973-74		24.99	pr
Back-Up I	Lens Gaske	ts		
N3010	1962-64	wagon	4.99	pr
N3011	1965	wagon	5.99	pr
			_	_







1962-79 Tail Lamp Body Gaskets

Manufactured with OEM equivalent materials, you can replace your originals and reseal your lamp assembly to prevent damage. Gaskets seal the area between the tail lamp assembly and the body.

Except Sta	tion Wagon			
4861854	1962-64	2 piece	29.99 p	e
W4155A	1965	4 piece	58.99 s	c
7587759	1966-67		19.99 p	e
7730113	1968-69		19.99 p	e
5963118	1970-72		21.99 p	¢
N1447	1975-79		34.99 p	¢
Station Wa	gon			
13900	1965	outer to body	59.99 p	e
N3012	1965	inner to body	5.99 p	e
7587759	1966-67		19 99 n	









54.99 pr

K1044







230



1965-79 Stop, Tail, & Turn Pigtail

A molded plastic connector used to hold stop/tail/turn light bulbs in their housing. The socket has lugs that lock into the lamp body and wiring to connect the bulb

to the powe	or source.			
A11157	1965-68		4.99	ca
A11154 WE369	1969-79 1979	90 degree	7.99	ca
W E309	1919	90 degree	0.77	ca




1962-79 Back-Up Lamp Pigtail A molded plastic connector used to hold Halogen type

bulbs in their back-up lamp shell. The socket has lugs that lock into the lamp body and wiring to connect the bulls to the power source

WE307	1962-68	5.99 ca
WE334		
WE351	1976-79	7.99 ca

RON FRANCIS WIRING



4" Weld-In LED Lamps

These 4" weld-in LED brake/turn signal lamps will give your classic ride that truly custom look. Includes LED, weld-in faceplate and rear mounting box. Available in red or amber with either 1 or 2 LEDs. Approximate cutout size for single plate is 5-1/4" x 1", double plate is 5-1/4" x 1-3/4".

BL200108	single	amber	48.99	ca
BL200109	single	red	48.99	
BL200110	double	amber	80.99	ea
BL200111	double	red	80.99	ea
BL200112	double	amber and red	80.99	ca

Lamps



Rear Window LFD Third Brake Lamn 🔥

This rear window LED brake lamp bonds to the inside of the rear window in a black ABS plastic case, paint to match interior, if desired. The small wires can be hidden in the window trim. Available in three different angles. All three models have slight adjustment to allow you to "aim" the lamp. Measures 4 inches wide. BI 200102 straight...... 42.99 ea BI 200103 15 degree 42.99 ea

BI 200104

New!		
	1	
	r 🕸 🎹	

3 LED Tail Lamp Sequencing System

This system converts any three LED tail lamps to sequential operation. A three segment sequence is used for turn signal operation, with "all at once" lighting for brake lamp operation. Includes: two modules, wiring. connectors, and instructions

Note: For use with LED tail lamp systems only. CP500440 54.99 set



3 LED Mini Dual Function Lamos

Customize your classic ride with these 3 LED miniauxiliary lamps. Each lamp includes 3 LED dual function lights with stainless steel bezel. Requires a 3/4" opening. Mounts with enclosed rubber grommet.

Available in amber or red with colored lens.

Note: Some fabrication may be required for installation			
	CP50011A	amber LEDs, amber lens	
	CP50011B	red LEDs, red lens	11.99 ca
	CP50011C	amber LEDs, clear lens	11.99 ca
	CP50011D	red LEDs, clear lens	11.99 ca



1962-67 LED Tail Lamp Lens

Make a bold statement with this hot reproduction tail lamp lens and back-up lens, both with LED circuit board to give your Chevy II/Nova an original but brighter look. The tail lamp lens comes equipped with super bright LEDs, and both feature fully sealed epoxy ted electronics

Note: Not	for station we	igon models.	
C10441	1962-64	tail lamp	43.99 ea
C10442	1962-64	back-up lamp	45.99 ea
153063	1966-67	tail lamp	42.99 ca
153064	1966-67	back-up lamp	41.99 ea



1970-72 set, from the center of the vehicle or from the center of the lens.

1966-72 Multi-Pattern I FD Tail I amn Panels

Animate your tail lamps and make your Nova stand out! These LED panels feature a self-contained microprocessor and circuitry to enable multiple sequential lighting patterns. Make the light pattern flow at various speeds from the center of the vehicle outwards, from the center of the lens outwards, and more! Each set offers four different patterns. Made in IISA

Important: The examples shown above are only two of the ur patterns available on each panel set. All panels require

153081	1966-67	4 flowing patterns	219.99 set
153082	1970-72	4 flowing patterns	239.99 set
F90652	1966-72	LED flasher	14.99 ea



1968-69 LED Tail Lamp Lens

Make a bold statement with this hot reproduction tail lamp lens, with LED circuit board to give your Chevy II/ Nova an original but brighter look. The tail lamp lens comes equipped with 36 super bright LEDs that are fully sealed with an epoxy coating. This lens eliminates the back-up lamps. Two required per vehicle.

DD150

LED Tail Lamp Conversion



1962-64 I FD Tail I amn Conversion 🔥

Make a hold statement with this hot LED tail lamp conversion for 1962-64 models. This conversion with special circuitry provides maximum brightness so your car will be safer and look better. These conversions will fit into your existing tail lamp housings and can use your existing wire harness for quick and easy installation. Tail lamp lenses and housings are not included and can be purchased separately if necessary. Note: This is the tail lamp circuit boards only.

DD120 1962-64.. 161.99 set





1965 LFD Tail Lamn Conversion

Make a bold statement with this hot LED tail lamp conversion for 1965 models. This conversion with special circuitry provides maximum brightness so your car will be safer and look better. These conversions will fit into your existing tail lamp housings and can use your existing wire harness for quick and easy installation. Tail lamp lenses and housings are not included and can be purchased separately if necessary. Note: This is the tail lamp circuit boards only



1966-67 LED Tail Lamp Conversion 🔥

Make a bold statement with this hot LED tail lamp conversion for 1966-67 models. This conversion with special circuitry provides maximum brightness so your car will be safer and look better. These conversions will fit into your existing tail lamp housings and can use your existing wire harness for quick and easy installation. Will work on Nova and Nova wagons. Tail lamp lenses and housings are not included and can be purchased separately if necessary.

Note: This is the tail lamp circuit boards only.

161 99 set DD160 1966-67



1966-69 LED Tail Lamp Upgrade

Update your 1966-69 Chevy II/Nova's taillights with new LED technology. LEDs are far brighter than incandescent bulbs, light up in less than .05 seconds, use less energy and last much, much longer. Since they are brighter, illuminate instantly and are visible from farther away. LED tail lamps are not only a significant safety upgrade for your vehicle, but also give your car a clean, modern look when the brake lamps are lit. These LED circuit boards are easy-to-install. Simply splice into the factory wire harness and the LED arrays fit into the factory wire harness and the LED arrays it in early beneath the stock lens, providing a stock look when the tail lamps are off. Because this upgrade is "invisible", it appeals to owners of both modified and restored cars. Each set includes: two LED arrays, electrical harnesses, connectors, and all necessary brackets and mounting hardware.

CL6037 1966-67 CL6044 1968-69 89 99 set







1968-69 LED Tail Lamp Conversion 🗥

Make a bold statement with this hot LED tail lamp conversion for 1968-69 models. This conversion with special circuitry provides maximum brightness so your vehicle will be safer and look better. These conversions will fit into your existing tail lamp housings and can use your existing wire harness for quick and easy installation. Tail lamp lenses and housings are not included and can be purchased separately if necessary. Note: This is the tail lamp circuit boards only.

DD140 1968-69 181 99 set



Due to the lower current draw of LED lamps, these electronic 12 Volt flashers are recommended for vehicles equipped with LED lamps. Available in 20 amp or a 25 amp. 20 amp available in two or three prong type.

14 99 ca

Important: If installing LEDs on both the front and rear, two flashers are usually required. Note: *Includes reverse polarity adapter. B6207 20 amps 2 prong 12.99 ea B6208 20 amps 3 prong 12.99 ca 2 prong

example of a 1970-72 tail lamp lens

1970-74 LED Tail Lamp Conversion 🔥

Make a bold statement with this hot LED tail lamp conversion for 1970-74 models. This conversion with special circuitry provides maximum brightness so your vehicle will be safer and look better. These conversions will fit into your existing tail lamp housings and allow you to use your existing wire harness for quick and easy installation. Tail lamp lenses and housings are not included and are available for purchase separately. Note: This is the tail lamp circuit boards only

DD150 1970-72 181.99 set DD380 1973-74 ... 161.99 set

DIGITALLS





1968-72 Sequential LED Tail Lamps 🔥

This is the latest in tail lamp technology! These LED replacements for your factory tail lamps fit perfectly behind your factory lens and bezel, and are far quicker responding and much brighter than DOT requirements! These sets use very high intensity, wide angle LEDs for an exceptional way to increase visibility and add an extra aesthetic touch to your Nova. They provide two modes of operation, standard or sequential. The sequential mode gives you a unique cascading affect that will really get you noticed! Changing modes is as easy as flipping a switch on the back of the circuit board. Every light circuit board is specifically designed to use the maximum area of the housing. The LEDs are arranged to compliment the original lens facets and provide the best light output. Diffusion material is added for an even distribution of light and to minimize the spottiness associated with LED lighting for a smoother, more natural look. These are to be spliced into the rear wire harness. Includes everything needed for a perfect installation. Each set will convert both LH and RH tail lamps. Tail lamp lenses and housings are not included and can

	ed separately it necessary.
Note: This i	s the tail lamp circuit boards only.
500875	1968-69
500876	1970-72

199.99 set 1970-72 199 99 set









F90652* 25 amps



License Lamps



1962-65 Rear License Lamn

This reproduction license lamp assembly includes bracket, lens, and wiring. Assembled and ready-to-install. Fits all 1962-65 except station wagon.



1966-72 Rear License Lamp 🛚 🗸



1975-79 Rear License Lamp

Quality reproduction of the original license lamp assembly designed for use on various GM models including 1975-79 Nova models. License lamp assembles are manufactured for keroty specifications. Each lens is injection modded in clear acrylic lens material that replicated the original in fitment and appearance. Includes the correct lens, bousing, and appearance. Includes the correct lens, bousing, and agasket allowing a complete replacement of the wom out, broken, or missing original.

8719.2 1975-79.



1069.79 Liconeo Lamn Lone

	7	
This is a rep	roduction of the license lam	p lens or
1962-72 Che	y II/Nova models. Replace yo	our broker
or faded lens	today. This lens is correct in	every way
and is easy to	replace.	
CM3027	1962-65	16.99 ea

LICENSE LAMPS



1962-65 License Lamp Gasket

Reproduction of the original license lamp gasket designed for use on 1962-65 Chevy Il/Nova models. Each correct dic-cut gasket will replace the original exactly and help prevent moisture or road elements from entering and causing damage. We recommend replacing your original whenever replacing the bulb or painting the vehicle.



1966-72 License Lamp Gasket

Correct reproduction gasket for 1966-72 Chevy II/ Nova. Fits between the license lamp lens and base. Seals the lamp to eliminate water and other elements from entering the housing and damaging the bulb or wiring. Sold individually. I required.



1975-78 License Lamp Socket

OER®Authorized replacement rear license lamp socket for 1975-78 Chevy Il/Nova models. For use with bulb 194 (not included). This socket assembly can also be used for all side marker assemblies, front or rear. A13558 1975-78 1 required................... 5.99 ea



1975-79 License Lamp Socket

Genuine GM or reproduction rear license lamp sockets for 1975-79 Chevy II/Nova models. For use with bulb 194 (not included). This socket assembly can also be used for all side marker assemblies, front or rear. G6718 1975-79 I required 8.99 ea



1979 License Lamp Socket and Wiring

Wiring is often overlooked as being the cause of a malfunctioning light bulb. Replacethe corroded license plate lamp socket in your 1979 Nova with this original style reproduction socket. Includes enough wiring for easy splicing into the harness.



Bulb Kit for Emergency Use!

Whether you're replacing your bulbs during a restoration of just want to be ure you're ready for any roadside emergencies that may come up, this handy kit takes all of the work out of searching around for the proper replacement miniature bulbs. It contains most every bulb you would need to replace all of your front parking lights, side markers, taillights, license lights, backup lights, and turn signals. Gain peace of out on the road, you have plenty of spares to fit most any application.

XX100 14 piece...... 19.99 kit

AUTHORIZED AUTHORIZED



Replacement Bulb

Replacement lamp bulbs for a variety of applications. Choose the cornect bulb by matching the number on the base of your original bulb. Descriptions listed below only provide a reference for application. Individual applications may vary depending on vehicle model and year. Listed below by: base style, bulb #, bulb type, and (CP)-reandle power.

1445	G3-1/2	0.7 CP	1.99 ea
53	G3-1/2	1.0 CP	
B363	G3-1/2	2.0 CP	1.99 ea
57	G4-1/2	2.0 CP	1.99 ea
1895	G4-1/2	2.0 CP	
1892	T3-1/4	.75 CP	1.99 ea
B1815	T3-1/4	1.4 CP	1.99 ea
	T3-1/4	2.0 CP	
1893	T3-1/4	2.0 CP	1.99 ea
1816	T3-1/4	3.0 CP	1.99 ea

HODY

Replacement Bulbs

AUTHORIZED









B2122 Replacement Bulb

Replacement lamp bulbs for a variety of applications. Choose the correct bulb by matching the number on the base of your original bulb. Descriptions listed below only provide a reference for application. Individual applications may vary depending on vehicle model and year. Listed below by: base style, bulb #, bulb type, and (CP)=candle power.

Miniature Wedge Base

74	T1-3/4	0.5 CP	1.99 ea				
Wedge Base							
	T3-1/4	1.0 CP	1.99 ca				
158		2.0 CP	1.99 ea				
	T3-1/4	2.0 CP	1.99 ca				
194A	T3-1/4	2.0 CP (amber)	1.99 ca				
168	T3-1/4	3.0 CP	1.99 ca				
Bayone	Base G-	5					
B67	single	4.0 CP (#67 or #97)	1.99 ca				
89	single	6.0 CP	1.99 ca				
90	double	6.0 CP	1.99 ea				
Bayone	Bayonet Base B-6						
B105	single	12.0 CP	2.99 ca				
1003	single	15.0 CP					
1004	double	15.0 CP	2.99 ca				
Bayone	Bayonet Base S-8						
1141	single	21 CP	1.99 ca				
1073B	single	32 CP	1.99 ea				
1156	single	32 CP	1.99 ca				
1034	double	3/32 CP	2.99 ca				
1157	double	3/32 CP	1.99 ca				
1157A	double	3/32 CP (amber)	1.99 ca				
Mini-Ce	apped						
B2122	Ť3	6 CP	2.99 ea				
Flat Cli	p						
562	T3	6 CP	2.99 ca				

AUTHORIZED





LED Replacement Lamp Bulbs

Brighten up your tail lamps with these LED replacement bulbs. LED lighting is up to 3 times brighter, does not heat up like incandescent lighting and requires far less

1157 Ser	iar Pulh	
	red	9 99 ca
	white	
500569	amber	9.99 ea
1156 Ser		
500577	white	
500573	red	9.99 ea
500575	amber	9.99 ea

AUTHORIZED





SMD LED Lamp Bulbs

LE4414W

LE3613W

Modernize the lighting equipment on your vehicle with these bright 6000k LED light bulb units. Manufactured to replace common bulbs on any vehicle with 12V capacity. LED bulbs not only react faster than traditional bulbs, but provide better light distribution.

194 Series B	ulbs	
LE194W	white	9.99 pr
LE194A	amber	9.99 pr
LE194B	blue	9.99 pr
LE194R	red	9.99 pr
LE194G	green	9.99 pr
1156 Series		
LE1156W	white	14.99 pr
LE1156A	amber	14.99 pr
1157 Series		
LE1157W	white	14.99 pr
LE1157A	amber	14.99 pr
LE1157R	red	14.99 pr
Dome Lamp	Bulbs	
LE3613W	3613 - white	10.99 pr
1.174414337	4414 12	10.00

194 Series Bulbs







1157 Series Bulbs







1156 Series Bulbs





67 Series Bulhs





MX01220



Colored Lamp Bulbs

Have some fun, switch over to blue, green, amber, or purple bulbs for show use. Sold in pairs. Note: Using a bulb other than amber is not street legal.
Use colored bulbs for off-road or show purposes only. 194 Series Rulhs

XX203	clear	3.99	pr
MX01214	purple	4.99	pr
MX01211	blue	4.99	pr
1157 Series Bu			
XX201	clear	2.99	pr
MX01203	green	4.99	pr
1156 Series Bu			
XX202	clear	2.99	pr
MX01209	purple	4.99	pr
MX01205	amber	4.99	
MX01207	green	4.99	pr
	s – License Plate Lamp		
XX204	clear	2.99	pr
MX01220	amber	4.99	pr
MX01221	blue	4.99	pr
MX01222	green	4.99	pr
MX01223	red	4.99	pr














Chevy II/Nova Grills

3833312 - Installed





1962-65 Chevy II/Nova Grills

OER® 1962-65 Chevy Il/Nova grills. Each grill is the finest reproduction on the market manufactured from all new tooling. Each grill features crisp lines and a clean stamping resulting in a precise fit and factory original appearance. Manufactured in quality stamped aluminum, the grills are polished and bright dip anodized to preserve the brilliant shine and prevent corrosion.

	ts	469.99	ea
			dimen.
			41152

1963-79 Polished Billet Aluminum Grills

Add a little style to your 1963-79 Chevy II/Nova with these finely polished billet aluminum grills. Made with uncompromising standards and quality workmanship. Feature original style cutouts where necessary for hood latch or signal lamps.

Note: *Without hood latch cutout. **Without hood_____

	taten ana	tamp cutouts	. Snippea oversize.	400	
	41122	1963-64		189.99	ca
	41152	1966		194.99	
	41153	1968-72		169.99	ca
	41154	1973-74	OE style	181.99	ca
	41156*	1973-74		181.99	
	41157**	1973-74		181.99	ca
Į	41155	1975-79		169.99	ca

333323 - Installed

1966-67 Chevy II/Nova Grill

Reproduction of the highly sought after 1966-67 Chevy II/Nova grill. Each grill features the correct end contours conforming to the headlamp bezels offering a clean fit and appearance. Note: Shipped oversize.

2005200

3886428

3867837

1966 Chevy II/Nova...... 149.99 ea 1967 Chevy II/Nova...... 169.99 ea







1968-72 Chevy II/Nova Grill

OER® Authorized reproduction of the original standard front grill designed for use with 1968-72 Chevy II/ Nown models. Each grill is meticulously manufactured offering an authentic and original appearance. Features correct mounting points for installation. Will replace the original grill exactly.

Note: Shipp	2 0S1		
3909164	1968-69	Chevy II/Nova	119.99 ca
3962979 3949721	1968-69 1970-72	Nova SS	
3962915	1970-72	Nova SS	119.99 ca



Quality reproduction of the SS grill for 1973-74 Nova Super Sport models. Painted black, the grill features the two horizontal bars in argent silver found on Super Sport model grills.

N3374 1973-74 124.99 ea

1975 Nova SS/LN Grill

344351


377033

OER® reproduction of the original front grill assembly for 1975 Chevrolet Nova models with the Super Sport option. Each grill is manufactured with Injection molded ABS to OE specifications replicating the original in every detail. Each grill is manufactured to exact specifications and features the correct black painted grill bars (SS) or chrome (LN) as original.

ote: Ship	pped overs	ize.		OS1	
44350 44351	1975 1975	SS LN	black chrome		

3.





1976-78 Nova SS/Rally Diamond Grill

OER® 1976-78 Nova grill for models with the Rally or SC option. Each grill is designed for Nova models equipped with the Rally grill brackets. Black grills were original equipment on the 1976 SS Nova, but will also fit the 1977-78 Nova with Rally option. The control of the 1977-78 Nova with Rally option. The diamond patterned center area. The OER® Rally SS grill was designed to replicate the original in every detail. Includes hardware.

Note: Shipped oversize.			1831		
36060			black		

Grill Components

1976-78 Nova Standard Grill

Reproduction of the original standard front grill designed for use with 1976-78 Nova models. Each grill is manufactured in injection molded ABS replicating the original in design and fitment. Features openings for LH and RH park lamp lenses and proper mounting

locations for the grill emblem. Note: Shipped oversize. 466818 1976-78 Nova. 274.99 ca



1962-65 Grill Guard

Reproduction of the optional chrome grill guard for 1962-65 Chevy II/Nova models, this an excellent dressup accessory item and comes in a chrome finish. Easily

installed using existing bumper bolt holes. Note: Shipped oversize.

985435 1962-65 Chevy II/Nova 169.99 ea

1968-72 Upper Grill Reinforcement 🗥

Reproduction upper grill reinforcement panel for 1968-72 Nova models. Manufactured to factory specifications featuring original style contours, pre-punched mounting holes and EDP coated for rust prevention.

153053 1968-72 46 99 ca

1966 Lower Grill Molding

Reproduction lower grill molding for 1966 Chevy II/ Nova models N1220 56.99 ea 1966 lower



1968-72 Grill Support Bracket

Reproduction grill support brackets for all 1968-72 Nova models. These stamped steel brackets attach to the radiator support and provide the grill with a mounting point on each end.

1968-72 IН 39.99 ea 1968-72 RH 39 99 ca

8



1976-78 Grill Support Brackets

Reproduction of the original grill support brackets for 1976 Nova (except SS models) and 1977-78 Nova (except Rally models). These stamped steel brackets attach to the radiator support and provides the grill with a mounting point. Comes with EDP coating for rust and corrosion resistance.

356625 1976-78 LH 356626 1976-78 RH 14 99 ca





1962-65 Nova Grill Brackets OER® reproduction of the grill mount brackets for

1962-65 Chevy II/Nova grills. Manufactured from stamped steel and EDP coated for rust prevention. Includes 2 rubber seal strips.

		_		
48733	1965	5 piece	119.99	set
81244	1964	5 piece		
48697	1963		99.99	
48732	1962	5 piece		



1966 Grill Brackets Reproductiongrillmountbracketsetfor1966ChevyII/ Nova makes replacing your damaged grill easy.

Correct stamped steel brackets with all the proper mounting holes in correct locations. Brackets are manufactured from stamped steel and EDP coated for rust prevention. A26105 1966 6 piece

AUTHORIZED





O	8	0	8	0	8	0	8	0	8
0	b	0	8	0	8	0	8	0	b
0	S	0	3	0	۵	0	۵	0	۵
0	2	O	2	O	8	0	8	O	8
0	8	0	2	0	2	0	3	ø	٤
							881	235	A

Universal Grill Attaching Rivet with Nut Grill attaching rivet with lock nut for various

applications where a rivet is needed. These have the look of a rivet with the ease of a bolt and nut. Available in silver zinc or black EDP coated. #10-24 x 3/8" rivet head bolt with lock washer nut.

748699 748698 881235 881236	silver black silver black	individualset of 25set of 25	1.99 ea 39.99 se
881235	silver	set of 25	39.99 sc



1973-79 Grill Nylon Anchor Nut 🔥

Attachment nut for 1973-79 grill. Use as required. For #8 screw size, 5/16" square hole, panel range 1/16" - 5/32"

347347 1973-79 nylon anchor nut..... 1.99 ea



1976-79 Grill Nut

Replacement U-clip nuts used on 1976-79 Chevy II/ Nova models. Black phosphate coated. Quantities vary by model. Use as needed. This is the correct nut used to install the rear tail lamp to the body. Can be used

to install the rear side marker lamp portion of the tail lamp assembly. 3982098 1976-79



15193









BODY COMPONENTS

ODY COMPONENTS

Radiator Support/Body Bolts

AUTHORIZED







1962-74 Radiator Support

Reproduction radiator support for 1962-74 Chevy II/ Nova models. Each support is ready-to-install and includes predrilled holes for easy installation to any application. These supports are for all 1962-74 Chevy II/Nova models except 1974 models with air conditioning or heavy-duty radiators.

C2488	1962-64		179.99		
C2489	1965		179.99		
C2482	1966-67		179.99		
C2463	1968-74	6 cylinder	169.99		
C2464	1968-72		164.99		
327515	1968-74	V8 small block	179.99	ea	
-				_	



1968-79 Radiator Support Top Reproduction of the radiator top support for 1968-79

Nova models without AC or heavy-duty radiator. Manufactured from stamped steel and available with chrome finish or black EDP coating. Includes hardware. Measures approximately 23-7/8° x 5-1/4°.

vicasuics app	5-7/6 X J-1/4 .	
	ome	



1968-74 Radiator Support Bushing Kit

Due to popular demand, Classic Industries® now stocks a separate kit to replace radiator support bushings for 1968-74 Chevy II/Nova models. This kit includes all the correct bushings, bolts and washers to completely remount the radiator support. K3029 1968-74 29.99 kit



1964-72 Master Body Fastener Set 🗥

These are the only fastener sets available for your Nova. They include fasteners for back-up Jamps, battery ray, bumpers, bumper brackets, bumper guards, bumper filler panel, cool panel, door lateches, fenders, fender panels, bumper brackets, bumper guards, bumper fill brackets, grill moddings, headalmap adjusters, headlamp bezels, headlamp housings, header panel, hood, hood hinges, hood each and lock plate, hood hood, hood hinges, hood each and lock plate, hood marker lamps, nameplates, parking lamps, tail lamps, trunk latch and striker, trunk lid, valance panel, wheelhouses, wheelhouse brackets, all related spring must and more!

nuts and			
N1300	1964	376 items	
N1301	1965	383 items	169.99 set
N1302	1966	383 items	169.99 set
N1303	1967	384 items	
N1304	1968	322 items	179.99 set
N1305	1969	327 items	174.99 set
N1306	1970	317 items	179.99 set
N1307	1971-72	314 items	179.99 set




Front End 5/16" Pointed Indented Head Bolts Correct black oxide bolts used for mounting radiator

Correct black oxide bolts used for mounting radiator supports, fender to radiator support braces, and hood latch support assemblies. The bolts are 5/16°.



1968-72 Front End Alignment Shim 🛭 🗸

Reproduction front end alignment shims for 1968-72					
		generic shims, these			
original ap	pearance. So	ld individually. Use a	s needed.		
F12391	1968-72	1/16"			
F12302	1968-72	1/8*	2 99 69		



1964-74 Front End Fastener Hardware Set

Includes all the correct fasteners used in assembling the entire front end sheet metal. This set replaces rusted, incorrector missing pieces. Includes: washer head point cap screws, plastic clip nuts, etc. This set is a must if you are replacing your front end sheet metal. The original hardware will probably need to be replaced. Take advantage of this set for everything you need!

rake au	vantage of this set for everything y	ou nee	u:
Note: Do	es not include grill installation hardwa	re.	
N221	1964-67	29.99	se



1962-79 Exterior Screw Set

Replace the essential screws and fasteners necessary for the grill, headlight bezels, outer mirros, parking lamp lens and bezels, quarter panel moldings, taillight lens and windshied moddings. Each set contains the correct amount of screws needed to replace the essential tiems found on the outer body. Sets vary from the course to year on screw count and only include those screws that are visible from the outside.

iat are visible from the outside.				
K1540	1962	41 piece	14.99 set	
K1545	1965	41 piece	14.99 set	
K1395	1966	39 piece		
K559	1967	26 piece	9.99 set	
K1400	1970	22 piece	8.99 set	
K1405	1971	35 piece		
K515	1973	26 piece	12.99 set	
K1410	1974	22 piece	8.99 set	
K1411	1975-79	24 piece	15.99 set	



Fender to Cowl Bolt Set

54.99 ea

Bumpers & Components



1962-72 Front and Rear Rumners 🔥

Reproduction bumpers are available in OER® Authorized standard replacement or OER® Premier. OCER® standard replacement bumpers are manufactured for an original appearance and fit. The OER® Premier line of bumpers features a superb quality chromeplating process and come highly polished for a show quality shine.

Note: Shipped double oversize.

OER® Pres	OER® Premier					
153197B	1962-64	front	199.99 ca			
153199B	1965	front	199.99 ea			
153198B	1966-67	front	189.99 ca			
153196B	1968-69	front	209.99 ca			
153193B	1970-72	front	219.99 ca			
153195B	1966-67	rear	209.99 ca			
153194B	1968-72	rear	209.99 ea			
Standard F	Replacement					
153197A	1962-64	front	169.99 ca			
153199A	1965	front	169.99 ca			
153198A	1966-67	front	169.99 ca			
153196A	1968-69	front	199.99 ea			
153193A	1970-72	front	199.99 ea			
153310A	1962-65	rear	169.99 ca			
153195A	1966-67	rear	179.99 ea			
153194A	1968-72	rear	189.99 ea			

New

AUTHORIZED

1531084



1973-74 Front and Rear Bumpers 🛕

OER® Authorized front and rear bumpers designed for 1973-74 Nova models. These reproduction bumpers are manufactured to factory specifications and feature triple chrome-plating.

Note: Ship	ped double	
Without I	mpact Str	ip Holes 539.99 es
		front
With Imp	act Strip I	Holes
C2608 *	1973	front 339.99 ea
C2609	1974	front 339.99 ea
Without I	mpact Str	ip Holes
C2612	1973	rear 339.99 ea
C2614	1974	rear 339.99 ea
With Imp	act Strip I	Holes
		rear 339.99 ea
C2613	1974	rear 339.99 ea

FI3050



1965-72 Fiberglass Front Bumper 🔥

These fiberglass replacement bumpers offer the ultimate in light weight durability while retaining an original appearance. Excellent for race car use. Important: *Though originally designed for 1965 models, 1967 70 and 1965 models.

Important: *Though originally designed for 1965 models, this bumper will fit 1962-64 models. **For 1970-72 models must use 1968-69 park lamps #916211. All bumpers are not for use with OEM brackets.

Note: Shimodel double oversite.

F13050* F13550 F14550**	1965 1966-67 1968-72	will ht 1962-65	241.99 ea 241.99 ea 244.99 ea
		HAR	WOOD
1	-	1	



1962-72 Fiberglass Rear Bumper

These fiberglass replacement bumpers offer the ultimate in lightweight durability while retaining an original appearance. Excellent for race car use.

Note: Not for use with OEM brackets. Shipped

-			_
F14560	1968-72	246.99	ca
F13560			
F13060	1962-65	241.99	
double over		0S2	

1962-65 Front Bumper Filler Panel A. Superb reproduction of the bumper filler panel for

69 99 ca

Supero reproduction of the number filter panel for 1962-65 Chevy II/Nova models. Manufactured to exact specifications for a factory fit.

Note: Shipped double oversize.

	## AUTR	ORIZED
		C2391
_		-
		3919083

1966-72 Front Bumper Filler Panel OER® Authorized front bumper filler panels for 1966-

72 Chevy II/Nova models. Located below the grill and extends to the front bumper. Manufactured in stel for 1966-67, and plastic as original for 1968-72 models. Note: Shipped double oversize.

C2391 1966-67 steel 64.99 ea 3919083 1968-72 plastic 46.99 ea

1968-72 Chevy II/Nova Front Rumner Filler Panel Reinforcement

Reproduction of the original front bumper reinforcement designed for use on 1968-72 Chevy II/Nova models. Manufactured to exact factory specifications replicating the original in quality and design. Features correct mounting locations for installation.

Note: Shinned double oversite.

New!	AUTHORIZED
	C2615

C2392 1968-72 ...

1973-74 Bumper Impact Strips

OER® Authorized reproduction of the original from bumper impact strip designed for use on 1973-47 Chevrolet Nova models. Each strip is manufactured to factory specifications for an original appearance and fit. Impact strip includes correctly located studs that mount directly into the bumper. These impact strips were installed on Novas with an upgraded exterior package. Refer to part numbers 2008 (1973) or 2609 (1974) for Nova front bumpers with pre-drilled impact strip holes.

C2615 C2616	1973-74 1973	frontrear	149.99 149.99	
----------------	-----------------	-----------	------------------	--





1974-79 Bumper Filler

Replacement fiberglass bumper fillers for 1974-79 Nova models. It is recommended you replace all pieces of the bumper filler for a better bumper fit.

Front	Bumpe	r Fillers		203] 4 1	152
RP503	9 1	1974	left	89.99	ea
RP503	8	1974	center	89.99	e
RP504		1974	right	89.99	
RP504		1975-79	left	89.99	
RP504	15	1975-79	right	89.99	ea
		r Fillers			
RP503	7**	1974	complete	148.99	ea
RP504	12	1975-79	left	89.99	ea
RP504		1975-79	center	135.99	e
RP504	1	1975-79	right	89.99	e









C2390 1962-65



Bumper Components



1966-67 Front Bumper Guards

OER® Authorized front bumper guards for 1966-67 Chevy II/Nova models. These chrome-plated guards are manufactured to factory specifications for an authentic fit. Includes hardware. Sold in pairs.



1968-72 Front Bumper Guard Cushions

Reproduction of the original front bumper guard inserts that were originally installed on 1968-72 Chevy II/ Nova models with the bumper guard option. Includes correctly sized studs for a flush placement into the bumper guard. Front bumper guard inserts attach to the deluxe style steel vertical bumper guard with mounting hardware. Sold in pairs.





1968-72 Rear Bumper Guard Cushions Reproduction of the original bumper guard inserts that were factory installed on 1968-72 Nova's with rear

bumper guards. Also fits 1973 Oldsmobile Omega front bumper guards. These are manufactured from injection molded rubber with steel inserts and correct mounting stud locations as original. Replaces OE #3916640 or 987179. Sold as a pair. K453 1968-72

LH and RH



1962-65 Front Inner Bumper Brackets

Reproduction of the original inner front bumper brackets designed for use with 1962-65 Chevy II/Nova models. Each bracket is manufactured in stamped steel to factory specifications allowing the bumper to fit correctly. Replace your bent or damaged original missing with these quality reproductions. Includes LH and RH brackets. Sold in pairs.

1962-65 LH and RH..... 84.99 pr P22250



1962-65 Front Outer Bumper Brackets

Reproduction front outer bumper brackets for 1962-65 Chevy II/Nova models. Manufactured to original specifications, each bracket will install as original. Note: Mounting hardware available separately

P22240 1962-65 LH and RH...... 84,99 pr



1966-72 Front Bumper Brackets

OER® front bumper brackets for 1966-72 Chevv II/ Nova models. Manufactured from quality stamped steel to factory specifications and EDP coated for rust prevention

N6533		LH and RH	69.99 pr
Inner and	d Outer Bra	ckets	
		LH	34.99 pr 34.99 pr
N68721	1968-72	RH	34.99 pr
LH and I	RH Brackets	s – 4 Piece	
N2337	1968-72		107.99 kit




1966-67 Outer Front Bumper Brackets

These brackets are just what you need to remount your 1966-67 Chevy II/Nova front bumper. They are manufactured to replace the originals exactly. Sold in pairs N740301 1966-67 LH and RH 59.99 pr



1962-65 Rear Bumper Brackets

This is a high-quality reproduction of the rear bumper brackets on 1962-65 Chevy II/Nova. These stamped steel, EDP coated brackets feature precise bends and mounting holes, they will fit and function like new. P22268 1962-65 LH and RH 94,99 pr







1966-72 Rear Bumper Brackets 🔥 OER® rear bumper brackets for 1966-72 Chevy II/

Nova models. Manufactured from quality stamped steel to factory specifications and EDP coated for

3872265	1966-67	LH	38.99 ea
3872266	1966-67	RH	
3916601	1968-72	LH	29.99 ea
3916602	1968-72	RH	29.99 ca

POMPONENT

License Components

New!






individual 1.69 ea

8557 TF400727 MN1701 Stainless Steel Capped Bumper Bolts 🔥


These stainless capped bumper bolts were used on both the front and rear bumpers on most 1962-72 vehicles, features the correct style low dome or flat style head. Includes bumper bolt and retaining put

Includes b	umper bolt a	ind retaining nut.	
7/16"-14:	x 1" - Low 1	Dome	
8557	1962-72	individual	1.69 ca
7/16"-14:	x 1-1/4" - L	ow Dome	
TF400727	1962-72	individual	1.99 ca
17758C	1862-72	8 piece	12.99 set
7/16"-14	x 1" - Flat		

1969-72







1962-72 Bumper Bolt Sets

Replace worn out or rusted bumper bolts with these high quality reproductions. Each set contains stainless steel capped bumper bolts.

Note: *Includes bumper bracket bolt.

ivote. Thei	uaes vumper	DIGUKEI DOUS.	
Front and	Rear Bum	per Bolt Sets	
GM158	1962-65		
GM198	1966-67	42 piece	18.99 set
NB6272*	1968-72	64 piece	24.99 set
Bumper E	Bracket Mou	inting Set	
GM159	1962-65	20 piece	14.99 set





1968-79 Chevy II/Nova Rear License Plate Bracket/Gas Door

B1019

OER® original style reproduction rear license plate bracket designed for use on various 1968-79 Chevy II/ Nova models. Manufactured in stamped steel to factory specifications for an authentic appearance. The door features a spring action hinge that allows access to the gas cap. License plate screws and insert nuts available separately.

344330	1975-79	24.99 ca
B1019	1973-74	
344330	1968-72	



1962-65 License Plate Bumper OER*reproduction of the original rubber license plate

bumpers originally installed on 1962-65 Chevy II/ Nova models. This bumper will keep the license plate bracket from making contact with the rear body panel possibly causing damage. Includes a set of 4 bumpers. 15/32" Diameter, 1/8" Tall K132 1962-65 4 piece 3.99 set



1966-74 License Plate Rubber Bumpers Reproduction rubber bumper originally installed

Carbo base Carpo


Chrome-Plated License Plate Bolt Set 🖽




License Plate Attachment Screw & Nut Kit

Original t	ype replacement screw and nut kits for th late bracket. The nylon nuts push into th
	nd screws secure the plate to the bracket.
K49007	10 piece - 5 screws, 5 nuts 4.99 ki
K49067	4 piece – 2 screws, 2 nuts 2.99 ki

1970-79 License Plate Installation Nut





1962-67 Underhood/Trunk Fastener Set 🔥

If you are looking for a bolt set for under the hood and the trunk area then this is it! The only complete set available for your Nova. Includes: fender bolts and U-nuts, hood hinge bolts, wheel well bolts and Us, radiator bolts, trunk lid bolts, bood latch, horn bolts, motor grounding serew. AC heater housing serews, master cylinder nuts, taillight nuts, windshield washer bottle, grill serews and nuts and more!

FK205 1962-65 215 piece 119.99 set FK201 1967 162 piece 99.99 set











Reproduction Hoods



1962-72 Chevy II/Nova Hoods

OER® Authorized standard hoods for 1962-72 Chevy II/ Nova models. Manufactured from high-quality OE gauge stamped steel to factory specifications featuring the correct shape, contours, and under hood bracing. Black EDP coated for rust prevention.

Note: Shippe	ed truck freight.	Track/religit
3826866	1962-65	299.99 ea
3872998	1966-67	279.99 ea
3938623	1968-72	279.99 ea





1962-74 Cowl Induction Hoods OER® Authorized cowl induction hoods for 1962-74

Chevy II/Nova models. Manufactured from high-quality OE gauge stamped steel to factory specifications featuring the correct shape, contours, and under hood bracing. Black EDP coated for rust prevention.

2" Cowl Inc	luction Hoo	ds	Texting	7
3826866C	1962-65	2"	349.99	ca
N6667	1966-67	2"	299.99	ca
3974588C	1968-72	2"	309.99	
341058C	1973-74	2"	324.99	ca
4" Cowl Inc	luction Hoo	ds .		
3974589C	1968-72	4"	309.99	ca

HARWOOD



1966-74 Fiberulass Hood

Fiberglass replacement hoods for 1966-74 Chevy II/ Nova models. Lightweight and sturdy in construction. Important: *Low tension hood springs are required for

mus noou.		
Note: Shipp	ed truck freight.	
	d - Hood Pin Style	Distributed.
F13100	1966-67	389.99 ea
F14100	1968-74	414.99 ca
	ood - Bolt-On Style	
N14660*	1968-74	689.99 ea
Stock Hoo	d with Cowl Panel - I	Hood Pin Style
E14005	1968-74	415 99 ca

HARWOOD



1962-74 Cowl Induction Fiberulass Hood

These fiberglass cowl induction hoods from Hardwood Industries will either meet or exceed your expectations for looks, clearance, or weight restrictions. Available in "pin-on" or "bolt-on" variations. "Bolt-on" hoods require part #B210 medium tension springs not the low tension springs.

rtant: *F14105 hood has a cowl panel integrated into the hood. Deletes factory cowl panel and windshield wipers. Note: Shipped truck freight.

	Hood Pin Style	
2" Cowl Inc		
F14102	1968-74	424.99 ca
4" Cowl Inc		
F13034	1962-65	431.99 ca
	1966-67	
F14104	1968-74	434.99 ca
5" Cowl Inc	luction with Integrated Cow	l Panel
F14105*	1968-74	
6" Cowl Inc		
F13036		
F13106	1966-67	444.99 ca
F14106	1968-74	451.99 ca
	Bolt-On Style	
2" Cowl Inc		
B14102	1968-74	636.99 ea
4" Cowl Inc	luction	
B13104	1966-67	639.99 ca
B14104	1968-74	639.99 ea
6" Cowl Inc	luction	

HARWOOD



1968-74 Pro-Touring Fiberglass Hood Give your Nova the Pro-Touring look with this fine fiberglass hood from Harwood. This Pro-Touring hood

has a 2-1/2" bump and features a fully finished underside and includes a custom trim bezel for the air inlet. The air inlet comes closed from the factory but can be cut open for a functional Ram Air effect. The hood utilizes the factory hinges and latches. Note: Shipped truck freight.

B14107 1968-74 bolt-on type .. 651.99 ea

1968-72 Cowl Induction Hood Screen

This is a really cool idea for cowl induction hoods. You can now cover the opening in the back of the hood on your non-functional cowl hood with this made in the USA stamped steel screen. This screen can be chromed, powder coated or painted to match your vehicle's color. Installs easily without removing

the hood. Includes mounting screws. 14345 1968-72 24 99 ca



1962-79 Underhood/Trunk Mirrors

Make a statement and beautify your engine and trunk compartments with these awesome looking custom cut mirror sets. These mirrors are made of 1/8' thick lightweight and heat resistant plastic that are professionally designed to fit perfectly to your factory hood and trunk lid. Mirror sets can be purchased for under the hood only, under the trunk lid only, or in a money saving hood and trunk set. All mirror sets include silicone, caulking gun, masking tape, 4 oz. cleaner, towel, and instructions

Hood Mirrors

13992	1962-65	315.99 set
13993	1966-67	315.99 set
13994	1968-72	315.99 set
13995	1973-74	315.99 set
13996	1975-79	315.99 set
Trunk Mi	rrors	
13997	1962-65	261.99 set
13998	1966-67	276.99 set
13999	1968-72	276.99 set
14000	1973-74	276.99 set
14001	1975-79	276.99 set
Complete	Mirror Sets	
14002	1962-65	453.99 set
14004	1966-67	453.99 set
14005	1968-72	453.99 set
14006	1973-74	
14007	1075 70	452 00 cat

665 99 ca

1968-74

Hood Insulation











High Temp ABS Finishing Panel

- Logo Design Options

396	427	7
01	02	
56.308	SS 427	

SS 427



Nova Script with SS



🗮 1962-77 Insulator and Cover Set

Precut, ready-to-install insulation panels, and cover! AcoustiHOOD insulator and cover sets by Quiet Ride are designed to help stop the vibration of the hood skin, thus reducing the transfer of airborn noise into the passenger cabin by 20-25%, or 3 decibels. It also covers the hood structure with a high temperature ABS panel to finish off the engine bay. These panels will regularly tolerate temperatures up to 250 degrees F. Important: Does not fit cowl hoods. For best results and air flow, maintain at least one inch or more of clearance between the surface of the hood cover and the engine components. Hood not included and is available separately.

Kit also includes a drill stop sleeve and drilling instructions in case drilling is required. Quiet Ride Solutions attempts to use existing hood pad mounting holes. Drilling may be required if never equipped. For non-metallic hoods (such as fiberglass or carbon fiber), hood magnets will be used to retain the hood cover, and will need to be glued into place. Note: Please specify 2 digit logo code when ordering.

shipments) du	e to aerosol	spray adhesive.	082
A74021	1962-65	specify logo	251.99 set
A7402100	1962-65	without logo	177.99 set
A74022	1966-67	specify logo	251.99 set
A7402200	1966-67	without logo	177.99 set
A74023	1968-72	specify logo	251.99 set
A7402300	1968-72	without logo	177.99 set
A74024	1973-77		251.99 set
A 7402400	1072 77	without logo	177.00 cat



1962-74 Hood Insulation

Reproduction hood insulation for 1962-74 Chevy II/ Nova hoods. Each hood insulation is manufactured in a heat resistant material which will help to extend the life span of the paint on your hood and helps dissipate heat from your engine compartment.

K4082	1962-65	20.99	set
K4083	1966-67	20.99	set
K4085	1968-74	20.99	set



Universal Hood Insulation

Dynamat hoodliners will protect your vehicle's paint and reduce irritating underhood noise. Made from 3/4" acoustic sound soaker foam with a reinforced. aluminized skin that is oil and water resistant. The hoodliner has a high tack pressure sensitive adhesive for easy peel and stick application. For those who prefer black, there is also Dvnaliner, which boasts the highest heat blocking properties available in a single layer synthetic foam. Dynaliner is available in 1/4" and 1/2" thick. Use the thickest one your space will allow. All hood insulation sheets measure 32" x 54" Hoodlings

DM11905	3/4"	72.99	ca
Dynaliner			
DM11102	1/4"	54.99	ca
DM11103	1/2"	87.99	ca



1975-79 Hood Insulation Retainer


Reproduction hood insulation retainers are just what your Nova needs! Keep your original hood insulation where it belongs ... attached to the hood. These retainers are service replacements for most models. They may differ cosmetically from the original retainer but will fit and function properly. Black nylon. Measurements: head diameter: 1-3/4*, stem diameter: 5/16*, stem length 3/4*. Sold Individually. Use as required. A1015





Underhood Thermal Acoustic Lining 🔥

DEI underhood thermal acoustic lining. Designed specifically for underhood applications, this lining will greatly reduce the heat, noise, and vibration coming from your engine compartment. Self-adhesive. 3/4" thick industrial acoustical grade foam with a reinforced reflective aluminum covering. 12 square feet of material is enough to insulate your entire hood.








Underhood Black Thermal Acoustic Lining

DEI black underhood thermal acoustic lining. Designed specifically for underhood applications, this lining will greatly reduce the heat, noise, and vibration coming rom your engine compartment. This black selfadhesive carbon fiber look material measures 32" x 59" (13.1 sq. ft.), enough to insulate your entire hood. DE050129 32" x 59".



Jute Padding Insulation

This insulation is just what you need to completely insulate the interior of your vehicle against cold or heat. Developed from 99.5% pure industrial grade aluminum, the insulation gives 97% reflectivity against heat radiation. Jute padding will insulate your interior for noise while helping to maintain an even temperature.
Use on firewalls, floor pans, trunks, doors, and roof

panels or other areas of the vehicle. CMD1003 4' x 2" x 6'











HARWOOD Fiberglass Hood Scoops



Fiberglass Cowl Hood Scoop

underhood and reduce weight while providing a high- bolt-on styles.

These hood scoops are designed to provide extra clearance | be bonded or riveted on, and also a limited selection of

	erformance look. Available in a flanged style that can No	a. supper overage. supper touch overage. supper track freign.
--	---	---

rart#	Style	Length		wiatn		neight	Notes	Frice
HA1103	flange	43"	X	28"	x	2.5"	trim to length for desired fit	179.99 ea
HA1107	flange	43"	X	28"	X	4"	trim to length for desired fit	184.99 ea
HA1111	flange	53"	X	28"	X	2"	trim to length for desired fit	184.99 ea
HA1112	flange	54"	X	28"	X	3.5"	trim to length for desired fit	179.99 ea
HA1114	flange	53.5"	X	31"	X	4"	trim to length for desired fit	224.99 ea
HA1116	flange	49"	X	28"	X	6"	trim to length for desired fit	226.99 ea
HA1124**	flange	53.5"	X	28"	X	4"	smooth top - trim to length for desired fit	224.99 ea
HA1126*	flange	57"	X	28"	X	6"	smooth top - trim to length for desired fit	224.99 ea
HA1128	flange	54"	X	28"	X	8"	smooth top - trim to length for desired fit	229.99 ea
HA4103*	bolt-on	43"	X	29.5"	X	2.5"	rivet-on	199.99 ea
HA4104	bolt-on	43"	X	29.5"	X	4"	rivet-on	201.99 ea
HA1117	flange	53.5"	X	27"	X	7.5	flange	231.99 ea



HARWOOD Fiberglass Hood Scoops

































Fiberglass Aero Hood Scoop

These hood scoops are designed to provide maximum air flow and a lightweight advantage while providing a look that will fit in with the sleekest of all-out performance machines. Available in a flanged style that can be bonded or riveted on, and also a limited selection of bolt-on styles. A selection of scoop plugs are also available.

Note: Larger scoops are shipped oversize.

							,				481
Part #	Type	Style	L		W		H	OAL	Notes	Use Plug #	Price
HA3161	Aero Pro I	flange	36"	Х	17"	Х	11"	48"	open back	HA2000	284.99 ea
HA3163	Aero Mini II	flange	30"	Х	15"	Х	7"	31.5"	closed back	HA2001	284.99 ea
HA3164	Aero II	flange	29"	Х	17"	Х	9.5"	35"	closed back	HA2000	284.99 ea
HA3165	Aero Mod I	flange	43"	Х	17.5"	Х	8.5"	48"	closed back	HA2000	284.99 ea
HA3166	Aero III	flange	29"	Х	17"	Х	7.5"	35"	closed back	HA2000	284.99 ea
HA3168	Aero Pro III	flange	37"	Х	20"	Х	11"	48"	open back	HA1999	279.99 ea
HA3182	Tri Aero	flange	40"	Х	14"	Х	13"	51"	open back	HA1996	334.99 ea
HA3183	Tri Aero Mini	flange	30"	Х	14"	Х	11"	33.5"	closed back	HA1996	334.99 ea
HA4162	Aero Mini I	bolt-on	30"	Х	14.5"	Х	9"	32"	incl gskt & hdwr	HA2001	344.99 ea
HA4163	Aero Mini II	bolt-on	30"	Х	15"	Х	7"	31.5"	incl gskt & hdwr	HA2001	341.99 ea
HA4164	Aero II	bolt-on	29"	Х	17"	Х	9.5"	35"	incl gskt & hdwr	HA2000	344.99 ea
HA4166	Aero III	bolt-on	29"	Х	17"	Х	7.5"	35"	incl gskt & hdwr	HA2000	344.99 ea
HA1996	scoop plug	use with H	A3182,	HA	3183						45.99 ea
HA1999	scoop plug	use with H	A3168.								35.99 ea
HA2000	scoop plug										45.99 ea
HA2001	scoop plug	use with H	A3162,	HA	3163, H	A4	162, HA4	163			45.99 ea











Hood Accessories



1968-79 Fiberulass Hood Scoon

Give your hood a touch of high-performance styling inspired by the scoops found on the famous Camaro IROC-Z for a sleek performance look. Manufactured in fiberglass rather than ABS plastic. This scoop measures: 50-1/2" x 24-3/4" x 3".

ote: Shipped double oversize PT15730 1968-79. 259.99 ea



Universal L-88 Style Hood Scoop

Give your vehicle some high-performance styling with this universal fit L-88 style hood scoop. Patterned after the famed L-88 hood originally found on 1968-69 Corvettes with the L-88 engine, this scoop is manufactured in high grade fiberglass rather than ABS plastic. This scoop measures: 45-1/2" x 26" x 3-1/2" Vote: Shipped double oversize.

264 99 ca

PT5639



Universal Hood Scoon

Add a subtle performance look by adding this cowl style hood scoop to the hood of your car. This universal style hood scoop is manufactured in fiberglass for added durability. Measures: 31-1/2" x 26" x 1-3/4" Note: Shinned oversize PT5700



Aluminum Finned Hood Scoon

Do you really want an ordinary stamped metal or fiberglass hood scoop? This unique and eve-catching finned hood scoop is east in the USA from A-356 aluminum alloy and polished to show quality finish. For those that may want to paint the hood scoop, a unpolished (sand blasted) finish is also available. Includes a full scale drilling template to tape to your hood for precise installation. Measures: 14-3/4" x 11" x 3-3/8" Opening measures 2-3/4" H

Note: Requires	eight 1/4"-20 hardware, not inc	luded.
A9706880	polished	248.99 ca
A9706881	unnolished	184 99 ca



1968-72 Super Sport Hood Louvers 🔔

OER® reproduction hood louvers for 1968-72 Nova Super Sport models. Each cast hood louver is painted black and features bright chrome accents with necessary mounting hardware and chrome bezels included Purchase the kit and save or just the individual components needed for your restoration.

Hood Louver Kit

3927442 3949698	1968-72 1968-72	louver bezels louver gaskets	43.99 ca 6.99 ca
3918764	1968-72	hood louvers	
	1700 72		

1968-72 Hood Louver Bracket

This high-quality reproduction is a must when restoring your 1968-72 Nova Super Sport back to its original condition. These stamped steel brackets mount the SS hood louvers to the underside of your hood. 1968-72 LH and RH.



1968-72 Hond Louver Gaskets

These gaskets are designed to prevent moisture from being trapped under the hood louver. Choose the original style adhesive backed sponge foam in roll form or replacement style molded gasket.

K964 1968-72 die-cut, LH and RH.... 9.99 pr 3949698 1968-72 OER® strip type -2 req.. 6.99 ea



Track Spec lightweight aluminum performance hood louvers. Increases performance by reducing engine compartment temperatures. Satin black powder coated for durability. Includes detailed instructions and all hardware required for a factory quality installation. Note: Product requires cutting

Angled TL20013 TL20014	4" x 12" 5-1/2" x 12"	179.99 pr 189.99 pr
Rectangular TL20015 TL20016	4" x 12" 5-1/2" x 12"	



35

39

R



1963-79 Hood Hinde

Original factory replacement or our superb quality reproduction hood hinges! Reproductions are manufactured from OE materials using new tooling. Hood hinge spring not included.

Important: The hinges for 1962 and 1963 2nd design used an 18 coil spring, and are currently not available. Note: *For use with 27 coil spring - 1st and 3rd design.

ER® Rep	roduction -	Black EDP Coate	d	
		LH		
	1963-65			
		LH		
		RH		
926829	1968-79	LH	49.99 ea	
926830	1968-79	RH	49.99 ea	
		pe – Dark Gray P		
54111	1966-67	LH	119.99 ea	
54112	1966-67	RH	119.99 ea	
eproduct	ion - Chron	re-Plated		
52227	1066 67	I U and DU	267 00 pr	



1966-74 Billet Hood Hinges

CNC-machined from solid 6061-T6 billet aluminum, these hinges are a direct replacement piece with no modifications necessary and feature ball bearing pivot joints and gas shocks either as a solid frame hinge or the new high tech air frame. Installation hardware and instructions included. Available in natural or black anodized aluminum finishes and for steel or fiberglass hoods.

	Solid	Arm Style	
Natural Ali			
CB60011	1966-67	steel hood	699.99 pr
CB60012	1966-67	fiberglass hood	
CB61011	1968-74	steel hood	699.99 pr
CB61012	1968-74	fiberglass hood	699.99 pr
Anodized E	lack		
CB60021	1966-67	steel hood	749.99 pr
CB60022	1966-67	fiberglass hood	749.99 pr
CB61021	1968-74	steel hood	749.99 pr
CB61022	1968-74	fiberglass hood	749.99 pr
	Air F	rame Style	
Natural Ali			
CB60111	1966-67	steel hood	699.99 pr
CR60112	1066 67	fiberglass bood	600 00 pr

Natural Ali			
CB60111	1966-67	steel hood	699.99 pr
CB60112	1966-67	fiberglass hood	
CB61111	1968-74	steel hood	699.99 pr
CB61112	1968-74	fiberglass hood	699.99 pr
Anodized E	lack		
CR60121	1966-67	steel bood	740 00 pr

fiberglass hood...

749.99 pr 749.99 pr

1966-67

1069 74

CB60122

CB61121

Hood Accessories



1963-79 Hood Hinge Springs

OER® hood hinge springs for 1963-79 Chevy II/Nova models. Manufactured from high-quality OE gauge spring steel to factory specifications. 2 required. 3848272 1963-64 14 99 ca 3864680 1965 22.99 ea 409025 1966-79 12.99 ea



1963-79 Stainless Hood Hinge Springs

Add a custom touch to your hood hinges with these brightly polished stainless steel hinge springs for 1963-79 models. Each spring is manufactured to fit and function like the original unit, while giving your underhood area the finishing touch. Manufactured to operate original or reproduction steel hoods only

153103	1963-64	132.99 pr
153102	1965	129.99 pr
153101	1966-67	137.99 pr
153101	1971-79	137.99 pr



1966-79 Low Tension Hood Springs 🔥

Never have to use a 'prop' rod on your trick looking fiberglass hood again. These low tension springs will allow you to retain the original workings of your hood. For cowl induction hood

B200 low tension 39.99 pr B210 medium tension..



1962-72 Stainless Hood Hinge Bolts 🔥 Replacement stainless steel hood hinge bolts with fixed

conical washers for 1962-72 Chevy II/Nova models.
Black oxide or plain stainless finish.

	de Coated Stainless Steel		
153343	1962-67	29.99	SC
153341	1968-72	19.99	St
Plain Stai.	nless Steel		
153344	1962-67	29.99	SC
153342	1968-72	19.99	cr

OE Style -Black Phosphate Coated

1962-79 Hood Hinge Bolt Set

Correct replacement hood hinge bolts for 1965-79 Chevy II/Nova models. Replacement style for 1962-64

models.	9/16" Hex with flat t	ip with 1" free	e spinning
conical v	vasher. Phosphate co	ated.	
B4244	3/8"-16 x 13/16"	8 piece	10.99 set



Replacement Hood Hinge Bolts

Replacement Hex head style bolts with loose washers available in polished chrome or polished stainless steel. For use on all Chevrolet hood hinges. Set of 8. ΔK120Δ 16 99 set chrome AK120B polished stainless.. 31.99 set



Adiustable Hood Prop

Constructed of high-quality aluminum and stainless steel, these adjustable hood props offer great looks as well as functionality on your ride. When the hood is raised, the hood prop will automatically lock itself into position. A quick release allows the hood to be opened to its max for easy engine access. A three position and a six position option allows the hood to be set at various levels. Each level of the 6 position prop increases the opening of the hood by approximately 6". Each level of the 3 level prop increases the opening of the hood by approximately 12". They also works great for cooling your engine in the staging lanes.

01024 6 position aluminum 89.99 01014B 3 position black 86.99 01024B 6 position black 89.99		3 position 6 position 3 position 6 position			c
---	--	--	--	--	---



Stainless Steel Hood Adjuster Custom replacement billet stainless steel hood adjusters

include rubber bumpers and are sold individually. Available in 1/4"-20, 5/16"-18, and 7/16"-14. ... 32.99 ca FB1057A FB1057B 28.99 ca FB1057C 7/16" - 14 32.99 ca



1962-73 Hood Adjuster Screw and Bumper

This correct OER® reproduction bumper and screw assembly is designed to fit on and adjust any 1962-73

K551 K555 3792828	1962-73 1962-73 1962-73	bolts and nuts only bumpers only	7.99 pr
-------------------------	-------------------------------	-------------------------------------	---------



1972-74 Underhood Lamp

Under hood lamp assembly for 1972-74 Nova models Manufactured to factory specifications featuring correct color wiring and terminal ends.

NV20682 1972-74. 40.99 ea

1965-66 Hood Lamp to Hood Bumper Reproduction rubber bumper. For 1965-66 Chevy II/

Nova models. This bumper was installed as the underhood lamp to hood bumper. 3762180 1965-66.





Hood Release Cable

The cables are cut-to-fit, designed with a specially extruded liner, aluminum fittings and stainless steel inner wire. The outer housing is 18" inside the vehicle

and 6' under the hood. The inner wire is 9' long. Available in a black or stainless steel housing with a billet cutout handle. Note: Requires cable operated latches. HR 1100 stainless steel housing 132.99 ea

100B	black housing
Hor	D ACCESSORIES

HR1100B









YOO E

D11703

Hood Accessories



1965-79 Hood Latch Pilot Rolt Reproduction hood latch bolt which attaches to the lock plate retainer. 1 required. 1/2"-20 x 3-15/16" 3857883 1965-79 .. 11.99 ca



1962-79 Stainless Hood Latch Pilot Bolt

Add a custom touch to your hood latch with this brightly polished stainless steel pilot bolt for 1962-79 Chevy II/Nova models. Each bolt is manufactured to fit and function like the original unit, while giving your underhood area the finishing touch. Made in USA. 153107 1962-64 34.99 ea

1965-79 35.99 ea

	-
	19
W ST	100

1963-74 Hood Safety Latch

Reproduction hood safety latch for 1963-74 Chevy II/ Nova models. This bracket and pilot bolt are mounted to the underside of the hood and act as a guide for the latch mechanism. Manufactured to factory specifications for proper fitment and function. Comes coated for rust prevention

153742	1963-64	32.99	ca
153743	1966-67		
153046	1968-74	39.99	ca



1963-74 Billet Hood Safety Latch

Direct replacement billet hood safety latch assemblies made from a solid piece of 6061-T6 aluminum and 304 stainless steel. Hood latch comes with a billet aluminum base plate, pilot bolt and retaining cup and pop-up spring (some applications). Stainless steel fasteners and billet aluminum finishing washers also included. Offered in black, polished, or satin finishes.

A7400101	satin		
A7400102	polished		
A7400103	black	174.99	ca
1966-67 Nova			
A7400104	satin	139.99	ca
A7400105	polished	161.99	ca
A7400106	black	174.99	ca
1968-74 Nova			
A7400107	satin	139 99	ca
A7400108	nolished	161 99	

black



1966-79 Hood Latch Assembly

Reproduction hood latch assembly for 1966-79 Chevy II/Nova models. These latch assemblies are

15112	1966-67		
15113	1968-72	57.99 c	a
6274330	1973-74	64.99 c	a
345535	1975-79	89.99 c	a



1966-79 Hood Latch Catch Support 🔥

The hood latch catch support is located between the grill and radiator support. The hood latch assembly bolts to the upper portion of the support and is stabilized by the support. Produced in correct gauge metal and comes finished in black EDP.

8872940	1966	
3892284	1967	29.99 ea
3938635*	1969-72	22.99 ea
339409	1973-74	
356624	1975-79	49.99 ca



1966-74 Flip Over Style Hood Pins

This set uses the 2 piece flip over pins ideal for installations where an extra strong pin is required. Ring flips over stud and over center action eliminates possibility of pin falling out. Includes lanyards. flip over style







CR40046

Rillet Hood Pins

Machined from 6061-T6 billet aluminum, these hood pins feature a base that screws into core support for easy installation and includes stainless steel locking pin for secure closure. Installation hardware and instructions included. Sold in pairs, available in natural or black finish

B40046 B40047	natural black	
	4	0

25100P





247.99 pr



Universal Simulated Hood Pins

Get the look of billet hood pins without having to drill holes in your expensive hood. Machined billet plate from 6061-T6 aircraft aluminum, stainless steel pins. screws and cables. Installs in minutes with no tools. just peel and stick. Available in classic or striker design. 24" cables sold separately.

Note: These are non-functioning hood pins

Hood Pir	15		
25109P	classic	polished	
25109B	classic	black	54.99 se
25110P	striker	polished	54.99 sc
25110B	striker	black	54.99 sc
Cables O	nly		
25113R	24" long	red	16.99 pt
25113B	24" long	black	16.99 pi
	and the same	and therein	





These Hotchkis custom universal hood pins add a high tech aerospace look to your car. They offer lightweight durable construction, easy installation, secure hood closure, and killer good looks.

universal.. 204.99 set











These U.S. made, 6061-T6 aluminum hood pin and scuff plate sets will help your car stand out in a crowd and complement any style hood. The billet scuff plates are available in your choice of machined, polished, or powder coated black finish. All hood pin sets include 6* aluminum pins and stainless steel hardware, so you'll never have to worry about rust.

HP5001	machined finish	99.99 set
HP5002	polished finish	109.99 set
HP5003	gloss black powder coated	119.99 set
HP5005	chrome-plated	129.99 set

174 99 ca

YOU

Reproduction Fenders

AUTHORIZED



1962-67 Fenders

OER® Authorized and standard replacement front fenders for 1962-67 Chevy II/Nova models. Manufactured from quality stamped steel to factory specifications featuring the correct shape, contours and mounting holes. Black EDP coated for rust prevention. Note: Shipped truck freight.

OER® Autho	rized		Track I religite
3859177	1962-65	LH	199.99 ea
3859178	1962-65	RH	199.99 ea
Standard Re	placement		
3888235	1966	LH	369.99 ea
3888236	1966	RH	369.99 ea
OER® Autho			
3892221	1967	LH	
3892222	1967	RH	319.99 ea

PHOICE...



1968-74 Chevy II/Nova Fender

Reproduction fenders for 1968-74 Chevy II/Nova models. Available in your choice of our Restorer's Choice™panel or standard replacement, manufactured in OE gauge steel featuring all original contours and details, or our standard replacement for the car builder on a budget. Fenders come finished in semi-flat black EDP coating to prevent rust and are ready to prep and

Note: Shipped	truck freight.		
Restorer's Cl	ioice TM		Text tests
3953851B	1968-69	LH	299.99 ca
3953852B	1968-69	RH	299.99 ca
6258337B	1970-74	LH	299.99 ca
6258338B	1970-74	RH	299.99 ca
Standard Rep	placement		
3953851A	1968-69	LH	259.99 ca
3953852A	1968-69	RH	259.99 ca
6258337A	1970-74	LH	239.99 ca
6258338A	1970-74	RH	230 00 ea



1962-67 Fender Auron

Reproduction passenger side fender apron for all 1962-67 Chevy II/Nova models. This panel installs on the front side of the inner fender panel and acts as the mounting point for the battery tray. Black EDP coated. 15245 1962-67 RH. 54.99 ea



1966-67 Inner Front Fender Panel

Reproduction 1966-67 inner front fender panels with lower frame rails. Features provisions for the upper and lower suspension arms, shock tower mounts and hood hinges. These panels also feature holes stamped in the correct locations for mounting the fender and mounting various engine compartment items. Panels are EDP coated for rust prevention and have all the correct ribbing and reinforcements as original Important: For factory type front suspension only

14725	1966-67	LH	624.99	c
14726	1966-67	RH	624.99	c



1962-67 Front Frame Inner Fenders 🔥

Detroit Speed's Chevy II inner fenders are designed to fit Chevy II models equipped with a DSE Chevy II front frame. They completely hide the front frame down bars resulting in a neat and clean underhood appearance. The inner fenders are stamped from 18 gauge steel and are made in the USA.

Note: Shinned double oversize 994.99 pr D32035 1962-65 I.H and RH 994.99 pr D32036 1966-67 LH and RH ..







1962-67 Inner Fender Panel

Now you can install new inner fender panels to complete your 1962-67 Chevy II/Nova subframe installation They are stamped so that they will bolt directly to the fenders, core support and frame rails, and include hood hinge mounting plates, firewall seals, and hardware They can also can be used where a Mustang II IFS suspension has been installed on stock frame rails. Note: Shipped oversize. 301.99 pr HS325 1962-65 ..

301.99 pr AFTHORIZED



1968-74 Inner Fender Well

Each fender well is manufactured with OEM thickness steel just like original. Each panel will fit and install correctly allowing the rusted or damaged panel to be replaced. These reproductions also include an EDP

oating that helps eliminate rust.				
Note: Shipped double oversize.				
N127	1968-74	LH	79.99 ea	
N126	1968-74	RH	79.99 ca	



HS326 1966-67



1968-74 Fender Skirt to Firewall Brace

Reproduction skirt braces that mounts to the rear inner side fender, dash panel bracket, and the firewall brace. C2363 1968-74 LH... 10 00 00 C2362 1968-74 RH 19 99 ca









K0076 1962-72



Fender Components







1962-79 Fender Patch Panel A correctly stamped front fender patch panel which

installs on the rear lower fender area. Each panel will replace the rear lower section of this commonly rusted rear area without replacing the entire fender. 1962-65 Models

PDN97L	LH	13" x 18"	84.99 ca
PDN97R	RH	13" x 18"	84.99 ca
1968-74 Mo	dels		
15253	LH	11-1/2" x 15-1/2"	64.99 ca
15254	RH	11-1/2" x 15-1/2"	64.99 ca
1975-79 Mo	dels		
PDN100L	LH	13-1/2" x 16"	79.99 ca
DDMIIOOD	DU	13-1/2" x 16"	70 00 an



1962-72 Lower Fender Extension Braces

The fender extensions require steel braces to connect the extensions to the fenders. Some applications include mounting bolts for installation. Sold in pairs.

ote: *Includes mounting hardware.

1662696	1962-65	LH and RH	9.99	_
1662678*	1966-67	LH and RH	9.99	
1662679*	1968-72	LH and RH	9.99	pr
Stainless :	Steel			
15102	1966-67	I.H and RH	49 99	m





suspension and wider wheels are suggested to achieve the right stance. Dimensions are approximate



Clinched Fender Flares Add an aggressive, wide body look to your muscle car with clinched flares universal fender flare sets. These

versatile flares can be installed on most makes and models with minor modifications. Flares are made from automotive grade, impact resistant 3mm ABS plastic for great looks and durability. Each set includes: 1 pair of flares, rubber gaskets, and type 3 installation hardware. Flares can be blended in with your fenders or left with open rivets. Available in a variety of styles and sizes to suit any virtually any build. Note: Installs with rivets/bolts and will require drilling/cutting of the fender/quarter panels in order to install. Lowered

Classic Style

Classic style features "pointy" tips and work very well not just on the classics but also on the more modern cars

Part#	A	B	C	D	Price
CF1090	2-1/4"	29-1/2"	18-3/4"	1-1/4"	149.99 set
CF1091	2-1/4"	29-1/2"	20"	2"	169.99 set
CF1092	4"	29-1/2"	17-3/4"	3-1/2"	199.99 set

New school style is the most universal line of fender flares. The go-to flares for most modern cars, this line

Part#	A	B	C	D	Price
CF1093	3-1/2"	34-1/4"	21"	1-1/2"	189.99 set
CF1094	3-3/4"	34-1/4"	21"	2-3/4"	239.99 set
CF1095	4"	34-1/4"	21-3/4"	4"	259.99 set
			Muscle Style		

Muscle styl	le pushes it to th	e next level for all th	ose looking to wi	le body their muscle cars.	
Part#	A	B	C	D	Price
CF1096	4-1/2"	33"	20"	4"	. 369.99 sc
CF1097	4-1/2"	33"	20"	4-3/4"	389.99 sc
CF1098	4-1/2"	33-3/4"	20"	6"	419.99 sc



1969-72 Front Fender Ornament

Reproduction fender ornament for 1969-72 Nova models with Exterior Decor Package (ZJ5). Fits LH or RH fender.

C21570 1969-72 29 99 ca 2 required...



1968-79 Outer Cowl Side Panel

Replace your rusted or damaged cowl side panels with these quality reproductions. These panels are installed behind the fenders at the sides of the firewall. C69541L 1968-79 LH uncoated...... 88.99 ea C69541R 1968-79 RH uncoated 88 99 ca







1966-67 Cowl Side Panel

Replace your rusted or damaged cowl side panels with these quality reproductions. These panels are installed behind the fenders at the sides of the firewall. Available with EDP coating or in a Weld-ThruTM Primer.

Outer			
14713	1966-67	LH - EDP coated	49.99 ea
14712	1966-67	RH - EDP coated	49.99 ea
14713W	1966-67	LH − Weld-Thru™	56.99 ea
14712W	1966-67	RH – Weld-Thru TM	56.99 ea
Inner Sid		oulder Panel	
153048	1966-67	LH − Weld-Thru™	114.99 ea

153049

WARNING: Cancer and Reproductive Harm-www.P65Warnings.ca.gov

1966-67 RH - Weld-Thru™ 114 99 ea

Т

YOU

COMPONENTS

Body Panels



1966-74 Fiberglass Front End

This fiberglass front end assembly is designed to fit various 1966-74 Chevy II/Nova models, Includes: the front fenders, grill, headlamp section, lower front valance, and bumper assembly. This form of construction completes a solid belly pan look and offers extreme rigidity. Perfect for strip or show.

ortant: This item does not include the hood p (sold separately). Not intended for street use. *Although originally designed for a 1967 model, the front end will also fit a 1966 Nova. **Although originally designed for 1968-72 models, the front end will also fit 1973-74 models.

Note: Shipped truck freight 1966-67 less hood. F13000* 1054.99 ea F14000** 1968-74 1054.99 ea less bond



1966-67 Front End Doghouse Assembly

Reproduction of the commonly rusted front end assembly for 1966-67 Nova models. Manufactured to factory specifications this assembly features correct contours, and includes the radiator support, inner fenders, shock towers and all factory bracing. Comes coated in Weld-Thru™ Primer.

Note: Shipped truck freight, Special order. 153061 1966-67



15723



1966-67 Lower Cowl Panel

Reproduction lower cowl panel for 1966-67 Chevy II/ Nova. This panel is welded-in below the cowl top vent grill panel. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped

panels, and	d promotes	superior weld chara	cteristic	S
Note: Shipp	ed double ov	ersize.	082	
16101	1966-67	EDP coated	219.99	c
1610137	1066 67	Martin Theorem	220.00	



1966-74 Cowl Top Vent Grill Panel 🗥

Reproduction cowl top vent grill panel for 1966-74 Nova models. Manufactured to factory specifications featuring correct contours, original style mounting points. Available with EDP coating or Weld-ThruTM

	ed double ove		8 \$2
16102	1966-67	EDP coated	174.99 ea
16102W	1966-67	Weld-Thru™	189.99 ea
153047	1968-74	EDP coated	159.99 ea

AUTHORIZED



1968-74 Upper Inner Cowl Panel

Reproduction of the upper inner cowl panel for 1968-74 Nova models. Features factory style contours, pre-punched holes, correctly made openings, and mounting points for the windshield wiper motor.

Note: *Made in USA. Shipped double oversize. Without AC C11020A 1069 74 EDP coated 174 99 ca C11020* 1968-74 uncoated 234 99 69



1968-74 Inner Cowl Panel

Reproduction inner cowl panel for all 1968-74 Nova models. Manufactured from heavy steel gauge, features correct contours and is EDP coated for rust prevention. Note: Shipped double oversize.

1968-74.



169 99 00

Body Alignment Shims

One of the most essential parts of sheet metal replacement is alignment shims. These reproduction shims are offered in a variety of sizes for most alignment situations. Check your original shims before ordering. 1-1/4" x 1-1/8" with 3/8" Slot

A3156	1/8" thick	50 piece		
	1-1/4" with 1/2	2" Slot		
	1/16" thick	50 piece	9.99	
A2453	1/8" thick	50 piece	12.99	set



1962-79 Stainless Steel Body Bolt Sets

Tired of endless searching for the correct fasteners? Growing weary of buffing, sanding and painting rusty old fasteners? These stainless steel sets contain individually packaged and labeled stainless steel component sets to eliminate any guesswork in assembling your restoration project. Our original style indented Hex body sets include black stainless where appropriate to retain a factory original appearance while giving you the rust free benefits of stainless steel.

1962-65 Body Bolt Set

Includes: bumpers, door hinges, door latch, door jambs. front and inner fenders, hood hinges, hood latch, hood catch, hood stops, radiator support, crossmember, shock towers, battery box, trunk hinges, trunk latch, trunk catch, tail lamps, master cylinder, windshield washer tank, interior trim screws, and more,

67041 1962-65

1966-67 Body Bolt Set Includes: bumpers, door hinges, door ambs, front and inner fenders, hood hinges, hood latch, hood catch, hood stops, radiator support, front seat mount, master cylinder, shock towers, battery box. trunk hinges, tail lamps, master cylinder, interior trim screws, and more.

1968-74 Body Bolt Set

Includes: bumpers, door hinges, door jambs, front and inner fenders, hood hinges, hood latches, hood catch radiator support, battery box, horn, front seat mount trunk hinges, trunk latch, trunk catch, license plate and bracket, gas tank, interior trim, and more!

1966-67

67203 1968-74 1975-79 Body Bolt Set

Includes: bumpers, door latches, front fenders, grill headlamp bezels, hood hinges, hood latch, hood catch. support, battery box, master cylinder, seat mounts, trunk hinges, trunk latch, trunk catch, interior trim screws, and more! 67803 1975-79 194 99 set



Rody Alianment Shims

Used to align body panels, these shims are available in various thicknesses to suit most alignment situations. Please check your originals to be sure you are ordering the correct size and number of shims necessary for your replacement. Sold in sets of 10. Amount required varies. C2005 1.6mm 10 piece 5.99 set C2004 3mm 10 piece 6 99 set C2001 6mm 10 piece 10 99 set











Body Panels



1969-72 Firewall Panel

Reproduction firewall panel for 1969-72 Nova models. Most original panels have either been drilled, cut, or have simply rusted out. This piece solves the rust problem and features correctly formed and punched openings for the heater box, hoses, throttle, and speedometer cables for simple installation. All panels are EDP coated for rust prevention.

te: Shipped truck freight 274.99 ca



1511490

R1642W

THE BUILD 1966-67 Firewall

Repairing and patching a dented, rusted out or over drilled firewall can be tedious, but now you can skip the headache and replace your 1966-67 Chevy II/Nova model's entire firewall with this reproduction firewall panel. Firewall to floor braces are not included with this panel, and sold separately. Available with traditional EDP coating or in a Weld-ThruTM Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics Note: Shipped truck freight.

15114	1966-67	EDP coated	
15114W	1966-67	Weld-Thru™	

1966-72 Steel Dash Panel

On 1966-72 Chevy II/Nova models the upper dash panel is especially notorious for rusting out where the windshield meets the dash. Replace your rusty original steel dash with this reproduction steel dash panel. Note: Shipped double oversize.

1642	1966-67	EDP coated	319.99	ea
1642W	1966-67	Weld-Thru™	349.99	ea
52679	1969-72	with AC	269.99	ea
52680	1969-72	without AC	269.99	ea

AUTHORIZED

1968-72 Upper Dash Panel

One of the most commonly rusted areas of your Nova is the upper dash panel. This "weld-in" upper dash panel unit replaces the dash pad mounting areas, VIN plate, speaker, and defrost vent cutout areas, but will require fabrication at the windshield/cowl panel area. Some modifications are required. Finished in

EDP black coating. te: Shipped double oversize C6840 1968-72



Without Seat Mounting Brackets 14627




The complete floor pan assembly is designed to factory specifications making sure that the structural integrity of each area is not compromised.

1962-67 Floor Pan — Weld-Thru™ 🔥

This floor pan for 1962-67 Chevy II/Nova models is manufactured to factory specifications. This steel reproduction with the new Weld-Thru™ Primer features the transmission tunnel, drain holes, seat belt anchors and factory style ribbing for added strength.

Note: Shippe	ed truck freight.	Testibus	þ
	Column Shift Automati	C	
	Mounting Brackets		
14614W	1962-67	359.99	c
	Floor Shift Automatic		
Without Se	at Mounting Brackets		
14392W	1962-67	411.99	c
	Floor Shift Manual		
With Rocke	r Panels without Seat Brackets		
14715W	1962-67	889.99	c



The complete floor pan assembly is designed to factory specifications making sure that the structural integrity of each area is not compromised.


1962-74 Floor Pans


This unique stamped steel reproduction is designed to offer the restoration enthusiast the finest in OEM quality and appearance. Our quality, one piece floor nans offer less bassle for installation and no natched seams for a cleaner restoration with greater strength and durability than a patchwork of sheet metal pieces. Save hours of costly body shop labor when welding in one panel instead of many. EDP coated.

	d truck freight.	Textimate
- (Column Shift Automatic	C
	Iounting Brackets	
	962-67	329.99 e
	Floor Shift Automatic	
	nt Mounting Brackets	
14392 1	962-67	359.99 e
	r Panels and Bucket Seat Bro	
14714 1	962-67	849.99 c
	Floor Shift Manual	
	r Panels without Seat Bracke	
14715 1	962-67	889.99 c

1968-74

weld characteristics. Note: Shipped truck freight C9008W 1966-67 Weld-Thru™





1966-67 Floor and Trunk Pan

Don't mess around with patching your floor and trunk section one at a time. If the floor pan in your Chevy II/ Nova is damaged or cancerous in multiple places, simply replace the whole pan at once. Superb, all-new reproduction of the entire original floor pan assembly and trunk pan offers less hassle of installation and no patched seams for a cleaner restoration and greater strength and durability than a patchwork of sheet metal pieces can offer. Plus, save hours of costly body shop labor when welding in one panel instead of many. This unique reproduction is designed to offer the restoration enthusiast the finest in OE quality. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior

ō

•



FIOOR

Includes the toe panel, the center transmission tun and under the rear seat panel.



1962-67 Full Length Floor Pan

Replace your existing floor pans with Classic Industries high-quality reproductions. Each floor pan is manufactured to factory specifications. You can now choose between the standard style replacement and the floor pan that includes the under rear seat metal and the toe board section. These are truly the finest quality floor pans available. You'll find the fit and quality extremely close to the originals. The seat track mounting area is not included and must be removed from existing panel d rainctallad on to p

Note: Shipped truck freight.			THEORY	
N12077	1962-67	LH	198.99 ea	
N12078	1962-67	RH	198.99 ea	

Includes the toe panel, stops at the front of the rear sear



1962-67 Floor Pan Halves with Toe Roard

Reproduction floor pan halves with toe board for 1962-67 Nova models. Manufactured to factory specifications featuring original style stiffening ribs, pre-punched drain holes, and EDP coated for rust prevention. These panels repair the area from the rear

Note: Ship	ped truck frei	ght.	Track Details
153723	1962-67	LH	109.99 ea
153724	1962-67	RH	109.99 ca

ludes the center transmission tunnel stops at the front of the rear seat.

1962-67 Front Floor Panel

Reproduction front floor panels for 1962-67 Nova models. Manufactured to factory specifications featuring correct contours and come EDP coated for rust prevention.

Note: Shipped double oversize. 153727 1962-67 LH... 50 00 00 153728 1962-67 RH 59.99 ca Restorer's Choice includes the toe panel,

Standard replacements do not include the toe panel. Does not include the center transmission tunnel section stops at the front of the rear seat.



1968-76 Full Length Floor Pan Factory style replacement floor pan sides for 1968-76

models. Available in your choice of our Restorer's Choice™, manufactured in OE gauge steel, featuring all original contours and details or our more economical standard replacement for the car builder on a budget. Each floor pan comes finished in black EDP coating for rust prevention and features pre-punched drain holes. Note: Shipped double oversize

· · · · · · · · · · · · · · · · · · ·			0.07
Restore	r's Choi	ce™ – with Toe	Board
21" x 64"			
E167211B	1968-76	LH	79.99 ca
E167212B	1968-76	RH	79.99 ca
Floor Pan	Set		
N6572B	1968-76	LH and RH	125.99 pr
Sta	ndard -v	rithout Toe Bo	ard
55-3/4" x 1	9-3/4"		
E167211	1968-76	LH	56.99 ea
E167212	1968-76	RH	56.99 ea
Floor Pan	Set		
N6572	1968-76	I.H and RH	98 99 pr

Front panels includes the toe panel, includes the center transmission tunnel section, rear panels stop at the front of the rear seat









1962-67 Floor Repair Panels

Reproduction floor repair panels for 1962-67 Nova models. Manufactured to factory specifications featuring correct contours and come EDP coated for rust prevention. Available as quarter repair sections, front section with toe board and rear section

Front Section 153719 1962-67 LH 29-1/2" x 43-1/2" 82.99 ea 153720 1962-67 RH 29-1/2" x 43-1/2" 82.99 ea Rear Section

153721 1962-67 LH 28-1/2" x 25".... 36.99 ea 153722 1962-67 RH 28-1/2" x 25".... 36.99 ea

1962-67 front includes the toe panel, 1968-76 front do not include the toe panel, does not include the center transmission tunnel section, rear panels stop at the front of the rear seat.









1962-76 Partial Floor Pan Each partial floor pan is manufactured to exact specifications. You may order the front section or the rear section for either side as desired. Each partial panel includes the correct drain hole area as a solid section built right into the panel. You may cut this section out before installing the panel to put the original drain plug back in if desired. The seat track mounting area must

be removed from the existing panel and reinstalled on to the reproduction panel.

ote: Snippi	ea oversize.	* Snip	pea aoubie oversi;	e.
ront Pane	els		- 4	OS1 - OS2
			27" x 30-1/2"	
106212*		RH	27" x 30-1/2"	
107211		LH		
107212	1968-76	RH	20" x 27-3/4"	79.99 ea

Rear Pane	ls			
			27" x 30-1/2"	
			27" x 30-1/2"	
E127211	1968-76	LH	20" x 28"	58.99 ea
E127212	1968-76	RH	20" x 28"	58.99 ea











COMPONENTS HODY

Floor Pan Components







Reproduction toe board panels for 1962-67 Nova models. Manufactured to factory specifications featuring correct contours and come EDP coated for rust prevention. Available as a Luicee panel or in halves

	ped double o	oversize.	- OS2
153713*	1962-67 1962-67	1 piece	159.99 ea 79.99 ea
153714	1962-67	RH	79.99 ea 79.99 ea





C1268

1968-72 Floor Pan to Firewall Extension Replacement panels which extend from the leading edge

of the front floor pan to the firewall. This panel completes the floor pan section. Manufactured in the correct gauge matches the original configuration

C126L	1968-72	LH		
C126R	1968-72	RH	49.99	ca



153716

4530





1962-74 Under Rear Seat Floor Panel 🗥

Reproduction under rear seat floor panels for 1962-74 Nova models. Manufactured to factory specifications featuring correct contours and come EDP coated for rust prevention. Available as a 1 piece panel or in halves.

153716*	1962-67	1 piece	69.99 ca
153717	1962-67	LĤ	49.99 ca
153718	1962-67	RH	49.99 ca
16484*	1968-74	1 piece	
153356	1968-74	LĤ	58.99 ca
153357	1968-74	RH	58.99 ca



MEAR

R10010W

1962-67 Rear Seat Floor to Trunk Pan 🔥

Reproduction rear seat floor pan for 1962-67 models. Features the braces that install under the floor pan Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics.

Note: Shipped double oversize. D 10010 1962-67 EDP coated.... 1962-67 Weld-Thru™.. 269.99 ea 369 99 ca





1962-76 Floor Pan Plug

Reproduction metal and rubber floor pan hole plugs used on various 1962-76 Chevy II/Nova models. Located on the front and rear floor pans and the trunk floor pan. Sold individually. Use as needed. Metal Plugs - Fits 3-1/4" x 2-1/4" Oval Hole 1962-76 4-5/8" x 3-5/8" 2.99 ea

Rubber Plugs - Fits 1-3/8" Round Hole 1962-76 2" diameter... 2 29 00



1962-67 Floor Brace These stamped reproduction floor braces are designed

to add support to the floor assembly of the vehicle. Use on the center section of the floor 1962-67 LH center section... 53.99 ea N1004 1962-67 RH center section .. 53.99 ea



1966-67 Firewall to Floor Braces 🔥

Reproductions of the firewall to floor braces for 1966-67 Chevy II/Nova models. Replace your rusted out or damaged originals with these high-quality reproduction braces. Installs between the firewall and the front frame rails. Weld-Thru™ Primer requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics. 1966-67 Weld-Thru™ 249 99 pr



1968-74 Front Floor Pan Rrace

Reproduction of the front seat floor brace designed for use with 1968-74 Chevy II/Nova models. Manufactured in quality stamped steel to the original factory configuration. Each brace is designed to match the original for an authentic fitment. Includes black EDP coating for rust and corrosion prevention.

14630 1968-74 front 79.99 ea

Note: Shipped oversize.



1966-67 Front Frame Rail Support

Stamped steel reproduction of the front frame rail support for 1966-67 Chevy II/Nova models. This support bolts onto the front frame rails above the

sway bar. 16105 1966-67 94 99 са



1966-67 Rear Frame Rail Floor Braces

Correct reproduction front frame rail braces for 1966-67 Chevy II/Nova models. These stamped steel braces include two pieces for each side. One piece mounts between the frame rail and the inner rocker panel. The other piece provides the mounting point for the leaf spring front eye bracket. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics.

14619 1966-67 LH EDP coated 39.99 set 1966-67 RH EDP coated ... 39.99 set LH Weld-ThruTM .. 44.99 set RH Weld-ThruTM .. 44.99 set 14618 14619W 1966-67 14618W 1966-67



MEAR

1962-67 Bucket Seat Frame Supports Reproduction of the bucket seat frame supports for

1962-67 Chevy II/Nova models. When replacing your seats, you might also need to replace the supports. Each support is manufactured to duplicate the original in fit and appearance. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics. 4 Piece Sets

14647 1962-67 EDP coated 109.99 set Weld-Thru™ 129.99 set 14647W 1962-67



Rocker Panels



1968 Bucket Seat Brackets

Reproduction of the original bucket seat brackets designed for use with 1968 Chevy II/Nova models. Manufactured in quality stamped steel to the original factory design. Includes black EDP coating for rust and corrosion prevention. Features correct mounting locations. Replaces the original bent or damaged original exactly. Replace your rusted or missing bucket seat brackets with this quality 8 piece set. One set required for two bucket seats.

14633	1968	8 piece	89.99	S
14000	1700	o piece	07.77	.,,



1969-71 Bucket Seat Supports

Reproduction bucket seat support set for 1969-71 Nova models. Manufactured to factory specifications and EDP coated for rust prevention. This set includes

tunnel, as	well as the outer seat mounting points.
152768	1969-71 94 99 si





1968-74 Under Rear Seat Floor Brace

Reproduction of the under seat floor brace for 1968-74 models. These braces are located on rear section under

		race is designed to fit	exactly as
the facto	ry intended.		
14628	1968-74	LH	58.99 ea
14629	1968-74	RH	58.99 ca



1968-74 Rear Seat Floor Brace

Reproduction of the rear seat floor brace for 1968-74 models. These braces are located under the rear floor. Each brace is designed to fit exactly as the factory intended LH RH



1968-74 Rear Seat Floor Hook

Reproduction rear seat floor hook for 1968-74 Nova models. This hook is welded to the rear seat floor and creates the mounting point for the front side of the bottom seat. 2 required per vehicle. ca

152/54	1968-74		7.9
		-	
- 100			8
		68012	or .

1962-67 Outer Rocker Panel Skin 🔥

Replacement outer rocker panel skin designed to replace the rusted or damaged original. Available for 2 or 4 door models. These are outer sections only.

Note: *49-1/.	2" long. **S	hipped i	oversize.	€ 081
680120L*	1962-67	LH	2 door	39.99 ca
680120R*	1962-67	RH		39.99 ea
680140L**	1962-67	LH		29.99 ca
680140R**	1962-67	RH	4 door	29.99 ea

AUTHORIZED

1966-67 Full Outer Rocker Panel

These factory style full outer rocker panels will replace rusted or damaged original panels on your 1966-67 Chevy II/Nova.

Note: Shippe	d double ove.	rsize.		2.082
4845357 4845356	1966-67 1966-67	LH RH	2 door 2 door	

WELH.

N14662W

1966-67 Complete Rocker Panel

Replace the rusted out rocker panels with these reproduction rocker panels for 1966-67 Chevy II/Nova models. These include the inner and outer portions. Measures 77" in length. Available with traditional EDP coating or in a Weld-ThruTM Primer.

Note. Snippe	a aouote oi	ersig		ليتناو
N14661	1966-67	LH	EDP coated	214.99 ca
N14662	1966-67	RH	EDP coated	214.99 ca
N14661W	1966-67	LH	Weld-Thru™.	309.99 ca
N14662W	1966-67	RH	Weld-Thru™.	309.99 ca

16122

1968-72 Inner Rocker Panel Reproduction inner rocker panels for 1968-72 Nova

models. Mounts behind the outer rocker to form the complete rocker panel. Note: Shipped double oversize 16122 16123 1968-72 1968-72 LH 76 99 ca 76.99 ca



1968-72 Inner Rocker Panel

Stamped steel reproduction inner rocker panels for 1968-72 Nova models. Installs under the doors behind the outer rocker panel and between the wheel wells. Includes the lower kick panel area as shown.

72 RH 104.99
S78002L

1968-79 Nuter Rocker Panel

Reproduction of the outer rocker panels fit directly below the door area and between the wheel wells.

S78002R S78004L	1968-79 1968-79	RH LH	4 door	39.99 ea 39.99 ea 39.99 ea
S78004R	1968-79	RH	4 door	39.99 ea







1968-72 Rear Rocker Panel Flans

Replace the often missing or disintegrating rear rocker panel flaps on your 1968-72 Nova with these highquality reproductions. These flaps prevent road splash and debris from entering the vehicle and blocking the rocker panel drain area. Each flap mounts on the rear side of the inner rocker panel. KW538 1968-72 3.99 pr



1968-79 Rocker Reinforcement Panel

Replace the commonly rusted rocker reinforcement panel on your 1968-79 Nova with this quality reproduction. This panel mounts between the inner rocker panel and the front wheel well near the kick panel area. For hardtop models or convertibles. K7926 1968-79 LH...... 31.99 ea K7927 1968-79 RH 31 99 ca











Roof Panels









R24004W

1962-67 Steel Floor Shifter Hump 🔔

Replacement steel shifter hump for various 1962-67 Chevy II/Nova models with floor mounted transmission shifters. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics.

N1409 N1409W	1962-67 1962-67	EDP coated Weld-Thru TM	
4-Speed wit	thout Conse	ole	
B24004	1964-67	EDP coated	
B24004W	1964-67	Weld-Thru™	42.99 ca



1968-72 Steel Shift Humo

Replacement steel shift hump for 1968-72 Chevy II/ Nova models N1407 1968-72 with console 52.99 ea



1968-74 Shift Hole Reinforcement Ring

Shift hole reinforcement ring for Nova models. Stamped steel shifter ring reinforces shifter hole in floor for mounting automatic shifter and 4-speed shift boot. This piece has often been cut-up or has rusted. Retainer ring welds to bottom side of the floor pan. A7100109 1968-74 ROOF PANELS



1966-72 Chevy II/Nova Roof Panel

1966-67 Coupe Roof Panel

Replace the dented, rusted or otherwise damaged original roof panel on your 1966-67 Chevy II/Nova hardtop with this stamped reproduction. Each panel is manufactured to exact factory specifications

tant: Roof drip rail and window molding channel not included. Note: Shipped truck freight.

16103 1966-67

1968-72 Roof Panel

Reproduction roof panel for 1968-72 Nova models. Manufactured to factory specifications from new steel tooling, featuring original style contours, correct gauge sheet metal and EDP coated for rust prevention.

Note: Shipped truck freight. 7722875 1968-72

16104W





1966-67 Coupe Inner Roof Panel Braces

If you're replacing your entire roof of your 1966-67 Nova coupe, you'll need this set of reinforcements to complete the job correctly. Stamped from correct gauge steel and designed to fit and install as original. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics.

Note: Shipped double oversize 16104 1966-67 EDP coated 16104W





1968-74 Roof Drip Rail Connectors 🔥

OER® drip rail connectors for 1968-74 Chevy II/Nova models without the stainless steel roof drip molding option. The connectors seam the union between the A-pillar drip rail and roof drip rail. Paint to match the body color. Manufactured from stamped steel with black zinc coating to help prevent corrosion. 1968-74 LH and RH



319.99 ea

339.99 ca

1966-67 Front Pillar Drip Rail Support

These supports are essential when installing a roof panel because they reinforce the front pillar section of the roof. Installs on the front pillar section of the roof panel and extends downward vertically between the roof panel and fender. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior

weld characteristics 16107 1966-67 LH EDP coated.. 26.99 ea 16108 EDP coated... 26.99 ea Weld-ThruTM 32.99 ea 1966-67 RH 16107W 1966-67 LH Weld-Thru™ 32.99 ca 16108W 1966-67 RH

1966-67 Rear Drip Rail Supports

Exact reproduction pillar drip rail supports. Installs on the rear pillar section of the roof panel and extends down vertically between the roof panel and trunk. These components are crucial when installing a roof panel because they provide critical support to the rear pillar section. EDP coating requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics. 1966-67 EDP coated

WARNING: Cancer and Reproductive Harm-www.P65Warnings.ca.gov

BLUBNOUNDE

Convertible Tops

If you're looking for an authentic reproduction of the original convertible top, then look no further! Our premium quality OER® Authorized tops, made in the USA, are the finest reproduction tops on the market today! Restore the original appearance of your early Chevy II/Nova, maintain originality, and protect your investment with a superb OER® Authorized convertible top from Classic Industries®. Available in a variety of color and material choices to fit your specific needs. Professional installation is recommended for best results.







	- Pinpoin	t Vinyl —	
tan	buckskin	white	black
tan	 buckskin Stayfast 		black

1962-63 Convertible Top Kits

OER® Authorized convertible tops and rear windows. Manufactured to factory specifications in your choice of Pinpoint vinyl or Stayfast canvas. Convertible top kits include the convertible top and a plastic rear window.

Pinpoint Vin	yl Convertib	le Top Kit	
N6263105	1962-63	tan	329.99 kit
N6263115	1962-63	buckskin	
N6263121	1962-63	white	
N6263133	1962-63	black	289.99 kit
Stayfast Can			
N6263214	1962-63	black	
N6263203	1962-63	beige	549.99 kit

~>> PRESTORERS ... CD1032233

Pinpoint Vinyl black

1962-63 Convertible Top and Rear Window

OER® Authorized convertible tops and rear windows. Manufactured to factory specifications in your choice of Pinpoint vinvl or Stavfast canvas. Convertible top kits include the convertible top and a plastic rear window. Pinnoint Vinyl Convertible Ton - Ton Only

CD1032105	1962-63	tan	219.99 ea
CD1032115	1962-63	buckskin	
CD1032121	1962-63	white	199.99 ea
CD1032133	1962-63	black	199.99 ea
Stayfast Canve			
CD2032114	1962-63	black	
CD2032103	1962-63	beige	449.99 ea
Pinpoint Vinyl	Rear Winds	ow - Plastic	
CD1032205	1962-63	tan	149.99 ea
CD1032215	1962-63	buckskin	149.99 ea
CD1032221	1962-63	white	119.99 ea
CD1032233	1962-63	black	119.99 ea
Stayfast Canva	as Rear Win	dow - Plastic	
CD2032214	1962-63	black	129.99 ea
CD2032203	1962-63	beige	129.99 ea





1962-63 Convertible Top Boot Reproduction convertible top boots are manufactured

using the factory patterns for a great fit! Each top boot is produced using the correct grain vinyls. Includes a complete set of snaps for easy installation and special stiffeners which help maintain the original shape of the boot and give added support when in use. Each boot is manufactured with a thick foam backing which gives the boot padded support. Top boots are available in virtually every original factory interior color. 99 ea

ı	N51001	1962-63	black	184.99 ea
ı	N51002	1962-63	bright red	184.99 ea
ı	N51003	1962-63	light blue	184.99 ea
ı	N51006	1962-63	aqua	
ı	N51010	1962-63	white	
ı	N51018	1962-63	saddle	
ı	N51029	1962-63	red	184.99 ea
Į	N51065	1962-63	fawn	184.99 ea



1962-63 Convertible Well Liner

Excellent reproduction liner covering the section between the rear seat and trunk area. Used in section where convertible top folds down into well area. Produced from factory patterns using top grade heavyweight sateen backed vinyl material. Note: The sateen side faces away from the rear window

when installed.

N53001 1962-63 black 84.99 ea

AUTHORIZED



1962-63 Ton Boot Storage Bag

Protect your convertible top boot when it's off the vehicle by using a sensible storage technique. The storage bag will help protect your vehicles top boot while being stored in the trunk or your garage K51020 1962-63 black...... 34.99 ea



1962-63 Convertible Top Pads Replace your old top pads when replacing your

convertible top. Each pad is original in appearance and quality. Includes cloth padding with cloth covering. Used as reinforcement between convertible top and K54000 1962-63 34.99 pr





1962-63 Convertible Top Binding End Clip Reproduction of the top rear binding end clip for 1962-

63 convertible models. These stainless steel covers finishes both ends of the rear window outer top bow binding trim strip. 1962-63 2 required ...



1962-63 Conv. Top Molding Clips

A reproduction of the clip that attaches the molding around the rear well section on 1962-63 Chevy II/ Nova convertible models. Manufactured in carbon steel with black zinc-plating for durability and originality. 13942 1962-63 individual. 2.49 ea 22.99 kit K8070











Convertible Top Parts



1962-63 Convertible Ton Cables

Replace your stretched or broken convertible top hold down cables with these fine reproductions for 1962-63 Chevy II/Nova convertible models. Sold in pairs. 14724 1962-63 LH and RH 34.99 pr

AUTHORIZED



1962-63 Motor Pump Assembly

OE style replacement motor and pump assembly. Features original style and locations for electric and fluid connections HK233 1962-63





1962-63 Conv. Motor Grommet

Reproduction rubber mounting/insulation grommet for 1962-63 Chevy II/Nova convertible models. Rubber grommet installs on the pump assembly and secures it to the vehicle, while creating a damper for noise and vibration when the pump is in operation.

3698109 1962-63 1.89 ca



Hydraulic System Bleeder After replacing your top, pump and hoses, you want

to be sure the system operates properly by bleeding all the air out of the hydraulic system. This set comes with a filler plug adaptor fitting and instructions. Fits OEM and replacement pumps.

BK001



1962-63 Top Cylinder and Hose Kit 🔥

Reproduction convertible top cylinders and a set of hoses. Each item is also available separately. Buy the kit and save 395.99 kit R8234 1962-63

ATTHORIZED



1962-63 Conv. Top Cylinder

After years of use the original cylinders will wear out. Replace them with new, not rebuilt, replacements. Manufactured out of aluminum, the appearance is slightly different from the original, but it will function and operate exactly the same. Sold individually. Two
cylinders are required per vehicle.

HK235A 1962-63... 150 00 00



1962-63 Hydraulic Hose Set

Finding original hose for your early 1962-63 Chevy II convertible is next to impossible. If you own a convertible model with a power top, this set is what you need to put it back to original working condition. Each set comes complete with the hoses which run from the pump assembly to the lift cylinders along with all the fittings necessary for installation.

1962-63 HK234 99 99 set



1962-63 Convertible Top Hose Clip 🔥 Reproduction convertible top hose retainer clip for

1962-63 Chevy II/Nova convertible models. This reproduction retainer holds the top hose to the body. keeping the hoses out of the way and allowing the hoses to move with the top cylinders. 1062 63



1962-63 Convertible Top Latch

Reproduction high-quality convertible top latch assemblies for 1962-63 Chevy II/Nova convertible models. These exact reproductions will install as original and are manufactured in the USA

CM2148 1962-63 LH...... 141.99 ea CM2147 1962-63 RH..... 141 99 ca



1962-63 Conv. Top Latch Bushings

This is a reproduction of the bushings that are in the convertible top latches on 1962-63 Chevy II/Nova convertibles. These are the bushings that act as guides for the convertible top when they go into the latch. Includes retainers CM2147A 1962-63

..... 19.99 pr



1962-63 Convertible Latch Screws 🔥

Reproduction of the convertible latch screws for 1962-63 models used to attach the convertible top latches to the header panel. Note: 2 required per latch

CM2148A 1962-63 2 chrome...... 1.99 ea



1962-63 Convertible Latch Knuckle Hook Reproduction of the book used to hold down the

convertible top. Screws directly into the convertible latch knuckle assembly. Sold individually. Two hooks required per vehicle 5716613 1962-63 LH or RH

à

Vinvi Tops

1962-79 Nova/Chevv II Vinvl Top

Reproduction vinyl tops for 1962-79 Chevy II/Nova models are manufactured using the finest quality Levant grain vinyls for the ultimate in originality. The seams are sewn with Dacron bonded thread and then dielectrically heat sealed as original for a truly authentic appearance. There are two types of seams were used for certain years 1) Heat sealed seams which are stitched seams then folded over (stitching is not exposed) 2) French stitched seams which are double stitched on the top (stitched seams are exposed). French seams go down the center of the roof and the heat sealed seams go along the sides. Replacing your original vinyl top will make your Nova look showroom new once again. Classic Industries® recommends professional installation for best results

Important: Each vinyl top is precut for the rear window and pillar post areas. All models used moldings to finish the lower rear edge of the vinyl top and will need to be cut and trimmed to fit the specific vinyl top moldings for each year. Be sure to check the design and placement of the moldings before trimming and gluing the top to ensure accuracy Note: Tops are full tops, must be trimmed to fit for vehicles with half tops. Can be used on hatchback models



	800000		1969 Nava	
dark gre	en buckskir		1909 11014	
2 Door Hardt				
XB102401	1962-65	black	two heat sealed seams	139.99 ea
XB102410	1962-65	white	two heat sealed seams	
XB102413	1962-65	dark green		209.99 ea
XB102437	1962-65	buckskin	two heat sealed seams	209.99 ea
N60001	1966-67	black	two heat sealed seams	139.99 ea
N60010	1966-67	white	two heat sealed seams	139.99 ea
XB101913	1966-67	dark green	two heat sealed seams	209.99 ea
XB101937	1966-67	buckskin	two heat sealed seams	209.99 ea
2 Door and 4	Door Sedans	- Including Co	ncourse and Hatchbacks	
XB102001	1966-67	black	two heat sealed seams	159.99 ea
XB102010	1966-67	white	two heat sealed seams	
XB102013	1966-67	dark green	two heat sealed seams	194.99 ea
XB102037	1966-67	buckskin	two heat sealed seams	194.99 ca
N61001	1968-74	black	two heat sealed seams	129.99 ea
N61010	1968-74	white	two heat sealed seams	129.99 ea
N61013	1968-74	dark green	two heat sealed seams	207.99 ea
N61037	1968-74	buckskin	two heat sealed seams	
N62201	1975-79	black	French center seam	216.99 ea
N62210	1975-79	white	French center seam	269.99 ea
N62237	1975-79	buckskin	French center seam	289.99 ea





AUTHORIZED

1968-74 Vinvl Top Moldings

A high-quality reproduction of the vinyl top moldings used on 1968-74 Nova that featured a vinyl covered roof. This pair of moldings run from the bottom edge of the quarter window to the bottom edge of the rear window. They are used to finish off the edge of the vinyl top. 1968-74



Top Secret Vinyl Top Care Formula Kit

Our exclusive Secret Formula Top Secret Vinyl Top Protectant kit is a complete system for the care of vinyl tops. In the first step, the P99 HD Cleaner targets soil and dirt from, bird droppings, tree leaves, light stains from organic material and other debris to effortlessly remove them from the vinyl material. Next, the Secret Formula TNT Gel works as a sealer to repel water and detergents and help keep tops hydrated and supple as well as looking brand spanking new. Kit includes: Vinyl Top/Interior/Fabric Cleaner P99 HD 32 oz. bottle, vinyl top VRT dressing 32 oz. bottle, applicator pads, gentle wash brush with 18" handle, elite microfiber towel. blue monster microfiber towel. Top Secret kit cleaner, protectant, VRT dressing, pads, and towels can be purchased individually.

nyl Top I	Kit			
	cleaner, protectant & applicator	39.99	kit	
p Secret	Components			
	32 oz. P99 HD top cleaner			
	32 oz. TNT vinyl dressing			
89816	microfiber applicator pads	5.99	pr	
89835	soft wash brush w/18" handle	9.99	èa	

gold elite microfiber towel..... blue monster microfiber towel Finishing Touch Matte Finish Protectant

Finishing Touch is an all purpose dressing that restores the "new car look" to vinvl. rubber. leather, and plastic. It cleans, beautifies, and protects. It is preferred by many detailers for interiors for its "softer look and non-greasy look and feel. Pleasant banana fragrance. Spray or wipe on ready to use. Cleans, protects and beautifies in one easy step. Gently wipes away light traces

 T_{ℓ}

K89819 K89805



of dirt while you apply. Patented UV absorber penetrates and acts as a protective barrier against harmful rays that cause premature aging, cracking, fading and peeling. Engineered to work like a lotion to soak into new vinyl or dry vinyl to aid in prolonging and strengthening the surface. Perfect for dashboards, vinyl tops, door panels, consoles, tires, trim, bumpers, vinyl seats, moldings, and more. K89523 32 oz. spray bottle . 18 99 ca

1 gallon Heavy Duty 20 Spray Adhesive

3M Heavy Duty 20 Spray Adhesive forms a powerful, permanent bond to wood, laminate, metal, plastic and more. Simply spray the adhesive on one or both surfaces, wait 15 seconds to 30 minutes, and press surfaces together to form a tight bond.

Note: Ships via ground freight only and is shipped exclusively within the continental U.S. only, as no air ships on aerosol spray cans.




BODY COMPONENTS

31 99 ca

3.99 ea

4 99 ca













Door Sheet Metal







1962-72 Door Shell

When replacing the outer sheet metal panel alone on your 1962-72 Chevy II/Nova isn't enough, these reproduction door shells are just what you need. Window regulator, handles, hardware, latches, etc... are not included and must be purchased separately or transferred over from the original door. Note: Shipped truck freight.

Hardtop			Inclines
14988	1962-65	LH	369.99 c
14989	1962-65	RH	369.99 e
B1621	1966	LH	389.99 c
B1622	1966	RH	389.99 c
B1620	1967	LH	341.99 c
B1619	1967	RH	341.99 c
2 Door Se	dan		
14990	1962-65	LH	389.99 c
14991	1962-65	RH	389.99 e
7788955	1968-72	LH	369.99 c
7788954	1968-72	RH	369 99 c

AUTHORIZED



1962-65 Outer Door Skin

These replacement steel door panels will enable you to replace your damaged or rusted out door skin with a long-lasting durable replacement. Each panel has been reproduced to exact specifications and will fit the door frame perfectly.

Note: Ship	ped double o	wersiz	e.	OS2
4845015	1962-65	LH	2 door hdtp	139.99 ea
4945014	1062 65	DII	2 4	120.00

AUTHORIZED

775220R



1966-72 Outer Door Skin

These replacement steel door panels will enable you to replace your damaged or rusted out door skin with a long-lasting durable replacement. Each panel has been reproduced to exact specifications and will fit the door frame perfectly.

7695740	1966-67	LH	2 door hdtp	134.99 c
4545232	1966-67	RH	2 door hdtp	134.99 c
7788951	1968-72	LH	2 door	128.99 c
7788952	1968-72	RH	2 door	128.99 c

1968-79 Lower Outer Door Skin Patch Panel

Replace the rusted out lower section of the outer door skin with this 7" high patch panel. Eliminates the need to replace the entire panel. For Nova only.

775220L 775220R	1968-79 1968-79	RH	
	_		



1966-74 Fiberglass Door

These fiberglass door shells will enable you to replace your damaged or rusted door with long-lasting durable fiberglass replacements. OEM style hinge and latch mounting pads are reinforced and accept OEM hardware for easy installation. The full inner panel must be trimmed out to gain access inside the door. Available for 2 door 1966-74 models. For use with Lexan window and hardware only (not included).

Note: \$1966-67 shipped oversize. \$\$1968-74 panels require

		1000000		
F13010*	1966-67	LH	399.99 ea	
F13011*	1966-67	RH	399.99 ca	
F14010**	1968-74	LH	399.99 ca	
F14011**	1968-74	RH	399.99 ea	

7580738 (sold is



1962-79 Upper Door Hinge

Reproduction door hinge designed and manufactured for the Chevy II/Nova. Each hinge will fit exactly as original. Each hinge includes four bolt holes for

7580738	1962-66	LH or RH	49.99 ea
9817407	1968-79	LH	49.99 ea
9817406	1968-79	RH	49.99 ea





1962-79 Lower Door Hinge

High-quality reproduction door hinges for 1962-79 Chevy II/Nova. Each hinge is ready to bolt on. 4841357 1962-67 IН . 59.99 ea 59.99 ea 4941356 1962-67 RH 3063212 1968-79 IH 57 99 ca 1968-79 57.99 ca 3063211 RH



1968-79 Lower Door Hinge Arm

Replace this often worn out or broken arm on the lower door hinge. The detent roller rides on cutout notches on the steel arm. The door hinge detent spring also attaches into this arm. 1 required per hinge. Attachment

rivet sold separately. HC241 1968-79 door hinge arm..... 8.99 ea HC241A 1968-79 rivet

COMPONENTS

BODY

◮

Door Hinges and Latches





1962-72 Door Hinge Bolt Set

Reproduc	tion bolt se	ets are for 2 upper or 2 le	ower door
hinges in	cluding bot	th door side and body s	side bolts.
748597 K195 K196	1962-67 1968-72 1968-72	upper – 14 piece lower – 16 piece	14.99 set 14.99 set 16.99 set





1968-79 Lower Door Hinge Roller Detent

These detent roller repair sets are an economical and simple repair alternative to expensive replacements. Instructions included.

K554 1968-79 LH and RH 19.99 set





1968-79 Lower Door Hinge Rebuild Set

Complete lower door hinge rebuild set includes: 4 hinge pins, 4 retaining clips, 8 bushings, 2 tension springs, and 2 roller detent studs with hardware. Everything you need to restore both lower door hinges on your 1968-79 Nova

1968-79 LH and RH 39 99 set



1968-79 Door Hinge Repair Set

Repair broken door hinges with this unique set that contains 4 proper hardened shouldered pivot pins and 8 bronze bushings. Will repair all 4 upper and lower hinges K401 1968-79



1962-79 Door Hinge Bushing

Correct replacement door hinge pin bushings for various 1962-79 Chevy II/Nova models 9721917 1962-79 smooth o.d. 99 ea 1968-79 splined o.d. 80 ea



1967-79 Door Hinge Replacement Pin Replacement door hinge pin to repair broken hinges

without the high cost of replacing the entire hinge. Length: 2-13/16", Diameter: 5/16" 398 1968-79 front upper or lower 2.99 ea

Length:	4-1/16", Di	ameter: 11/32"		
A1029	1967	front upper	1.79	c
A1029	1975-79	4 door	1.79	c



Door Alignment Wedges

The door alignment wedges are necessary to help keep the doors from sagging due to fatigue in the door frame structure which could cause damage to the weatherstrips and body. The door mounted wedge will contact with the door frame wedge to maintain proper alignment. 40 99 set

CM5195 1963 1966-67 hardtop K1901 37.99 set





1969-77 Door Latch Rod Clip 2 piece door latch rod retaining clip set. These clips secure the door release rod to the inner door skin. 7746988 1969-77 2 piece...



1968-72 Door Latch Rod Center Clip

This clip mounts to the inner door panel and keeps the door latch rod assembly from bending when operated. KW704 1968-72...



1963-70 Chevy II/Nova Door Latch Assembly

OER® reproduction of the door latch assembly for 1963-70 Chevy II/Nova models. Help the door to

way the rac	tory intended:	
1963-65	LH	
		69.99 ea
		69.99 ea
1969-70	RH	69 99 ca
		1963-65 RH



Correct replacement oval Phillips head door latch screws used on various GM vehicles from 1962-70. 1/4"-20 x 5/8". Cadmium-plated.

B12527 1962-70 6 piece...



1968-76 Door Latch Mechanism Push Rutton Return Spring

OER® reproduction door handle push button lock spring When the spring is broken, it will become difficult to lock, unlock, and open the door of your vehicle. 9720761 1968-76 I.H 4.99 ea 9720760 1968-76 RH 4 99 ca













Door Lock Hardware



1963-67 Door Lock Striker Plates 🔥

Reproduction door striker plates for 1963-67 Chevy II/ Nova models. Worn striker plates can interfere with the correct operation of our door. Fits front and rear doors for 2 and 4 door models.

152602 1963-67.



1968-79 Door Lock Striker

The door lock striker is screwed into the door jamb area for either LH or RH side. Available for 1968-79 models. 2 required.

8770193 1968-79 12 99 69



1968-79 Door Lock Strikers

These are a custom stainless steel versions of the door lock strikers that mount in the door jamb area of the quarter panel

Plain Washe			
MD1024	1968-79	machined	47.99 pr
MD1030	1968-79	polished	54.99 pr
Accented Wo			
MD1024A	1968-79	machined	54.99 pr
MD1030A	1968-79	polished	58.99 pr





1968-79 Billet Door Strikers

These custom billet aluminum and stainless steel door lock strikers mount in the door jamb area of the quarter panel and keep the door securely closed. Each striker plate is machined from 6061-T6 billet aluminum and features a striker turned from 304 stainless steel for durability. 7/16"-14 thread pitch, 1" thread length, 1-1/4" striker length. Sold in pairs. Available in natural

ı	or black fin			
	CB44101	1968-79	natural	
и	CD 44102	1069.70	Internal	92.00







1968-79 Door Striker Rolt Washer 🔥

Reproduction door striker bolt washer manufactured in die-stamped steel and finished in clear zinc coating. Used to correctly position the door striker bolt for proper alignment with the door latch assembly. Use as required. Note: *Part #115003667 threads on. The other 3 slide on.

4469196	1.25mm thick	1.99 ea
4469197	2.00mm thick	1.99 ea
11500367*		4.99 ca
4469195	4 00mm thick	1 99 ca



1968-79 Door Striker Plastic Washers Reproduction of the door striker washers for 1968-79

models. These are the correct plastic washers installed behind the striker to allow you to adjust the striker without marring the paint. Sold in pairs.

1968-79 ... 3.99 pr



1969-79 Door Lock Pawl

Reproduction lever that mounts at the end of the door lock cylinder allowing the door latch assembly to be

CL1127	1962-67	LH	6.99 ea
CL1128	1962-67	RH	6.99 ea
CL1113	1968-79	LH	6.99 ea
CL1112	1968-79	RH	6.99 ea



1968 Inner Door Lock Rod

Reproduction of the inner door lock rod for 1968 Chevy II/Nova models. This rod attaches to the door latch and is used to unlock the door from the inside. This is the upper vertical rod threaded at one end where the door lock knob screws onto. For driver or passenger door. Sold individually, 2 required,

1968-77 Door Inside Locking Rod Clip

7733785

This clip is used to hold the door lock knob rod assembly to the lower rod assembly which pivots up and down when the door lock knob is raised or lowered. Clip used to hold the inner locking rod to the inner door frame panel. Eliminate rattling which occurs from damaged or missing clips 7762203 1968-77 4 required 2.79 ca

AUTHORIZED



1978-79 Door Lock Rod Retaining Clip

Reproduction of the clip that retains the two inner door lock rods. This nylon clip joins the horizontal rod from the door latch with the vertical rod that the door lock knob screws on to. Sold individually. One required per door. Fits into a 17/64" hole and secures a 5/32" rod. K4013 1978-79 ..



1968-79 Door Lock Bellcrank Retainer

Door lock bellcrank retainers attach the door lock rod bellcrank to the inner door on 1968-79 Nova models This injection molded retainer is designed to replace the original exactly, 2 required per door,

8733856 1968-79... 4.99 ea



1962-79 Door Lock Cylinder Retainer

If you're replacing your door lock cylinder it may be necessary to replace the retainer. This retainer holds the lock cylinder in the correct position. 9728247 1962-79 2 99 69




1962-79 Door Lock Cylinder Gasket

Correct replacement door lock gasket for 1962-79 Chevy II/Nova models. This gasket prevents your lock cylinder from making contact with the paint. We recommend replacing your original gaskets when replacing your locks. Sold individually. Use as required.



1962-79 Door Bumpers



4840894 1962-66 K130 1968-79 4 piece 4.99 set 1968-79 20376243 upper - short 1 99 ca

Т

90

Door Handles & Hardwa











1962-79 Exterior Door Handle Set 🔥

OER® Authorized exterior door handles for 1962-79 Chevy II/Nova models. Manufactured to factory specifications. Triple chrome-plated. Includes: 2 door handles, 2 push buttons with o-rings, handle to body gaskets, and hardware.

2 or 4 Doc		
R5050		61.99 set
R5051	1966-67	59.99 set
R5001B	1968-79	49.99 set



1962-79 Door Handle Set

CM3063

SP2

CB70001

Replace your original pitted or worn out outer door handles with these sets. Includes the necessary components to replace your outer door handles, door handle gaskets and o-rings. Each handle is manufactured to factory specifications and includes highly polished triple chrome-plating for a dazzling appearance.

CM3082		4 door	88.99	set
Rear Door	s Only			
CM3014	1962-65	4 door	89.99	set
CM3063	1966-67	4 door		
CM3083	1968-79	4 door	88.99	set





CB7000



1968-79 Billet Door Handles

Add some stylistic flair to your exterior door handles with a set of high tech billet door handles. CNCmachined from solid 6061-T6 billet aluminum, these handles are a direct replacement with no modification necessary for 1968-79 Chevy II/Nova. Installation

П	hardware and instructions included.					
П		1968-79	polished/polished			
П	CB70002	1968-79	polished/matte	467.99 pr		
ı	CB70003	1968-79	black/matte black	467.99 pr		



1962-67 Door Handle Gaskets Classic Industries® recommends replacing the door handle gaskets and lock gaskets when painting the

vehicle or replacing the outer door handles. Each door handle gasket and lock gasket is die-cut for a perfect fit. Includes door handle gaskets and lock gasket for both LH and RH sides. One set required for 2 door models. 2 sets required for 4 door models.

	1962-65 1966-67		
--	--------------------	--	--



1968-79 Door Handle Gaskets

OER® exterior door handle to door gasket for various 1968-79 Chevy II/Nova models. These EPDM rubber seals are manufactured to factory specifications. Some trimming may be required for use on some replacement door handles. Includes LH and RH side. peen

1968-79 4 99 set



1962-79 Outer Door Handle Push Button

This set includes the LH and RH door handle push button assemblies. These high polished chrome buttons include: the chrome thumb knob, attachment rods, tension springs, o-ring gaskets and button retainers for easier installation.

Note: On some models the push button retainer flange may require minor trimming in order to fit correctly on the inner retainer at the back of the outer door handle. This was due

R5252	1962-65		
R5253	1966-67	14.99	set
R5254	1968-79	14.99	set



1962-79 Door Handle O-Ring

This door handle o-ring is one of the most overlooked replacement parts on any vehicle. The o-ring inserts onto the outer door handle push button and eliminates rattling and wear between the handle and the push button. Manufactured to factory specifications and installs on 1962-79 Chevy II/Nova models. Sold individually. 4156548 1962-79 LH or RH 2.99 ca









Lock Assemblies

Make it easy on yourself by installing lock sets that already include the lock assembly and coded keys! Original replacement lock assemblies usually need to be coded to your original keys.

This process is eliminated when purchasing these sets. Choose from individual lock assemblies or complete sets which are guaranteed to make installation easier.



Set Includes:

✓ Door ✓ Ignition ✓ Glove Box ✓ Trunk

1962-78 Lock Cylinder Sets-

Lock set designed to replace your ignition, door, glove box and trunk lock assemblies. Each set is supplied with "coded" cylinders and 2 precut keys which will fit the new door, ignition, glove box and trunk lock cylinders. Early locks are available with original style keys, or later style square or oval keys.

TK295 TK296	1962-64 1965	original keyoriginal key	59.99 59.99	
TK288	1966-67	original key	46.99	set
TK336	1968	original key	59.99	
TK337	1969-78	original key	59.99	set



✓ Door ✓ Ignition ✓ Trunk

1962-67 Ignition, Door, & Trunk Lock Set Lock set designed to replace your ignition, door and

Lock set designed to replace your ignition, door and trunk lock assemblies. Each set is supplied with "coded" cylinders and 2 precut keys which will fit the new door, ignition and trunk lock cylinders.



✓ Door ✓ Ignition

1962-78 Ignition and Door Lock Set 🛕

Lock set designed to replace your ignition and door lock assemblies. Each set is supplied with "coded" cylinders and 2 precut keys which will fit the new door and ignition cylinders. Early locks are available with original style keys or later style sumar and oval keys.

TK142	1962-64	late model key	39.99 set
TK142A	1962-64	octagon key	
TK143A	1965	original key	44.99 set
TK104	1966-67	late model key	19.99 set
TK104A	1966-67	original key	27.99 set
TK105	1968	late model key	24.99 set
TK105A	1968	original key	36.99 set
TK106	1969-78	late model key	



Set Includes:

1962-79 Door and Trunk Lock Set 🔥

This lock set for your doors and trunk includes 2 door lock cylinders, trunk lock and 2 precut keys. Lock cylinder retainers which are used to hold the lock cylinder in place, and gaskets are also included. Early locks are available with original style keys, or later style square or oval keys.

Early locks are available with original style keys, or later style square or oval keys.					
TK135	1962-66	late model key	28.99 set		
TK135A	1962-68	original key			
TK135	1969-79	late model key			



Set Includes:

Door V Glove Box V

1962-79 Door. Glove Box. & Trunk Lock Set

This comprehensive set will allow you to replace all the major lock cylinders (door, glove box, and trunk) using just one precut key. Each set is a convenient and easy way of replacing your criginal locks without going through the trouble of taking your cylinders to going through the trouble of taking your cylinders to be separately. You may purchase the ignition lock with a precut key (will not match lock set keys) or purchase a non-codedignition lock. Early locks are available with

originai	style keys, or	later style square or	ovai ke	eys.
TK170	1962-65	late model key	44.99	set
TK170A		original key		
TK128	1966-67	late model key	49.99	
TK128A			41.99	
TK155A				
TK155	1968-79	late model key	44.99	set



✓ Glove Box ✓ Trun

1962-79 Glove Box and Trunk Lock Set

This lock set for your glove box door and trunk includes glove box lock cylinder and catch, trunk lock and 2 precut keys. Early locks are available with original style keys, or later style square or oval keys.

style keys, or later style square or ovar keys.					
	TK164A	1962-65	original key	37.99	set
	TK164	1962-65	late model key		
	TK121A	1966-67			
	TK121	1966-67	late model key	27.99	set
	TW 150				



1962-79 Ignition Lock

Replace your original ignition lock assembly with these "coded" lock cylinders which include keys. Each set includes a cylinder assembly and the key which is precut for fast installation. Early locks are available with

Original styl	c keys, or	ater style square or ovar keys.
TK157	1962-64	octagon key 12.99 ea
TK161	1962-64	original key 14.99 ea
TK158	1965	octagon key 9.99 ea
TK158A	1965	original key 12.99 ea
TK100	1966-67	late model key 11.99 ea
TK100A	1966-67	original key 16.99 ea
TK101	1968	late model key 12.99 ea
TK101A	1968	original key 16.99 ea
20071252	1969-78	late model key 12.99 ea
TK103	1979	late model key 11.99 ea





Replace your old outer door lock cylinders with these correct replacement type assemblies. Each pair of cylinders include 2 precut keys for easy and fast installation. Lock cylinder teatiners which are doed to hold the lock cylinder in place, are not included (available separately). Early locks are available with original style keys, or later style square or oval keys.

Genuine (iM .		
G6863	1962-79	original key	40.99 ea
Reproduct			
TK109	1962-79	late model key	14.99 pr
TK109B	1962-66	original key	22.99 pr
TK109A	1967-68	original key	18.99 pr



1962-79 Trunk Lock



Window Compone Door



1962-68 Briggs and Stratton Style Key

We offer these original Briggs and Stratton type GM keys which are not precut and may be purchased for the indicated years listed. Simply take these keys and your original keys to a locksmith or key shop, present your old key and have a new key cut-to-fit

your lo	ck cylinder.		
K161 K162	1962-66 1962-66	ignition A trunk B	
K109	1967	ignition A	4.99 ea
K110	1967	trunk B	
K111	1968	ignition C	4.99 ea



1964-79 Genuine GM Replacement Kev We offer these genuine GM keys which are not precut and

may be purchased for the indicated years listed. Simply take these keys and your original keys to a locksmith or key shop, present your old key and have a new key cut-to-fit your lock cylinder.

G10255	1964	ignition	late style	3.99 ea
G10255	1965	ignition	late style	3.99 ea
G10255	1966	ignition	late style	3.99 ea
G4611	1967	trunk	late style	3.99 ea
G4604	1968	ignition	late style	3.99 ea
G4605	1968	trunk	late style	3.99 ea
G4606	1969	ignition		3.99 ea
G4607	1969	trunk		3.99 ea
G4608	1970	ignition		3.99 ea
G4609	1970	trunk		3.99 ea
G4610	1971	ignition		3.99 ea
G4611	1971	trunk		3.99 ea
G4604	1972	ignition		3.99 ea
G4605	1972	trunk		3.99 ea
G4606	1973	ignition		3.99 ea
G4607	1973	trunk		3.99 ea
G4608	1974	ignition		3.99 ea
G4609	1974	trunk		3.99 ea
G4610	1975	ignition		3.99 ea
G4611	1975	trunk		3.99 ea
G4604	1976	ignition		3.99 ea
G4605	1976	trunk		3.99 ea
G4606	1977	ignition		3.99 ea
G4607	1977	trunk		3.99 ea
G4608	1978	ignition		3.99 ea
G4609	1978	trunk		3.99 ea
G4610	1979	ignition		3.99 ea
G4611	1979	trunk		3.99 ea





1969-79 GM Black Key Cover Ea the

		stic key cover is pr	
the exact cor	nfiguration	of the GM square or	oval keys
7839425	1969-79	square key cover	1.99 ea
20364745	1969-79	oval key cover	. 1.99 ca



1962-74 Door Window Regulators

ca

ca

ca

OER® door window regulators for 1962-74 Chevy II/ Nova models without power windows. Window regulators are manufactured to factory specifications for a correct fit and function. Zinc-plated for rust prevention.

All 2 Door	Models		
4842001	1962-65	LH	89.99
4842000	1962-65	RH	89.99
4542781	1966-67	LH	89.99
4542780	1966-67	RH	89.99
8767855	1969-72	LH	89.99
8767854	1969-72	RH	89.99
4 Door Mo	dels - Front	Doors	
8767857		LH	89.99
8767856	1969-72	RH	89.99
4 Door Mo	dels - Rear	Door	
8752681	1968-74	LH	89.99
8752680	1968-74	RH	89 99



1962-71 Auarter Window Regulators OER® quarter window regulators for 1962-71 Chevy II/

Nova models without power windows. Window regulators are manufactured to factory specifications for a correct fit and function. Zinc-plated for rust prevention. 2 Door Hardtop

4846611	1962-65	LH	
4846610	1962-65	RH	89.99 c
7580114	1966-67	LH	89.99 c
7580113	1966-67	RH	89.99 c
2 Door See	lan		
7746387	1968-71	LH	89.99 c
7746388	1968-71	RH	89.99 c



1962-65 Lower Window Track This is a reproduction of the lower frame portion

			the door glass in	
produced to or oval keys.		idow glass e for LH or	on this lower win loor.	dow tracl
r 1.99 ea 1.99 ea	C2386 C2385		2 door 2 door	



1962-72 Window Regulator Roller 🔥

OER® window regulator roller and rivet for various 1962-72 Chevy II/Nova models. Fits 1962-72 door regulators and 1962-65 1/4 window regulators. C1072 1962-72



1968-77 Window Guide Roller Nut Tool This OER® manufactured tool is designed to easily

remove the guide plate nut on door or quarter window glass. Fits most models 1968-77.

110020	1908-77	 19.99 6
New!		OEE



Reproduction glass roller washers, retaining

152742	1970-81	plastic washer	4.99	ea
4491086	1970-81	steel washer	3.99	ea



1971-75 Window Regulator Guide Cam Spacer

Correct reproduction of the window regulator guide cam spacer for all 1971-75 Nova models. Sold individually. Use as required. 2 door... 9804150 1971-72 1 99 ea

9804150 1973-75 all 1.99 ca







9

COMPONENTS

1968-69 Lower Window Bumper 🔥

Correct replacement rubber stop bumper to keep the door glass from rolling down beyond the required travel point. 9810036 1968-69 4 99 ca





Reproduction front window guide for 1962-65 Chevy II/ Nova models N2222 1962-65 front 12.99 ca













Power Door Components



Set Includes:

- Two 4 button keyless remotes
- Two 15 lbs actuators for the door locks Wire harness
- Mounting hardware
- Installation instructions

1962-79 Power Door Lock Conversion Set

Looking to convert your manual door locks to a full power remote system? The combination power door lock and keyless entry system will convert your old manual locks to power, and activate them from up to 100 feet away!



Set includes:

- Two 4 button keyless remotes Two 15 lbs actuators for the door locks
- Trunk lock actuator
- Wire hamess
- Mounting hardware · Installation instructions

1962-79

1962-79 Power Door

Lock and Trunk Conversion Set Convert your manual door locks and trunk release to a full power remote system. The combination power door lock and trunk release provides everything necessary

to convert your manual door locks to power, plus pop your trunk. You can activate them from up to 100 feet with the same remote!



Set Includes

- Two 4 button keyless remotes
- · Two 15 lbs actuators for the door locks
- 45 lb trunk lock actuator 120 dB 6 tone siren alarm
- Wire harness
- Mounting hardware
- Installation instructions

1962-79 Power Door Lock and Trunk Conversion Set with Alarm

This power conversion system has everything! It includes all you need to add remote power door locks, remote power trunk release, and a high security alarm. This fully integrated system allows you to control door locks, trunk release and alarm, and activate them from up to 100 feet through a single 4 button remote. PDL5165 1962-79 with alarm 187.99 set



🌦 1962-72 Remote Door Ovener

Give your vehicle a sleek, custom look by eliminating the door handles and the door and trunk locks. Install the super trick, Made in USA remote door and trunk opener systems to enter your vehicle. These are available in your choice of either a 2 way or 3 way system. The way system features two door actuators, two door latches and one 2 way remote transmitter. The 3 way remote system features two door actuators, two door latches, one trunk actuator, one trunk latch and one 3 way remote transmitter. Both sets include all necessary connections and instructions.

2 way two doors 251 99 set 14030 3 way two doors and trunk 349 99 set



Shaved Door Handle Sets

Building a custom vehicle means you're looking for unique ways to separate your vehicle from the rest. These shaved door handle sets will give your vehicle

the ultimate smooth look to do just that! Important: Door handle block off plates not included.

SDH100 without emergency entry..... 199.99 set SDH101 191.99 set with emergency entry with alarm ... 191 99 set



Set Includes

- 2 High Powered 45 lb door solenoids Trunk solenoid
- Relay pack
- Wiring harness
- Door jammers
- Δlarm · Mounting hardware
- Installation instructions

Shaved Door & Trunk Lock Set with Alarm Building the ultimate custom vehicle means drawing

lots of attention, but sometimes you get the wrong kind, too. Smooth over those clumsy door handles and that stodgy trunk lock, plus protect your asset with one great set! This shaved door and trunk lock set offers the ultimate smooth look that will put all eyes on your vehicle, and it also includes a built-in alarm to protect your tricked out ride! Operated by a 3 channel keyless entry.

Important: Door handle and trunk block off plates

SDH103 with alarm 234 99 set

Power Window Comp



1968-74 Keyless Entry System

Do-it-yourself keyless entry set designed specifically to fit your Nova. Sets include: a Keyless Entry module with onboard relays, two 2 button remotes, two 15 lb door lock actuators with integrated overload protection, necessary wiring and mounting hardware. Full color. step-by-step installation instruction manual.

Note: Trunk release may require some minor trimming on some vehicles for installation.

KK012 1968-74 keyless door...... 219.99 set KK014 1968-74 keyless door & trunk 374.99 set





1968-77 Power Door Lock Switch

Reproduction replacement switches for 1968-77 Chevy II/Nova models with power door locks. Installs on the door panel.

8792174 1725099	1968-70 1972-77	



12V Exterior Door Handles

Elevate your vehicle's style with these electronic exterior door handles from Lokar! Each billet door handle utilizes a weatherproof 12 Volt pressure pad switch to supply power to an electronically actuated doorlatch (door popper). Its 2 piece design and available 0 degree or 10 degree mounting surface allows the insert to be removed, and door handle positioned for ultimate customization. The XL design provides 7/8" of clearance between the door and the switch, allowing for easier mounting and less modifications to the door. Made in the USA from 6061-T6 billet aluminum.

Important: This requires electronic door latch actuators, which are not included.

Note: *Installa	tion requires	hand pocket for cli	earance.
GSE2100A*	brushed		
GSE2100B*	polished		412.99 pr
GSE2101A*	brushed	10 degree	
GSE2101B*	polished	10 degree	412.99 pr
GSE2102A	brushed	XL	412.99 pr
GSE2102B	polished	XL	412.99 pr
GSE2103A	brushed	10 degree XL	
GSE2103B	polished	10 degree XL	412.99 pr



1975-79 Power Window Motor

These remanufactured power window motors have been re-engineered for a better than new performance. Each motor is remanufactured and then sealed with a higher than OE quality gasket to protect the motor from the elements. Each unit is supplied without the window lift gear. We recommend replacing the gear with our W300 gear sold separately.

Power	Window Mo	tors without		
W102	1975	LH	front	129.99 c
W103	1975	RH	front	121.99 c
W103	1975	LH	rear	121.99 c
W102	1975	RH	rear	129.99 c
W104	1976-79	LH		127.99 c
W105	1976-79	RH		115.99 e
Windo	w Lift Gear			
M300		I II or DII		44.00 a

1967-79 Power Window Relay Replace your inoperative power

window relay and bring your factor power windows back to working order. These are reproduction power window relays used by GM on most models equipped with optional power windows. 30 amp.

4849847 1967 power tailgate 21.99 ea 4849847 1975-79 pwr windows/locks... 21.99 ea

AUTHORIZED New

1962-72 Chevy II/Nova Power Window Relay

Reproduction of the multi-purpos relay designed for various 1962-72 Chevy II/Nova models. Replaces OE #1116920 or 7428426.

Note: This replacement part may differ cosmetically from the original, but will fit and function properly. HR614 1962-72... 14 99 ca

1964-72 Firewall Relay Cover

Reproduction rubber firewall relay cover for 1964-72 Chevy II/ Nova models. This cover was originally equipped on convertibles and models equipped with power accessories.





1968-74 Power Window Harness Roots OER® reproduction power window harness rubber boots for various 1968-74 Chevy II/Nova models.

These boots protect the power window wiring as it passes through the door jamb area. Manufactured from EPDM rubber. Sold in pairs. K4412 1968-74 I.H and RH





1975-78 Window Switch Assembly 🔥 Refresh your interior by replacing your peeling or

inoperative window switch with a reproduction switch. Choose from a one button switch that mounted on the passenger and rear door or 2 button switch which mounted on the driver door. Note: Reproduction style window switches may differ

button style	1975-78 swi	and function as original tch will work on the pas: trimming back the lengtl	senger side
1725094 1725092	1975-78 1975-78	1 button	





1962-72 Power Window Sets

Power window regulator sets for 1962-72 Chevy II/ Nova models. Sets include: motors, regulators, and hardware for installation. A universal switch and harness set is required to complete the installation.

Power Window Sets							
VWK101			ht/conv				
NR56300200	1966-67		ht/conv				
VWK105	1968-72		2 door				
WK106	1968-72		2 door	344.99	set		
Switch/Harnoss Sats							

One 2 Button Switch, One 1 Button Switch & Harness

One 4 Button Switch, Three 1 Button Switches & Harness SWK101 176.99 set





1962-63 Power Window Switch Base

Single button power window switch base, center notch style for 1962-63 Chevy II wagon (3 seat) on left rear quarter panel. Sold individually. 4723098 1962-63 1 button .. 39.99 ea



1975-79 Rear Window Switch Retainer Clin

Correct clip which holds the window switch to the door panel. 9722397 1975-79 use as needed













Outer Door Mirrors



1962 Row Tie Door Mirror

Reproduction Chevrolet Bow Tie mirror for 1962 models. Correct base with highly polished chrome. Mirrors include mounting gasket and screws.



1963-65 Row Tie Door Mirror

OER® correct reproduction outer door mirror featuring a ribbed neck and a Bow Tie logo cast into the rear of the mirror head. Each mirror includes the bracket. gasket and mounting screws.

985878 1963-65 LH or RH 47.99 ea



1966-72 Bow Tie Door Mirror

OER® correct reproduction outer door mirror with the correct Bow Tie logo engraved on the rear of the mirror. If you want an exact replacement, these are the mirrors you'll need! Each mirror includes the bracket, gasket and mounting screws. Fits LH or RH. Original Style Ribbed Base

CM3006 1966-72 with Bow Tie 39.99 ea Replacement Style Smooth Base CM3005 1966-72 with Bow Tie 29 99 ea



OER® reproduction outer door mirror without Bow Tie emblem. Features original style ribbed base. Each mirror includes: the bracket, gasket, and mounting screws Fit LH or RH sides



OER® replacement mirror for 1969-79 Nova models. These mirrors are original equipment for Camaro and Chevelle models, they can be used on your vehicle as a service replacement. Each mirror includes the bracket, gasket and mounting screws.

Original Style Ribbed Base - Show Quality 48.99 ca 1969-79 LH 1969-79 3914754 RH . 48.99 ca Original Style Ribbed Base - Replacement29.99 ea 1969-79

3914754X 1969-79 RH 29.99 ca Replacement Style Smooth Base CM3004 1969-79 29 99 ca 1060 70 RH 29 99 ca




1966-79 Clear Shot Door Mirrors 🔥

Clear Shot Mirrors by Morris Classic Concepts help eliminate the passenger side blind spot by allowing the mirror to be adjusted further in. They also have built-in tensioning screws that lock the mirror heads into place, to keep them from falling down. Mirrors feature original style ribbed bases. Includes mounting gaskets and hardware. Sold in pairs.

Note: Round mirrors are both standard glass, 4-1/8 diameter. O.E. is 4-3/4". Rectangle mirrors are LH standard RH convex

A94101 1966-72 round mirrors...... 217.99 pr A94102 1969-79 rectangular mirrors 217.99 pr



1963-79 Door Mirror with Convex Glass

Correct style reproduction outer door mirror featuring convex glass. The convex glass helps eliminate the passenger side blind spot. Each mirror includes the bracket, gasket and mounting screws.

Original Style Base and Bow Tie 985878C 1963-65 RH 66.99 ea Original Style Ribbed Base and Bow Tie CM3006C 1966-72 RH... 66 99 ca

Original Style Convex Ribbed Base 3014754C 1969-79 RH 66 99 ca



1966-67 Remote Door Mirror

OER® reproduction 1966-67 Chevy II/Nova LH remote mirror assembly. Includes: the mirror, cable, interior chrome bezel, mounting bracket, gasket, and mounting screws.

169 99 ca

Note: 1966 three cable design. 1967 all. 3899857 1966-67 LH



1968 Remote Mirror

OER® reproduction 1968 Chevy II/Nova LH remote mirror assembly. Includes: the mirror, cable, mounting

bracket, gasket, and mounting screws. 3921816 1968 LH

ō

•

Outer Door Mirror Components



74 Bullet Door Mirror

OER® reproduction bullet mirrors for 1973-74 Nova models. These mirrors were optional from 1973-74. The driver side mirror is remote and includes the cable assembly and adjustment knob. Each mirror is ready to prep and paint to desired color. Bracket, gasket and mounting screws available separately.

ste: The RH mirror does not include the words "Objects In Mirror Are Closer Than They Appear' 9865801 1973-74 LH remote 159.99 ea



1973-77 Door Mirror

Correct reproduction exterior side view mirror for 1973-77 Nova model. Each reproduction mirror includes the bracket, gasket, and mirror to bracket mounting screw. Fits LH or RH.

9826594 1973-77 LH or RH



Billet Door Mirrors Billet Rides universal side mirrors blend style and

elegance with craftsmanship and functionality. They have been designed to fit either side of any vehicle with door mounting holes between 1-1/2"-2-1/2". These mirrors feature an articulating pivot ball that can be tightened and locked in place. Hardware included gaskets sold separately. Sold individually.

Note: "With fasteners" denotes the decorative Hex head fasteners that run up the leading edge of the mirror.

Round			
BR1003	polished	with fasteners	259.99 e
BR1004	gloss black	with fasteners	274.99 c
BR1005	brushed	with fasteners	264.99 e
BR1009	flat black	with fasteners	
BR1006	polished	w/o fasteners	259.99 e
BR1008	gloss black	w/o fasteners	274.99 c
Rectangui	lar		
BR1010	polished	w/o fasteners	259.99 e
BR1011	gloss black	w/o fasteners	274.99 c
BR1012	brushed	w/o fasteners	264.99 c
BR1013	flat black	w/o fasteners	284.99 e
Gaskets			



1973-74 Bullet Mirror Glass

0606231

OER® reproduction bullet mirror replacement glass for 1973-74 Nova models. ote: The RH glass does not include the words "Objects In

Mirror Are Cle ser Than They Appear 9606231 1973-74 LH 5.1" x 2.9".... 23.99 ea 9683156 1973-74 RH 5.4" x 3.2".... 23.99 ea

1970-79 Remote Mirror Door Panel Bezel



bezel retainer, adjusting knob retainer and screws. 3021833 1070-70

1964-66 Remote Mirror Pivot Plate

This is a reproduction of the remote mirror pivot plate for 1964-66 Chevy II/Nova models with a remote outside mirror. Note: For 2 cable design CM2330 1964-66.



K

1966-72 Door Mirror Mounting Set

OER® reproduction standard (non-remote) mirror mounting set for 1966-72 Chevy II/Nova models. Includes: correct reproduction mirror mounting bracket, gasket, and screw. R355 1966-72 LH or RH....



1968 Remote Mirror Mounting Kit

OER® offers an installation kit designed to install a remote outer door mirror. Includes: correct reproduction mirror mounting bracket, gasket, and screw R318 1968 IН



1973-74 Rullet Mirror Mounting Set 🔥

1973-7	reproduction 4 Nova mode mounting br	els. Inch	ides: co	rrect repro		
R313	1973-74	LH		1	3.99	



1963-72 Outer Mirror Bracket

OER® reproduction standard (non-remote) mirror mounting bracket for 1963-72 Chevy II/Nova models. Fits I.H or RH 7.99 ea 3821962 1963-65 with screw... 1966-72 6.99 ea



1966-69 Remote Mirror Mounting Bracket

	duction 1966-69 remote mirror s LH chrome remote mirrors.	mountir
3899859	1966-67	12.99 c
3921836	1968	16.99 c
C507659	1969	19.99 e
	/ 0	GET.



		llet mirror mounting nal style bullet mir	
20055804 20055839	1973-74 1973-74	LHRH	



3021835

991	1966-72	LH or RH	1.99 ca
994	1963-65	LH or RH	3.79 ca
ount	ing gasket for	1963-72 Chevy II/Nova	models.
		standard (non-remote	

1966-76 Remote Mirror Mounting Gasket OFR® reproduction 1966-76 remote mirror mounting

gaskets. Fit	s chrome re	emote mirrors.	
3899860 3921835	1966-67 1968-76	LH	
3921833	1908-70	LH	7.99 ea



		LH or RH	
--	--	----------	--

1963-74 Mirror to Bracket Screw 🗥

Reproduction mirror mounting screw for 1963-72 Nova models. Fits chrome or bullet mirrors. 8/32" thread. 9423325 1963-74 LH or RH



round









BODY COMPONENTS



Test Fit All Panels Prior to Paint and Installation:

Classic Industries® recommends test fitting all sheet metal panels prior to final paint and installation. Minor modifications including elongating mounting holes, adding additional shims, etc. are normal and may be necessary when installing sheet metal. It is important to note that hard driving conditions, like racing, can twist bodies and frames out of original tolerances. Poor body work from previous collisions can cause problems with the body structure that the panels are attached to. Some vehicles were manufactured with a unitized body (no frame) thus causing even the most minor accident to twist the body creating a situation that would cause sheet metal panel misalignments. Take into consideration that tolerances on classic vehicles are not nearly as exact as they are on modern vehicles. This is primarily due to the hand fitting of panels at the factory on most antique and classic cars as opposed to the robotics used in today's modern factories. All of these factors will affect the way your new reproduction sheet metal will install and fit on the car. There is really no such thing as a direct fit body panel when it comes to older vehicles.

Returns and Defects:

may occur during transit.

Prior to returning any defective body panel or sheet metal item to Classic Industries®, please contact our customer service department. Classic Industries® will not replace a panel, nor will we be responsible for freight on returns should it be deemed that the panel is not defective. See policies for more information.

For Best Results. Hire a Professional to Install the Panels:

Classic Industries® recommends that you hire a professional paint and body technician that has the skills, knowledge and experience necessary to install the new panels on your vehicle. A professional body technician will be able to prepare the panels for installation and repair any imperfections.

When Welding Sheet Metal Products . . . Save time when replacing sheet metal by using Classic

Industries® new, innovative "Weld-ThruTM" primed sheet metal products. Our all new coating process is designed to eliminate the unnecessary process of grinding or sanding the EDP coating off to ensure a solid and rust-free weld. This "Weld-ThruTM" primer requires minimal preparation and eliminates corrosion problems between overlapped panels and layered spot welds. It also minimizes heat zone problems, reduces panel distortion, and allows better penetration into the dense replacement steel to compensate for the older metal's impurities. Look for the "Weld-ThruTM" logo when purchasing sheet metal products to save time during installation of weld-on sheet metal repair panels.

Some Guidelines on EDP Coating

Many sheet metal products are delivered with a black electrophoretically deposited coating (EDP. or E-coat) for superior long-term corrosion protection, while others use a similar lacquer-based coating designed to provide protection for storage and shipping. Before panel installation, Classic Industries® recommends applying lacquer thinner with a shop towel to determine the type of coating. If the coating is removed by lacquer thinner, then it should be completely stripped from the product before any primer or paint is applied. If the lacquer thinner does not remove the EDP coating, it can simply be prepped, primed and painted without stripping.

Classic Industries® The Restorer's Choice™

Count on the Classic Industries®

Restorer's ChoiceTM symbol

whenever purchasing reproduction parts and accessories. You can be sure that each and every product displaying this symbol is manufactured correctly to exact specifications and fits the way the factory intended. Products denoted throughout the catalog with this symbol are officially approved by Classic Industries@ as a genuine restoration product. Look for the Restorer's ChoiceTM logo. The Classic Industries® symbol is your assurance

Made in USA

of quality.

Look for the "Made in USA" logo for products that are proudly manufactured in the United States







Quarter Panels and Skins



1962-65 Full Quarter Panel

Reproduction of the original rear quarter panel designed for use with 1962-65 Chevy II/Nova 2 door hardtop models. Manufactured in stamped steel to original factory specifications for an authentic appearance

and fit. This	s replaceme	nt is perfect for v	ehicles that
have rust ar	ound the wh	eel well or rear lo	wer section
		es not include the	
of metal ne	ar the top of	door jamb area. Sn f door jamb must l l re-welded to new	oe removed
Note: Shippe	d truck freigh.	t.	Driet Lington
4409685	1962-65	LH	269.99 ea
4409684	1962-65	RH	269.99 ea







1966-72 Nova Quarter Panels

Reproduction of the original complete quarter panel specifically designed for 1966-72 Chevy II/Nova models. Each quarter panel is manufactured in quality stamped steel and matches the original in quality and fitment. Not just a replacement skin, this panel replaces the entire quarter panel section including the door jamb, trunk gutter, upper sail panel, and more. Will attach at the original factory seams. Panel features a black electrophoretically deposited coating (EDP, or E-coat) for superior long-term corrosion protection. Ready to be prepped, primed, and painted without stripping. The quarter panel is complete and ready-to-install. These quarter panels are designed to fit 2 door models.

Note: Ship	ped truck fro	right.		Track breight
14339				
		2 dr hdtp		
8778517		2 dr sedan		
8778516	1968-69	2 dr sedan		
8756531		2 dr sedan		
8756530	1970-72	2 dr sedan	RH	249 99 ca



1968-69 Full Ouarter Panel

Reproduction of the original quarter panel with a detached sail panel included! Sail panel is detached from the quarter panel and must be welded on during installation. Features correct door jamb area. reinforced bumper bracket area, and side marker cutouts. Careful attention is paid to packing and shipping to avoid damages. These panels will fit 2 door coupe models only.

Note: Snipp	ea truck freigi	ur.	-	w
8778519 8778518	1968-69 1968-69	LHRH		



1962-65 Auarter Skin

Replace your original quarter panels with these reproduction skins. Each skin will install as original. This is an excellent replacement if you have rust around the wheel well areas. This panel offers a good fit and will install with minimal refitting. This is a partial quarter panel skin which extends to the center body line. Will eliminate all rust located around wheel opening. Each panel is manufactured to allow application of the chrome wheel opening moldings. These panels are excellent for convertibles due to the elimination of the sail panel area. Careful attention is paid to packing and shipping to prevent damages!

2 Door – 1	8" x 75"	fricklinker
1667277 1667276	1962-65 1962-65	144.99 ea 144.99 ea

Note: Shipped truck freight



1966-67 Ouarter Panel Skin

Replace your original quarter panels with these reproduction skins. Each skin will install as original. This is an excellent replacement if you have rust around the wheel well areas. This panel offers a good fit and will install with minimal refitting. This is a partial uarter panel skin which extends to the center body line. Will eliminate all rust located around wheel opening Each panel is manufactured to allow application of the chrome wheel opening moldings. Careful attention is paid to packing and shipping to help prevent damages during shipping Note: Shipped truck freight

129.99 ea

129 99 ca



1966-72 Quarter Panel Skins w/Door Jamb

Replacement quarter panel skin for 1966-72 Nova models. Manufactured with correct heavy gauge steel using new tooling, these quarter panel skins replace about 80% of the rear quarter. These panels are ideal when replacing the upper sail section of the quarter panel is not necessary. Carefully patterned after original quarter panels, each skin features all correct mounting holes and flanges and includes the door jamb area for a complete replacement. The featured door jamb area makes aligning the quarter skin during installation

Note. Ship	ped truck frei	ght.	Testings
153051	1966-67	LH	159.99 ea
153052	1966-67	RH	159.99 ea
152888	1968-69	LH	159.99 ea
152889	1968-69	RH	159.99 ea
152890	1970-72	LH	159.99 ea
152891	1970-72	RH	159.99 ea
		ATTEN	ADITED

AUTHORIZEI



1968-72 Quarter Panel Skin

Reproduction quarter panel skin for 1968-72 Chevy II/ Nova models. The skin extends to the top crease of the original quarter panel and is cut so it extends from the door jamb to the bumper area and includes precut side marker openings. The panel offers a good fit, will install with minimal refitting and will allow application of the wheel opening moldings. Each panel requires welding for installation. Professional installation is dad to ancura

Note: Shipp	SATTANI			
1668049	1968-69	LH	119.99 e	
1668048	1968-69	RH	119.99 e	a
1668051	1970-72	LH	119.99 e	a
1668050	1970-72	RH	119.99 e	a









1667279

1667278





YOU

Quarter Patch Panels



1973-74 Ouarter Panel Skin

Reproduction quarter panel skin is an excellent option if you have rust around the wheel well areas, dents or minor damage when replacing the full panel is not necessary. The skin extends to the top crease of the original quarter panel and is cut so it extends to all from the door jamb to the bumper area and includes precut fuel and side marker openings (when applicable). The panel offers a good fit, will install with minimal refitting and will allow application of the chrome wheel opening moldings.

Important: This panel requires welding for installation.

Professional installation is recommended to ensure proper fit. Note: Not for use on hatchback models. Shipped

1668053 1973- 1668052 1973-	119.99 ea 119.99 ea



1975-79 Ouarter Panel Skin

Replace your original quarter panels with these reproduction skins. Each skin will install as original except for the roof sail panel which is not included with this reproduction. This is an excellent replacement if you have rust around the wheel well areas. This panel offers a good fit and will install with minimal refitting. This is a partial quarter panel skin which extends to the top crease of the original quarter panel.
Will eliminate all rust located around wheel opening. Each panel is manufactured to allow application of the chrome wheel opening moldings. Careful attention is paid to packing and shipping to prevent damages! Not for hatchback models

1667343	1975-79	LHRH	118.99 ea
1667342	1975-79		118.99 ea



quarter panel from the area behind the rear bumper to the middle of the wheel well. These are partial quarter panel skins that extend to the center body line. This is a common rust area, and this is an inexpensive way to correct that problem. These panels have the side marker lamp cutouts and extend approximately 9-1/2" above the wheel well.

ant: Due to differences in the side marker holes, odifications may be required to match your models

Note: Shipp	ed oversize.			€ 0\$1	
1667285	1968-74	LH	21" x 56"	37.99 ea	



1962-79 Lower Rear Ouarter Patch Panel

Replaces the lower section of the rear quarter panel from the bottom portion behind the bumper area to the wheel opening. This patch panel will allow you to replace the commonly rusted area without replacing

ш	ile entire	quarter pain	CI.		
	DN93L	1962-65	LH	10" x 29"	
	DN93R	1962-65	RH	10" x 29"	
	663287	1968-74	LH	14" x 36"	
	663286	1968-74	RH	14" x 36"	
	667295	1975-79	LH	12" x 32"	
1	667294	1975-79	RH	12" x 32"	30.99 ca



1968-74 Lower Front Quarter Patch Panel

This patch panel replaces the lower front section from the front edge of the quarter panel to the center of the wheel well opening and extends up to the center body line. This patch panel will repair a commonly rusted out area on 1968-74 Nova models. A quality steel stamping, it extends approximately 9-1/2" above the wheel well

LH 20" x 33" .. 39.99 ea RH 20" x 33" .. 37.99 ea 1667283 1968-74 1667282



1968-74 Rear Quarter Center Patch Panel

Reproduction of the original center quarter repair panel for use with 1968-74 Chevy II/Nova models. Each panel is manufactured in stamped steel to original factory specifications featuring correct contours for an authentic appearance and fit. Replaces the wheel opening area on the rear quarter panel. Extends approximately 6* above the top of the wheel opening. This repair panel is a great way to replace the damaged or rusted wheel opening area without replacing the entire quarter panel. Has black EDP coating for rust and corrosion prevention

Note: Shipp	ed oversize.		OS1	
1667289	1968-74	LH	19" x 48"	45.99 ca
1667288	1968-74	RH	10" v 48"	45 99 ca



1962-65 Rear Outer Wheelhouse Panel

Reproduction rear outer wheelhouse panels for 1962-65 Chevy II/Nova models. Each panel is an exact duplicate of the original.

Note: Shippe	d oversize.	OSI	
	962-65 962-65	64.99 ea 64.99 ea	



1966-67 Rear Outer Wheelhouse Panel

Reproduction rear outer wheelhouse panels for 1966-67 Chevy II/Nova models. Each panel is an exact duplicate of the original. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics.

Note: Shipped oversize.				# US
N119	1966-67	LH	EDP coated	64.99 ca
N118	1966-67	RH	EDP coated	64.99 ea
N119W	1966-67	LH	Weld-Thru™	89.99 ea

Wheelhouse Panels



1966-67 Complete Rear Wheelhouse Panel

Reproduction complete rear wheelhouse panels for 1966-67 Chevy II/Nova models. This is the inner and outer wheelhouse welded together. Available with traditional EDP coating or in a Weld-ThruTM Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics.

Note: Ship	- OS1			
14380	1966-67	LH	EDP coated	169.99 ea
14381	1966-67	RH	EDP coated	169.99 ea
14380W	1966-67	LH	Weld-Thru™	179.99 ea
14381W	1966-67	RH	Weld-Thru™	179.99 ea



1968-74 Rear Wheelhouse Panel

Reproduction wheelhouse panels for 1968-74 Nova models. Each panel is an exact duplicate of the original.

Note: Shi	pped oversize.		_
Inner W	heelhouse P	anels	0S1
14994	1968-74	LH	89.99 c
14995	1968-74	RH	89.99 e
Outer W	heelhouse P	anels	
C2468	1968-74	LH	59.99 c



Factory Nova models featured fairly small tires by today's standards. These cars cry out for bigger tire and wheel combinations which will not fit in stock form. The 1966-67 units increase to a 36" opening. The 1968-74 units increase the factory opening to 37 without altering the original width or height.

. tote. simpl	oed oversize.	-
F13700	1966-67	234.99 pr
F14700	1968-74	234 99 pr

1968-79 Lower Rear Cross Rail

Replace your rusted lower rear cross rail on your 1968-72 Nova with this quality reproduction. This rail mounts underneath the rear end of the trunk floor Note: Shipped oversize ∠ 0\$1



1968-72 Rear Cross Rail

14998

17.99 ca

Replace the bent, damaged or rusted original rear cross rail on your 1968-72 Chevy II/Nova. The rear cross rail installs behind the rear bumper and it mounts to the tail panel and the lower rear cross rail. 14998 features the upper and lower rear cross rail.

	ludes#14996. Shipped oversize. ear Cross Rail Only	081	
14997	1968-72	119.99	ca
Rear Cre 14998*	oss Rail Assembly 1968-72	199.99	ca
	4		



1968-77 Rear Cross Rail Filler

Reproduction of the 1968-72 rear cross rail filler panels for all Chevy II/Nova models. Each cross rail filler is manufactured in stamped steel to original factory specifications featuring correct contours for an authentic appearance and fit. This cross rail filler is spot welded at the end of the lower rear cross rail and fills the space left between the trunk floor and the rear cross rail. Black EDP coating for rust and corrosion prevention. 16111 1968-72 LH.. .. 17.99 ca





1966-72 Rear Frame Rail Rear Brace

Correct reproduction rear frame rail braces originally installed on 1966-72 Chevy II/Nova models. These stamped steel braces mount between the outside of the frame rail and the rear tail panel under the trunk area. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and

promotes	superior w	eld ch	aracteristics.	
14621	1966-67	LH	EDP coated	
14620 14621W	1966-67	RH LH	EDP coated	
14621W	1966-67	RH	Weld-Thru [™] Weld-Thru [™]	
16120 W	1968-72	LH	EDP coated	
16121	1968-72	RH	EDP coated	39.99 ea





1966-73 Rear Frame Rail

Restore the structural integrity of your 1966-73 Nova by replacing the damaged, bent or rusted frame rails with these reproductions. Manufactured to exact factory specifications to replace the original rails exactly. Each frame rail covers the entire trunk area from front to rear. Classic Industries® recommends professional installation. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics

Note: Ship	Note: Shipped double oversize.					
14617	1966-67	LH	EDP coated			
14616	1966-67	RH	EDP coated	249.99 e		
14617W	1966-67	LH	Weld-Thru™	269.99 e		
14616W	1966-67	RH	Weld-Thru™	269.99 e		
14992	1968-73	LH	EDP coated	249.99 e		
14993	1968-73	RH	EDP coated	249.99 e		











1968-72



COMPONENTS

Trunk Lids



1966-67 Trunk Divider

Reproduction trunk divider/package shelf for 1966-67 Nova models. Featuring all correct contours, back seat support bracing and rear speaker mounting locations, each panel will fit and install as original. Includes deck lid hinges and torsion rods. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics.

Note: Shipped truck freight. 15192 1966-67 EDP coated.... 429.99 ea Weld-Thru™ ... 429.99 ea 15192W 1966-67





1968-72 Package Tray Panel

Reproduction rear package tray panel for 1968-72 Nova models. Manufactured to factory specifications from new steel tooling, featuring premade speaker openings

and EDP coated for rust prevention. nte: Shipped double oversize. 4 692 1968-72... 169 99 69



1962-65 Trunk Floor Drop Off Reproduction of the original trunk floor drop off panel designed for use with 1962-65 Chevy II/Nova models.

Manufactured in stamped steel to original factory specifications replicating the original dimensions and design. This panel fills the area between the trunk

272	TRUN	K LIDS		
153131	1962-65	RH	49.99	ea
153130	1962-65	LH	49.99	ea
for rust a	nd corrosio	n prevention.		
		 Comes with black E 	DPcoat	ed



1962-67 Chevy II/Nova Trunk Lid 🔥

Reproduction trunk lid for 1962-67 Chevy II/Nova models. Each trunk lid is manufactured and stamped from steel as original. EDP coated to prevent rust, Will replace the factory trunk lid exactly.

Note: Shipped	truck freight.	THEOLOGIC
N249	1962-64	
N250		319.99 ea
7661139	1966-67	299.99 ca

ATTHORIZED



1968-74 Nova Trunk I id

Reproduction trunk lid for 1968-74 Chevy II/ Nova models except hatchback. Each trunk lid is manufactured and stamped from steel as original. Will install same as original with existing trunk lid brackets. Features EDP coating to prevent rust.

Important: *Modifications of lock hole is required to obtain proper clocking of lock cylinder.

Note: Shipped	i truck freis	pht.	-	w
		Restorer's Choice TM		



1966-72 Fiberglass Pin-On Style Trunk Lid

This is a fiberglass replacement of the original trunk lid assembly for 1966-72 Chevy II/ Nova. These high-quality replacements may be used for street, strip or show use. No provision for stock hinges. Attach with pins or fasteners.

Note: Shipp	ed truck freig)	ht.	Treat trapes
F13500	1966-67		281.99 ea
F14500	1968-72		284.99 ea



966-67 Trunk Lid Hinges

Reproduction trunk hinges for 1966-67 Chevy II/ Nova models. These high-quality reproductions are manufactured to exact specifications and will replace your rusty or damaged original trunk hinges. Sold as a pair

B16104 1966-67 159.99 pr



1966-67 Trunk Hinge Torsion Rods 🗥

Torque rods are essential for keeping your trunk stable in the open position. The torque rods apply pressure to the hinge to allow the trunk lid to remain open. These replacement torque rods feature the proper tension specifications and feature a black wrap for an original appearance.

15187 1966-67 torsion rods



1962-65 Trunk Lid Guides

Reproduction trunk lid guides for all 1962-65 Nova

15188 1962-65 9.99 pr



models. Sold as a pair.



1962-79 Trunk Lid Bumper

Correct replacement rubber bumper which applies to the body and lid assembly for 1962-79 models. Sold individually. 2 required

4721222 1962-67 5/16* thick...... 1.99 ea 1/2" thick 1.99 ca 3/8" thick 2.99 ca Δ4447 1968-79 4767559 1969-79

AUTHORIZED





1962-74 Trunk Latch

Reproductions trunk latch for 1962-74 Chevy II/Nova models except wagons. Each latch is manufactured like original for perfect operation. 1962-72 1973-74 4753019 26 99 ea 20291279 34 99 ca

Trunk Components



AUTHORIZED



22.99 ea

19.99 ea

1962-74 Trunk Lid Catch Precise reproduction trunk lid catch for 1962-74 models. This catch mounts to the trunk lid, replacing your broken or missing trunk lid catch, to provide a precise and solid surface for the latch to hook onto. 153156 1962-65



152928 1966-70

153852





1962-70 Trunk Latch Striker Anchor

Reproduction trunk latch striker/catch mounting bracket designed for use with 1962-70 Chevy II/Nova models. This anchor is welded to the center of the rear body panel inside the trunk and the latch striker is then bolted on. Manufactured in quality stamped steel replicating the original in quality and design. Features black EDP coated for rust prevention.

7678550	1968-70	





1962-79 Trunk Lock Cylinder Gasket 📤 OER® trunk lock cylinder gaskets for various 1962-79

Chevy II/Nova models. These EPDM rubber gaskets are manufactured to factory specifications for an authentic fit and appearance. 4471426 1962-72 molded...... 4.99 ea



1962-79 Trunk Lock Handle Shaft 🔥

Correct replacement of the trunk lock cylinder to latch torque rod. This rod extends from the outer trunk lock cylinder to the inner latch assembly and allows the lock to engage when the key is turned.

CL2040 1962-79 2.49 ca



1962-72 Trunk Lock Retainer

Replace this often lost or broken item with a quality reproduction. Trunk lock retainers are now available for 1962-72 Chevy II/Nova models.

N3110	1962-65	13.99	
N3120	1966-67	13.99	ea
N3130	1968-72	13.99	ca
			_



1966-76 Trunk Lamp Assembly

This assembly is used to replace the old or worn out trunk lamp on your 1966-76 Chevy II/Nova. 1973-76 assemblies include lead wire.

36381 1973-76 31.	99 99	
-------------------	----------	--



Universal Underhood or Trunk Lamn 🔥

Add an under trunk or hood light to your car. Includes: bracket, bulb, internal switch, and wiring to install. TF900114 metal housing...



1964-79 Trunk Lamp Replacement Bulb

Correct replacement bulb for 1964-79 Nova models. Replaces the trunk lamp bulb on models equipped with a trunk lamp. 1003 1964-79



1962-74 Power Trunk Release

The Klassic Keyless system is a complete do-it-yourself set designed specifically to fit your 1962-74 Nova, and Nova SS. In this power trunk release set you will receive: 1 Power trunk latch, 1 manual push button, wire and wire loom, full color step-by-step instruction manual, trimming template, and all necessary hardware. This is everything you will need to install a factory style power trunk release system in your classic car. Note: May require some minor sheet metal trimming on some vehicles for installation.

KK009 1962-74 149.99 set



Power Trunk Lock Conversion

This set is designed to convert your vehicles manual trunk release to power release. A great addition when installing power door locks or a keyless entry system. Includes: actuator, push button, brackets, and wiring. PTI.1001



1966-67 Electric Trunk Release Add a modern touch to your classic Nova, an electric

trunk release. Set includes: latch, modified catch, bolts. wiring, electrical connectors, push button switch, and detailed instructions.

Note: Some metal trimming required, template included. 199 99 set M81001 1966-67









Correct replacement spring clip for 1965-67 station wagon models. G11399 1965-67 1 required











Trunk Accessories

Add or replace the original trunk mat with an all new Classic Industries® reproduction. Guaranteed to fit perfectly!









1962-79 Reproduction Trunk Mat 🔥

Excellent quality reproduction mats installed on 1962-79 Chevy II/Nova models, except hatchbacks. Each trunk mat is specifically die-cut for your particular year. Restore your trunk area by first painting the trunk with OEM type spatter paint for an original appearance and protection. Then install your new trunk mat. Your trunk area will look factory new again! D 11 - T - 1 Mai

	Rubber	' irunk wats	
Herringbo	ne		
N76000	1962-66	black/gray	39.99 ea
N76006	1967	black/gray	39.99 ca
N76007	1968-72	black/aqua	39.99 ea
Crowsfoot			
N76004	1962-66	black/gray	39.99 ca
Houndstoe	oth		
N76001	1967	black/aqua	39.99 ca
Foe	m/Felt B	acked Trunk M	ats
Houndston	oth		
N76005	1967	black/aqua	29.99 ea
Herringbo	ne		
N76002	1968-72	black/aqua	32.99 ea
N76008	1973-74	black/aqua	32.99 ca
N76003	1975-79	black/aqua	54.99 ca

Perfect Looking Trunk!



1968-72 Nova Trunk Panel Set This trunk panel set is the perfect way to beautify your

trunk area. There's no need to spend big bucks having it professionally paneled when this precut set fits in place exactly. Panels can be covered with vinyl, cloth or even carpet to achieve whatever custom look you desire. lote: Shipped double oversize. 052 CM53146 1968-72











1973-77 - A7400205



- These 2 stage trunk insulation sets feature:

 Dynamat Xtreme Damper Pads
- · Heat Shield Insulator Panels
- Spray Adhesive
- Sealing Tape
- Rubber Trunk Mat
- Illustrated Installation Instructions

1962-77 Insulator and Trunk Mat Set

Precut, ready-to-install insulation and rubber trunk mat set! Most vehicles have little or no insulation in the rear trunk floor area of the vehicle. QuietRide's new AcoustiTrunk floor mat and insulation sets can help you stop the noise, vibration and heat and dressup the trunk area as well! This is a great solution to quiet down the trunk of your vehicle, while adding a custom touch. Your choice of smooth, no logo design, or a 3D raised logo trunk mat.

Important: All models, except wagons,

	double oversize and ground only (to aerosol spray adhesiye.	no air	
1962-67		1057	
A7400201	without logo	191.99	set
A7400202	Nova script logo	220.99	set
1968-72			
A7400203	without logo	191.99	set
A7400204	Nova script logo		
1973-77			
A7400205	without logo	191.99	set
A7400206	Nova script logo	220.99	set
. 1174.0	amic c In I		



1962-79 Trunk Partition and Padding 🔥

between the trunk and back seat section. Rear jute which attaches to partition sold separately

VIJ000 1973-79 DIACK	29.99 ea
N15800 1975-79 black	
	19.99 ea
	19.99 ea
	21.99 ea
Note: Shipped oversize.	- 081

Original material jute padding which attaches to the trunk partition. Eliminates noise and helps insulate the trunk area

Note: Use	3M spray adhesive part #08090 for in	stallation.
RJ162	1962-65	15.99 ea
RJ166	1966-67	10.99 ea
RJ168	1968-74	10.99 ea
RJ170	1975-79	14.99 ea









Soare Tire Cover Reproduction spare tire cover manufactured in

the correct aqua/black or black/gray Houndstooth, Herringbone, Crowsfoot pattern. Each tire cover is specifically designed for 13", 14", or 15" spare. Fiberboard Tire Cover

Houndstooth

K/4255	13"	black/aqua	
K78007A	14"	black/gray	44.99 ea
K78008A	15"	black/gray	44.99 ea
K78007B	14"	black/aqua	
K78008B	15"	black/aqua	44.99 ea
Herringbone			
K78011C	15"	black/aqua	47.99 ea
Crowsfoot			
K74256	13"	black/gray	44.99 ea
F	elt Ba	cked Tire Cover	
Standard Ho	undstoe	oth	
K78000A		black/gray	34.99 ea
K78006A		black/aqua	34.99 ea
Space Saver	Hound	stooth	
K78000B		black/gray	34.99 ea
K78006B		black/aqua	

Jack Hardware



OER® Complete Trunk Refinish Kit 🔥

Restore the trunk area of your classic car to a factory original appearance and provide the ultimate protection from the elements. First prime the area to be painted. On bare metal, you should use a self-etching primer. Next, spray your base coat. Then spray your spatter coat and let dry thoroughly. Finally, coat the entire surface with our clear top coat to seal the surface. Contains everything you need to refinish the trunk of your classic vehicle including 2 cans of primer, 3 cans of spatter paint and 2 cans of clear top coat.

Note: Ships ground only. No air shipment.

	Buy the Kit and Save!	
With Stand	ard Gray Primer	
K51490	black and grav	104.99 kit
K51491	black and aqua	104.99 kit
K51492	gray and white	109.99 kit
With Self-E	Etching Gray Primer	
K51493	black and gray	109,99 kit
K51494	black and aqua	109,99 kit
K51495	gray and white	109.99 kit
Trur	k Refinishing Compon	ents
	tra can of a component?	
Primer On	ly - 20 oz. Cans	
K89576	standard gray primer	14.99 ca
K89560	standard gray primerself-etching gray	14.99 ea
Base Coat	Only - 20 oz. Cans	
K89578	flat black	14 99 ca
K89581	dark gray	14.99 ca
	at Only - 12 oz. Cans	
K51496	black and gray	12.99 ca
K51499	black and aqua	12.99 ca
K51498	gray and white	12.99 ca
		12.55 Cu
K51497	Coat Only - 12 oz. Cans	14.99 ca
KJ149/	clear top coat	14.99 ca
		OFF)



OER® Trunk Spatter Paint

Restoration grade spatter paint for the discriminating restorer who wants to accurately replicate the original texture and finish in their trunk. Produced by the original manufacturer for an authentic texture and color match. These water soluble paints are designed to be applied with a paint gun and do not require a clear coat. One

quart required per vehicle. Includes instructions. Important: GM originally applied trunk spatter paint with a Binks 2100 gun with a 200 tip and a 66 fluid nozzle with

130	quart	black and aqua	99.99	¢
131	quart	gray and white	99.99	c





1967-70 Bumper Jack Assembly 🔥

Exact reproduction of the original bumper jack assembly designed for 1967-70 Chevy II/Nova models. Each component is designed to replace the original and includes the jack base, jack stand, and wrench mounting bracket. The jack load rest bracket is available separately depending on the year and model. Note: Due to the inherent dangers of this type of jack, it is

mended for show use only 3909108 1967-70. 130 00 set



1967-74 Jack Base

Reproduction of the original trunk jack base designed for 1967-74 Nova models. This is an original style reproduction of the jack base that works and functions as original. The correct 1969 base is available and features the date code U69 that was correct for 1969 models only.

15138 1967-74 1969 (Date Coded-U69)..... 38.99 ea



1967-69 Space Saver Tire Inflator Bracket Reproduction bracket used to hold the space saver

spare tire canister in place. C101991 1067.60 early style 16 99 ca 1967-69 C341851 late style. 18 99 ca



1962-74 Spare Tire Clamp Anchor Plate Correct anchor plate for all 1962-74 models. Be sure

to protect your spare tire from unnecessary movement by making sure the spare tire anchor plate is correctly mounted. Acts as a clamp by holding the spare tire hold down rod in place after the nut is tightened. Manufactured in stamped steel including correct

mounting holes for installation.



1962-79 Spare Tire Hold Down Rod

Reproduction hold down rod used with all 1966-79 Chevy II/Nova models. Depending on the application, you may need to trim the hold down rod to the desired size. Includes extra threading for this purpose. We offer the spare tire hold down rod and nut for a complete replacement.

9785

h


993	1962-79	rod – 9 1/2"	5.99 ea
5616	1966-79	wing nut	4.99 ea



1966-79 Jack Wrench Storage Sleeve

Correct reproduction of the original storage sleeve for the trunk wheel jack and wrench unit. This special storage sleeve was found originally on 1966-79 Chevy II/ Nova models. Manufactured from quality rubber material, this sleeve slides over the jack in the trunk and then secures the wheel lug nut wrench. Features

COHECT I	ib design pa	itterii.		
781956	1966-79	2-1/4" wide	19.99	ea
781957	1966-79	2-3/4" wide	21.99	ea





K79000A

Jack Storage Bag

Handy jack and load rest bracket storage bag with snap

	a with reproduction riounds		ICI
acked materi	ial. Fits original jack assembl	y.	
79000B	black/aqua	15.99	ea
79000A	gray/black	15.99	ca





Reproduction of the lug nut wrench and jack handle for models with 3/4" Hex head lug nuts and also used to operate the tire jack. K1088 1962-79 3/4" Hex

K86










Trunk Pans







14354



1962-67 Trunk Pan

Reproduction trunk pans are available for 1962-67 Chevy II/Nova models. Each trunk pan is reproduced to factory specifications and will replace the entire bottom portion of the trunk area. Available as a set with fillers, or purchase separately. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics

Pan Set -	 3 Piece Set 		-	*
C3869*	1962-67	trunk pan	169.99	sc
Pan with	Filler Panels	Attached - 1 Piec	e	
14354*	1962-67	EDP coated	299.99	ca
14354W*	1962-67	Weld-Thru™	384.99	ca
Center Se	ction			
C3868*	1962-67	38-1/2" x 39"	69.99	ca
Filler Pan	iels			
C3865	1962-67	LH	47.99	ca
C2066	1062 67	PU	47.00	

Note: *Shipped truck freight.



1962-65 Trunk Gutter Brace

for 1962-	65 Nova mod inel and help	original trunk gutter s dels. These braces mo support the trunk gu	unt behind
153729	1962-65	LH	24.99 ea
153730	1962-65	RH	24 99 ca





1968-72 Trunk Pan

Reproduction trunk pan available for 1968-72 Nova models. Each trunk pan is reproduced to factory specifications and will replace the entire bottom portion of the trunk area. Available as a full pan with the well section, the sides and the trunk floor brace or purchase

Full Pan			frecientes de 100
16113*	1968-70		359.99 ea
153347	1971-72		329.99 ea
Center Sec			
C6834**	1968-72	39-3/4" x 31"	89.99 ea
Side Exter	isions		
C6833	1968-72	LH	69.99 ea
C6835	1968-72	RH	69.99 ca



1962-72 Trunk Floor Brace These replacement braces attach to the underside of

CM4203

the trunk pan and provide the anchor points for the fuel						
tank mounting straps. Will fit and install LH or RH.						
CM4205	1962-67	LH or RH				
N111	1962-67	LH or RH (USA)				
16114	1968-70	LH or RH				
153348	1971-72	LH				
153360	1971-72	RH	59.99 ea			



1962-74 Trunk Floor to Quarter Filler

CNIOOI

Reproduction quarter panel fillers located between the trunk pan extension and the quarter panel. Available as a set with fillers, or purchase separately. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes

superior we	ld characte	ristics.	
153130	1962-65	LH	
153131	1962-65	RH	
N1633L	1966-67	LH - EDP coated	
N1633R	1966-67	RH - EDP coated	
N1633LW	1966-67	LH – Weld-Thru™	
N1633RW	1966-67	RH – Weld-Thru™	56.99 ca
CM1001	1968-74	LH	
CM1002	1968-74	RH	29.99 ca



1968-72 Trunk Gutter Brace

Reproduction of the original trunk gutter side brace for use with 1968-72 Chevy II/Nova models. Each brace is designed and manufactured to replicate the original configuration and dimensions offering an authentic appearance and fitment. This brace mounts behind the tail panel and helps support the trunk gutters in the rear corners. Features a black EDP coating for

15106	1968-69	LH	39.99 ea
15107	1968-69	RH	
15108	1970	LH	
15109	1970	RH	
15110	1971-72	LH	34.99 ea
15111	1971-72	RH	34.99 ea



1962-79 Rubber Trunk Floor Pan Plug

These rubber plugs are designed to keep air and water from entering the trunk area. They are also used in other locations including tailgate, floor pans, lock and hinge pillars, roof panels and crossmembers on various models throughout the GM line from 1962-96. 1962-79 3/4" hole 2.49 ea 4805844 4805843

BODY COMPONENTS

18964

MELR

N2106W

1966-67

89 99 ca

Rear Body Panels

1962-65 Center Tail Panel

Reproduction center tail pan for 1962-65 Nova models. This piece finishes the lower trunk opening between the tail lamps. Features correct contours. EDP coating for rust prevention and includes the two wiring retainers. 153132 1962-65 130 00 00



1962-64 Tail Panel Assembly

Reproduction tail panel for 1962-64 Nova models. Manufactured to factory specifications, with tail lamp mounting panels, tail panel braces, and trunk lid striker included. Black EDP coated for rust prevention. Note: Shipped double oversize.

153679	1902-04		229.99
		1 2	

1966-67 Tail Panel Set

Replace the often rusty tail panel on your 1966-67 Chevy II/Nova. These panels form the lower trunk ledge above the rear bumper area and will fit all models except wagons. Available with traditional EDP coating or in a Weld-Thru™ Primer. Note: Shipped oversize.





1966-67 Tail Lamp Panel Assembly

1966-67 EDP coated.

Classic Industries® is offering this correct reproduction rear tail panel for 1966-67 models except wagon. This exact reproduction will install on all Chevy II/Nova models. Features mounting panel to install the tail lamp lenses. Manufactured in steel and EDP coated. Available with traditional EDP coating or in a Weld-Thru™ Primer. Note: Shipped double oversize. 289,99 ea

N2107W	1966-67	Weld-Thru™	339.99 ea
		A SHEET STATE	
			7736116
:			
			8785408

AUTHORIZED 1968-72 Tail I amn Panel

Reproduction rear tail lamp panel for 1968-72 models. This exact reproduction will install on all Chevy II/Nova models. Features the mounting panel to install the tail lamp lenses. Manufactured in steel and EDP coated.

vote: snippea	aoubie oversize.	-	
		119.99 ea	
3785408	1970-72	109.99 ea	I



1973-74 Tail Lamn Panel

Finally there's a solution to the rusty or damaged rear tail lamp panel on your 1973-74 Nova. We offer this quality reproduction which is stamped to match all of the factory body contours exactly. It's EDP coated for corrosion resistance and ready to prep and paint.

Note: Shipped double oversize N73741 1973-74 124 99 ca



1966-67 Rear Window to Trunk Panel

Reproduction steel body panel that installs between the rear window and the trunk lid for 1966-67 two door hardtop/sedan models. Panel covers the area between the trunk and window. Available with or without the studs to mount the clips for the exterior rear window molding trim. Note: Shipped oversize. CM6455 1966-67 without clip studs 69 99 ca



-		
		146371

1968-72 Upper Rear Outer Body Panel

Reproduction upper rear outer body panel which installs between the rear window and trunk lid. Replace your missing, damaged or rusted upper rear body panel with this quality reproduction. Available with traditional EDP coating or in a Weld-Thru™ Primer that requires minimal preparation, eliminates corrosion between overlapped panels, and promotes superior weld characteristics.

Note: Shipped oversize. 14637 1968-72 68 99 ca FDP coated 14637W 1968-72 Weld-Thm™ 109.99 ea





1962-67 Chevv II/Nova Tail Lamp Mounting Panel

Reproduction tail lamp mounting panels for various 1962-67 Chevy II/Nova models except station wagons. Available with traditional EDP coating. 54.99 ea N2101 1962-64 LH 1962-64 54.99 ca RH N2104 1966-67 LH. 59.99 ca N2105 1966-67 59 99 ca RH

N2107











POMPONENT HODY

Windshield Wiper Parts



1962-79 Windshield Wiper Arm

OER® reproduction of the original wiper arms designed for use on various 1962-79 GM vehicles. Each wiper arm is manufactured in stainless steel and painted replicating the original in appearance, quality and design. Arm measures approximately 13" from the wiper arm tip to the center of the wiper shaft. Accepts Trico or Anco blades with 1/4" bayonet style connector. Wiper arms are sold individually. For windshield wiper arm set, refer to part number # GS670.

GS677	1962-67	polished - 12-3/4"	59.99	pr
K589	1962-69	13" long	22.99	èa
GS670	1962-69	silver – 13" long	39.99	pr
GS674	1968-79	polished - 14"	49.99	рr





1962-69 Windshield Wiper Blades/Inserts Reproduction wiper blade assemblies and rubber refills/ inserts for 1962-69 Chevy II/Nova models. These blades will replace your worn out or missing originals.

Available for both Anco and Trico style wiper blades. Blade Assemblies 1962-67 GS675 Anco GS679 1962-67 Trico 15" 19.99 pr 3899508 1962-69 Trico 15" 19.99 ea Refills/Inserts 1962-67 Anco ... 11.99 pr GS679R 1962-67 Trico 15" repro... 15.99 pr



1962-67

Windshield Wiper Bullets

15" GM 10.99 ea

Eliminating windshield wiper arms on your classic vehicle? Cap off the wiper transmission with these chrome wiper bullets for that "finished look" wiper bullets .. C4041



1962-79 "AERO" Wiper Blades

308035

High-quality OER® reproductions of the "AERO" style wiper blades for 1962-79 models. These "AERO" blades are designed to better hold the rubber against the glass for a better wipe, and reduce blade lift at highway speeds.

Wiper Blad	es		
K164	1962-67	15"	72.99 pi
3980353	1968-79	16"	79.99 pi
Wiper Blad	e Refills		
K164R		15"	19.99 pt
3980353R	1968-79	16"	20.99 pi
		_	



Winer Blades

Trico wiper blades offer superior wiping in the harshest of weather conditions! Change out your blades, and when the rain begins to fall, you will have confidence that your blades will be ready. Available in 3 different options: Our Classic Series is designed to imitate the look of classic wiper blades featuring a bright silver finish. The Standard Series is a basic black metal construction blade. Finally our Premium Force Series wiper arm was designed to use the down force of the wind to contour to the shape of the windshield and create maximum contact. cr · c · orne

389	9508	15"		19.99	ca
	ndard Ser				
	224			3.99	ca
	225			7.99	
	226			7.99	ca
	227			5.99	
153	228	22"		3.99	ca
Pre	mium For	ce S	Series		
	229			12.99	ca
	230			14.99	ca
	231			14.99	ca
153	232	20"		14.99	ca
153	233	22"		16.99	00

Windshield Winer Arm Remover

Remove the wiper arm safely without possible damage with this windshield wiper arm removal tool. Y65750 4 99 ca



1962-79 Winer Arm & Blade Sets OER® replacement windshield wiper arm and blade

sets for 1962-79 Chevy Il/Nova models. Available with Anco or Trico blades. Sets include 2 arms and 2 blades. 1062.67 D966 Anco 76 99 set R867 1962-67 Trico (sedan/wagon) 79 99 set R871 1968-79 Δnco 69 99 set R872 1968-79 "AERO" 109 99 set



1962-74 Windshield Washer Nozzles 🔥

Exact in every way, these are a high-quality reproduction windshield washer nozzles for 1962-74 Chevy II/Nova models. Δ22223 1962-67 29.99 pr

1968-74

24.99 pr

1968-70 Windshield Washer Hose Set

Reproduction set includes replacement style ribbed hoses precut to factory lengths, correct pickup screen, tie straps and installation diagram.

748564 1968-70 replacement style 19.99 set



1970-75 Spray Connector Tee GM replacement T-connector for all 1970-75 models.

G5135 1970-75 2.99 ea

1963-74 Washer Hose Tie Strans Straps used to hold windshield washer hoses to fender well. 3 straps are included.

K0143 1963-74 9 99 set

484718

Windshield Washer Parts





Glass Windshield Washer Rottle

Reproduction glass windshield washer bottle with antifreeze/washer solvent lettering on cap. This complete replacement set includes the mounting bracket. For use on virtually all early GM models

WB125 bottle, cap and bracket 39.99 set WB126

replacement cap ... 5.99 ea



1962-66 Outikleen Washer Bottle Decal Exact reproduction washer bottle decal for 1962-

66 Chevy II/Nova models with Optikleen washer bottle. Each decal includes the correct type style with instructions for antifreeze, bug removal, and

temperature ratings. DC204 1962-66 Optikleen decal..... 7.99 ea



Universal Washer Bottle and Pump Set Universal washer bottle and pump for Nova models.

This set is for when you need a low maintenance high-quality washer pump and bottle. MP40100 24 99 set

1968-70 Washer Jar & Bracket

Includes the bracket, bottle, and cap. Is your original washer jar damaged? Is your bracket bent beyond use? Maybe it's time to replace your originals with Classic Industries® washer jar and bracket kit. The kit includes: the correct washer jar, attaching bracket and washer jar cap. We now offer this unique kit which fits 1968 through 1970 Chevy II/Nova models! Each kit includes the correct mounting bracket for installation. 1968-70



1962-70 Windshield Washer Jac 🔥 OER® reproduction jar which holds the windshield

washer fluid. This jar is for 1962-70 Chevy II/Nova models. Manufactured to factory specifications in the correct opaque white ABS plastic. The washer cap is sold separately.

3840083 1962-70. 11 99 ca



1971-79 Windshield Washer Jan OER® windshield washer fluid iar for various 1971-

specificati	II/Nova models. Manufactur ons in the correct opaque white er cap and hardware sold sepa	ABS plastic.
3990892	1971-74	23.99 ca
4961312	1975-79	23 99 ca





1962-70 Windshield Washer Jar Bracket

OER® windshield wiper jar brackets designed to fit 1962-70 Chevy II/Nova models. Constructed from high-quality stamped steel with rust preventative black EDP coating. 1962-67

19 99 са 548935 1968-70 10.99 ca



1962-79 Washer Jar Fluid Screen 🔥

The correct replacement filter screen used to eliminate dirt and other residue which could clog the washer hoses, water pump or washer nozzles. Replace your screen periodically for best results. 3986821 1962-79.. 4 99 ca



1962-79 Windshield Washer Jar Cap 🥕

These replacement caps are for 1962-79 washer iars. Genuine GM service replacement part or OER for vegre listed 3798372 1962-74 OER®.... 3.99 ea G8312 1975-79 5.99 ea GM











Windshield Wiper Parts





Our remanufactured wiper motors are the high-quality, low cost alternative to brand name motors. Why pay more?! Enjoy safety, performance, and reliability at a fraction of the cost of OE. We'll back that up with a 1-year manufacturer's limited warranty.

A40119	1963-67	1-speed	124.99	
A40120	1963-67		115.99	
A40121	1963-67	2-speed, 4 terminal	155.99	
A40140	1968-79	all	139.99	ea



1962-72 Selecta-Speed Wiper Motor

Classic Industries® offers this great upgraded wiper motor for 1962-72 Chevy II/Nova models. The Selecta-Speed wiper system contains a low profile, 7-speed wiper motor (with five different delays, a low and a high speed), rotary switch (complete with a billet knob), adapter plate and wire harness. The CNC aluminum adapter plate mounts the wiper motor to the stock firewall bolt pattern.

Note: This set includes a rotary wiper switch to replace the original slider switch. The dash must be modified for new switch to fit, and there is no provision to operate the

windshield	washer fun	ction.	
D121614		wiper motor set	
D121616		wiper motor set	
D121617		wiper motor set	
121401	1968-72	wiper motor set	
121501	1968-72	billet headlight knob	19.99 ea



1967-79 Wiper Motor Ground Strap 🔥

w/o hidden winers 3 99 ea

Reproduction wiper motor ground strap for various 1967-79 GM models equipped with or without hidden wipers. Manufactured to factory specifications for proper fitment and appearance. 1967-79 153795 w/o hidden wipers... 3.99 ea



1968-74 Two-Speed Hidden Wiper 🔥

Our wiper system is a modern, high-quality replacement for the old system. It is the only replacement wiper system that is completely hidden, fitting entirely within the airbox in the cowl! This allows you to remove the stock wiper motor. The wiper motor hole in the firewall can be covered up with the cover plate supplied in the set or you can weld in a patch panel to eliminate the hole entirely. Perfect for Pro Street cars or if you just desire a clean looking firewall. For models with concealed wipers.

Important: Very minor mod wiring through the firewall. odification is required to run the

	without Delay		
152820			
152822	1969-74	605.99 s	set
2-Speed	with Delay		
152821			
152823	1969	653.99 s	set



1963-79 Windshield Washer Pumn 🔥

Replacement windshield washer pumps for 1963-79 Nova models. The pump circulates water from the windshield washer jar to the washer nozzles. This is a Delco service replacement part which may differ cosmetically from the original motor. However, it will fit and function correctly

Note: For use with Delco wiper motors. Not for use with

	1963-74 1975-79	59.99 15.99		
--	--------------------	----------------	--	--



1962-75 Washer Pump Repair Set

This washer pump repair set will replace the top of the pump which includes the hose connections, the pump gaskets and mounting screws. The set is designed to stop leaks which may occur over time and repair non-

OER® reproduction grommets used to mount the wiper motor to the firewall. These reproductions feature the original type steel sleeve built directly into the grommet, ground strap and screws with lock washers. 4010190



1968-74 Winer Motor to Firewall Seal

Circular seal fits between motor and firewall which prevents water from entering through the firewall area. This is a small gasket that can keep your interior free from water which can ruin your carpet and rust your floor pans.

1968-74 CA180 # AUTHORIZED



1968-79 Wiper Motor Link Arm 🔥

OER® Authorized windshield wiper motor to transmission link arms designed to fit 1968-79 Nova models. Includes link and ball stud pivot. 4918326 1968-79



1962-79 Windshield Winer Transmission

Reproduction of the windshield wiper transmission for 1962-79 Chevy II/Nova models. These are high-quality and include all links and pivots from the wiper motor to the spline output shafts that the wiper arms attach to. N2340 1962-67... 90 99 69 4918754 1968-79 94 99 ca



Wiper Transmission Mounting Screws

for 1964-79 Chevy II/Nova models. These are the correct screws that are used to mount the wiper transmission and feature the correct head style with washers included 153021 1064.70

functional washer pumps.

4014257 1062 75

à

COMPONENTS



Sheet Metal Tools

Blaircutter

Provides fast, accurate holes in materials up to 3/16" thick. These cutters provide a quality, virtually burr free hole. Available in seven sizes for 1/4" and

larger drill chucks. Spring loaded pilot "pops" the slug from the cutter. Buy the set and save! Set includes: all cutters, arbor and 3 extra pilots.

Note: D.O.C = depth of cut. Arbors and Cutters sold senarately Blaircutter Set 13218 11 piece 52.99 set

Arbor fo	r 1/4" and Larger	Chucks
13216	with pilot pin	11.99 ca
Replacer	nent Pilot Set	
	3 piece	6.99 set
	3/16" D.O.C.	
132001	1/4"	11.99 ca

132021 14.99 ca 132041 3/8" 12.99 ca 132061 7/16 21.99 ca 19.99 ea 132081 132101 9/16 24.99 ca 132121 5/8" 29 99 ca



Premium Spotweld Cutters

When you have a lot of spotwelds to remove, step up to the premium spotweld cutters for longer life in today's high strength body steels. These cutters have a heavier wall (.090") for extreme durability and two step geometry that splits the chips and helps clear them. Premium spotweld cutters have a fast cutting action and lasts for hundreds of spotwelds. They are for use in 3/8" or larger drill chucks. The spotweld cutters are available individually or in sets containing arbor, 3 cutters, your choice of 2 skip proof or 2 standard pilots.

11096	w/skip proof pilot w/standard pilot	39.99	set
11082	w/standard pilot	39.99	set
	ith Cutter		
11093	skip proof	24.99	ca
11094	standard	21.99	ca
11093 R	eplacement Parts		
11123	arbor	21.99	ca
11097	pilot - 3 piece	14.99	set
111083	cutters - 3 piece	26.99	set
11094 R	eplacement Parts		
11122	arbor		
11121	pilot - 3 piece	6.99	set
111083	cutters - 3 piece	26.99	set



Ideal for all Blair hole cutters. Softer than standard stick lubricants, it provides superior adhesion to the tool and can be used in place of cutting fluids on ferrous and non-ferrous metals to increase tool life, improve cutting performance and easier slug removal 11750 1.68.07



Double-End Spotweld Cutter

Double-end spotweld cutters makes removing body panels fast and easy Their hollow design cuts around the spotweld so weld hardness does not affect tool sharpness. When one end becomes dull, simply unscrew the cutter and flip it over using the new teeth on the other end. An adjustable depth rod sets the tool so only the outer panel is cut, leaving the

underity	ing panei undamaged.			
13224	arbor w/cutter	12.99	ca	
13214	replace cutters, 3 pc	12.99	set	
13216	replacement arbor	11.99	ca	
13217	replace pilot, 3 pc	6.99	set	



extended tool life. Holcutters produce holes from 11/16" up to 3" diameter in sheet metal, rubber, gasket or fiber materials, and some plastics. Ideal for aftermarket installations. custom fabrication, trailers, or gauge installation. Arbor fits 3/8' drill chucks. Holcutters have a new patented Ouad-Lead Thread System for quick cutter changes. Buy the set and save! Holcutter set includes arbor, hex washer, extra pilot and the following sizes of cutters, 7/8", 1-1/8", 1-1/4", 1-3/8", 1-3/4", 2", and 2-1/2". Note: D.O.C = depth of cut. Arbors and

Holcutter	r Set	
140061		154.99 se
Arbor for	3/8" and Larger	Chucks
146091		24.99 ca
Replacen	nent Pilot	
146101	3 piece	21.99 se
Cutters 1	/8" D.O.C.	
146221	11/16"	13.99 ca
146241	3/4"13/16"	13.99 ca
146261	13/16"	13.99 ca
146281	7/8"	12.99 ca
146301	15/16"	14.99 ca
146321	1"	12.99 ea
146341	1-1/16"	14.99 ca
146361	1-1/8"	14.99 ca
146381	1-3/16"	14.99 ca
146401	1-1/4"	14.99 ca
146421	1-5/16"	15.99 ca
146441	1-3/8"	15.99 ea
146461	1-7/16"	17.99 ca
146481	1-1/2"	14.99 ca
146501	1-9/16"	17.99 ca
146521	1-5/8"	17.99 ca
146541	1-11/16"	17.99 ca
146561	1-3/4"	16.99 ea



Blair Cutter Sets

Antenna and Access Holcutter Set Note: Each set includes: arbor, extra pilot drills, and cutters as shown. 14003 3/8", 1", and 1-1/4" 59.99 set Rustproofer Cutter Set Note: Each set includes: arbor, three 1/2" cutters, pilot and extra pilot. 11081 with standard pilot - 11122... . 49,99 set 11095 with skip proof pilot - 11123. 49 99 set Paintless Dent Removal Access Hole Set Note: Each set includes: arbor with standard pilot, extra pilot and cutters as shown 11083 1/4", 3/8", 1/2", and 3/4". 49.99 set

otabroach C	Cutter S	ets 🐠
-------------	----------	-------

Potabroach Cutter Set

11356 cutter Rotabroach annular cutters are ideal for sheet metal fabrication, paintless dent removal and for cutting rustproofing access holes without clogging. Unlike hole saws and twist drills that push and tear through materials, these cutters will make hundreds of holes in steel, sheet metal or plastics up to 1/2" thick with no deforming of stock, jagged edges or out-of-round holes. Arbors for Rotabroach cutters fit 3/8° and 1/2° hand held drill chucks and use either spring loaded pilots or skip proof pilots which eliminate predrilling operations. Each set includes: arbor, Hex wrench, center punch, extra pilot and a variety of cutters as listed. Note: D.O.C = depth of cut. Arbors and cutters sold separately.

<i>company</i> Rotabroa	ch Replacement Cutters		Δ
11628 pilot for 11007 arbor.		19.99	set
11097 pilot for 11123 arbor.		14.99	
3 Pack Replacement Pilot 11121 pilot for 11122 arbor.		6.99	
	ll Chucks	34.99	ca
	20mm cutters with skip proof pilot	21.99	ca
	0mm cutters with pilot pin		
Arbor for 3/8" and Larger Dri			
11091 7/8", 1", 1-1/8", 1-1/4	", 1-3/8", and 1-1/2"	174.99	set
	14mm, 16mm, 18mm, and 20mm		
	". 9/16". 5/8". and 3/4"	64 99	set

Replacement cutters for Rotabroach cutter set. Available in a 3 pack or as individual cutters in a variety of sizes.

111003 111043 112063	5/16"		19.99 set 19.99 set 21.99 set		112073 112083 112093	7mm 8mm 9mm	24.99	se
3 Pack Ci		Depth	of Cut for	Use	with 1112.	2 or 11123 Arbor	31 99	_

2 Pack Cuttors 1/4" Donth of Cut for Use with 11122 Arbor Only

111083	3/8" 26.99 set	112123	12mm 31.99 set
111123	7/16" 26.99 set	112133	13mm 31.99 set
111163	1/2" 29.99 set	112143	14mm 39.99 set
111203	9/16" 31.99 set	112153	15mm 39.99 set
111243	5/8" 31.99 set	112163	16mm 39.99 set
111283	11/16" 41.99 set	112173	17mm 44.99 set
111323	3/4" 39.99 set	112183	18mm 46.99 set
112103	10mm 29.99 set	112193	19mm 47.99 set
112113	11mm 31.99 set	112203	20mm 49.99 set

Individual	Cutters 1/2" Dep	th of Cut fo	r Use with 1	1007 Arbor	
11336	13/16"	24.99 ca	11360	1-3/16"	37.99 ca
	7/8"	22.99 ca	11364	1-1/4"	39.99 ca
11344	15/16"	26.99 ca	11365	1-5/16"	41.99 ca
11348	1"		11366	1-3/8"	44.99 ca
11352	1-1/16"	33.99 ca	11367	1-7/16"	45.99 ca
11356	1-1/8"	34.99 ca	11368	1-1/2"	46.99 ca









146601 1-7/8"

146621

146641

146661 2-1/8"

146681 2-1/4

146721 2-3/8

146741 2-1/2"

146761 2-9/16

146781 2-5/81

2-1/16

2-3/4"

2-7/8



21.99 ca

21 99 ca

24.99 ca

25.99 ca

29 99 ca

29.99 ca

29.99 ca

31 99 ca

34 99 ca

34.99 ca

30 99 ca

39.99 ca

miss and it indicates exactly where the body filler is and includes a test plate to confirm accuracy. Never again wonder whether or not a vehicle has been in a wreck! The Filler Detective

solves the mystery every time. FDA0100 red.. 79 99 ca



EZ Rest Door Hanger

The EZ Rest door hanger enables a single person to quickly remove and/or install vehicle doors. The padded. removable side rails and plastic, ribbed base inserts allow for accurate positioning of the door. The easy on/off design quickly adapts to most floor jacks with a removable saddle and 30mm (1.18*) diameter saddle hole. Me: Floor jack is not included

S21870

S21900

145 99 ca

22 99 ca

Door Spring Tool

Compresses spring for easy safe removal. Slides safely over spring. Constructed of heat treated, high carbon steel



You can now easily adjust the hinges without the aggravation of trying to align by eyesight with this handy tool. Specifically designed to help adjust the hinges so they help to align the door.

V65800 45 99 ca

Door Bushing Tool

If you've ever tried removing a door hinge bushing with just a regular punch, you know it's a hassle. Luckily,

now there's the specially designed door bushing tool Its special design makes it easy to punch out bushings and align bushings when reinstalling. Offset design allows for easy access to all door hinges. Super tough alloy steel construction. \$21825

Body Tools



Door Aligning Bar

Finally, a convenient door aligning tool that will fit in our tool drawer! Features a Hex stub to use with a breaker bar and socket for additional leverage. S21845 38 99 69

Pro Paint Gauge

The Pro Gauge is a device which measures paint thickness. Factory paint is usually four to five mils in thickness. By using the Pro Gauge you can determine if the vehicle has been repainted. For instance, you can take measurements of about 4.5 mil around the vehicle but the hood may read seven mils on the Pro Gauge. That tells you the hood has been repainted

PG2437 84 99 ca



Fliminator Rust Remover

Before touching up paint, you first must remove all rust, wax, and dirt or the rust will return and the paint won't adhere. This unique tool will scrub away all dirt, rust, and wax. The results are touch up paint adheres. seals and blends smoothly into the rest of the paint. F3437 0 00 00



Body Dent Removal Tools

Pulls dented sheet metal back into place with our convenient tools. 13" long shaft with 1/2" - 13 UNC thread screw on our slide hammer permits high pulling force. 44.99 set X2290 slide hammer set X2290-76 replacement nose nut.....



Spot Weld Chisel Chisel tool to separate panels after the spot weld has

been drilled out. Drive the blade with a hammer from the end or the side through the panel seam. Panels are separated without damage. The blade is sharpened on three sides, and offset for clearance.

Note: The sharpened edges will wear with use. Resharpen on a grinding wheel.



Body Dent Removal Tools

The pull rod set includes: 4 pull rods with formed shank, 2 pick pulls with straight shank, straight edge and HS split point drill bit. \$20000 null rods

Cleco Sheet Metal Fastener Kit

Everything you need to secure sheet metal panels during the fit and alignment stage. The pliers can be used with all standard spring loaded fasteners and clamps. The kit contains: one pair of Cleco pliers, twenty-five 1/8" Kwik-Lok clecos and four side grip fastener clamps. Also available are individual components so you can add to your kit as necessary. Complete Vit

X9858	29 piece	49.99 kit
Clecos		
X9859	Clecos 1/8"	1.49 ea
X9860	Clecos 3/16"	1.49 ea
Side Gri	p Fastener Clamps	
X9862	3/4" x 1"	4.99 ca
Cleco Pl		
X9863	Cleco pliers	12.99 ea



These plugweld pliers make plug welding fast and easy. Panels won't separate and copper alloy pad prevents burn through, allows higher welding temperature and better penetration

\$23230 \$23231	pliersreplacement pad	36.99 ea 9.99 ea	



Vise Grip Flange Pliers

Preparing panels with an offset flange will produce a clean, flush fit. Work on up to 18 gauge sheet metal without removing panels from the vehicle. The added feature of "Vise-Grip" locking pliers allows for better leverage. Available with your choice of 1/2" wide nonslip jaw or wider 1" clamping surface.

1/2" wide jaw 13229 30 00 69 X9853 1" wide jaw 41.99 ea



Seam Buster HD Chisel

Easily separate spot welded or bonded panels. Save up to 15 minutes per panel replacement. Great for quarter panels, rocker panels and other pinch welded areas. Sharpened on two edges, the sharp end allows for penetration between panels and the side edge allows for side impact to drive the panels apart without damage. Made of super tough alloy steel. Cushioned handle

absorbs sh	ock.	icu nandic
S20015 S20016 S20017	straight	34.99 ea

ō

•

Body Chemicals





҈≫

J-B Weld Perma-Lock Threadlocker 🔥

J-B Weld Perma-Lock threadlocker offers a no spill, no clog or mess cap. OEM approved and can withstand 300 degrees F. Use blue for medium strength or red for high strength. Seals threads against leakage and prevents rust and corrosion. Great for use on rocker arms, stud bolts, frame bolts, fasteners, bushings, loose screws and vibration sensitive items. Made in USA IB24213 blue 13ml, medium strength 11.99 ea JB27113 red 13ml, high strength 11.99 ea



J-B Weld PlasticWeld

J-B Weld PlasticWeld will repair and rebuild any rigid or semi-flexible plastic including ABS, PVC and CPVC. Rebuild automotive trim, fiberglass parts and vinyl siding Bonds instantly with superior strength and does not shrink or pull away. Cure color is off white. Made in USA.

25ml Syringe Sets in 5 minutes	
JB50132 25ml syringe	5.49 ea
2 oz. Stick Sets in 20 minutes	
JB8237 2 oz	6.49 ca



Acryl-Red Putty 3M putties spread easily, dry fast, sand easily and offer minimum shrinkage. Each tube includes 21 ounces of

putty. 3M Rocker Panel Spray is a paintable coating that will match the factory applied textured coating on the rockers and stone throw areas of automobiles. Note: Due to current FAA regulations all aemsol spray cans must be shipped ground delivery.

05966 red putty for pinholes 27.99 ca

Rubberized Undercoating (A) 325



Note: Due to current FAA regulation: all aerosol spray cans must be shipped ground delivery K89570 19-3/4 oz. aerosol

TRUNK&FLOOR PAU

















Trunk and Floor Pan Repair Set

The KBS trunk and floor pan repair set allows you to restore your floor pan, trunk pan, or pickup truck bed back to new without producing any ugly weld seams. Our included step-by-step instructions make it easy and simple to use. After cleaning the area with KBS Klean (an industrial strength water based cleaner/degreaser), and KBS RustBlast (a powerful rust remover/metal etch), simply use the included BackBone reinforcing mesh and NuMetal epoxy putty to fill any small pin holes. Last, finish it off with a coat of RustSeal® for a restored finish without any weld scams. Each set includes: 1 gal. KBS Klean, 1 gal. RustBlast, 1 qt. RustSeal®, 1 lb NuMetal epoxy putty, 1 sq. yard BackBone Reinforcing Mesh, 8 oz. #1 Thinner, KBS paint spout, Nitrile gloves, mask, two brushes, stir stick and complete and detailed instructions.

KB590103 KB590203 KB590304 KB590504 KB591504	trunk/floor repair set trunk/floor repair set trunk/floor repair set trunk/floor repair set trunk/floor repair set	satin black silver gray	k			126.99 set 126.99 set 126.99 set 126.99 set 126.99 set
103		-	1	1	1	V











or sunlight



Press firmly to repair surface. Remove transparent film backing and expose to sunlight or KBS UV Light. Curing times depend on UV intensity between 5 minutes (sunny) and 50 minutes (cloudy)

KB70003

KB70013

Renair Patch

The KBS Patch is an easy to use, UV/sunlight activated repair patch. The fiberglass reinforced polyester patch is perfect for making watertight, durable repairs on engine parts, decking, fenders, gas cans, drain pipes, water tanks, PVC pipes, plastics, Plexiglas, fiberglass, metal, wood, concrete and more. The KBS patch is waterproof, will not rot or rust, requires no mixing, can be drilled or tapped, sandable and accepts paint in 1 hour. Sold in three different sizes. UV light available separately.

KB70101	KBS patch	3" x 6".		18.99
KB70102	KBS patch	6" v 9"		29 99
10070102	reno paten	0 4).		27.77
			LED UV Flashlight	
			andheld UV flashlight containing 51 Ultraviolet LED bulbs for gr	
coverage and	d is designed t	o cure the	KBS Patch when sunlight is not feasible or available. The KBS	UV Lie

ight includes batteries, features an aircraft aluminum alloy body and is water resistant. KB70109 KBS patch UV light... 19.99 ca

Nu-Metal Epoxy Putty News



1 pound

3.5 ounces black







22.99 ca 8 99 ca











black

YOO E

COMPONENTS



Bolts

Replacement bolts used on various GM vehicles. Black

A15783

		iece sets.
	Individual	
Dog Point T	ip with Free Spinning Washer	
A9480	1/4"-20 x 1"	.89 ea
A876257	1/4*-20 x 1-3/16*	.89 ca
Flat Tip wit	h Free Spinning Washer	
A9756	5/16"-18 x 1" with washer	.99 ca
Pointed Tip	with Hex Washer Head	
10084	5/16"-18 x 3/4" 5/16"-18 x 13/16"	.99 ca
10362	5/16"-18 x 13/16"	.99 ea
A784896	5/16"-18 x 1" 5/16"-18 x 1-1/4"	.99 ea
X600750		.99 ea
Dog Point T	ip with Hex Washer Head	
A3615	5/16"-18 x 3/4"	.79 ea
Pointed Tip	with Free Spinning Washer	
A15783	5/16"-18 x 7/8" with washer	.99 ca
A11109	3/8"-16 x 1" with washer	.99 ca
A11110	3/8"-16 x 1-1/2" with washer	1.29 ea
	10 Piece Sets	
Dog Point T	ip with Free Spinning Washer	
A9480K	1/4"-20 x 1"	7.99 set
A876257K	1/4"-20 x 1-3/16"	7.99 set
Elmt Tim mit		
	h Free Spinning Washer	
A9756K	h Free Spinning Washer 5/16"-18 x 1" with washer	
A9756K Pointed Tip	5/16"-18 x 1" with washer with Hex Washer Head	8.99 set
A9756K Pointed Tip K1551	5/16"-18 x 1" with washer with Hex Washer Head 5/16"-18 x 3/4"	8.99 set 8.99 set
A9756K Pointed Tip K1551 K1552	5/16"-18 x 1" with washer with Hex Washer Head 5/16"-18 x 3/4" 5/16"-18 x 13/16"	8.99 set 8.99 set 8.99 set
A9756K Pointed Tip K1551 K1552 A784896K	5/16"-18 x 1" with washer with Hex Washer Head 5/16"-18 x 3/4" 5/16"-18 x 13/16"	8.99 set 8.99 set 8.99 set 8.99 set
A9756K Pointed Tip K1551 K1552 A784896K K1553	5/16"-18 x 1" with washer with Hex Washer Head 5/16"-18 x 3/4" 5/16"-18 x 13/16" 5/16"-18 x 1" 5/16"-18 x 1-1/4"	8.99 set 8.99 set 8.99 set
A9756K Pointed Tip K1551 K1552 A784896K K1553 Dog Point T	5/16"-18 x 1" with washer with Hex Washer Head 5/16"-18 x 3/4" 5/16"-18 x 13/16" 5/16"-18 x 1" 5/16"-18 x 1-1/4" To with Hex Washer Head	8.99 set 8.99 set 8.99 set 8.99 set 8.99 set
A9756K Pointed Tip K1551 K1552 A784896K K1553	5/16"-18 x 1" with washer with Hex Washer Head 5/16"-18 x 3/4" 5/16"-18 x 13/16" 5/16"-18 x 1" 5/16"-18 x 1-1/4"	8.99 set 8.99 set 8.99 set 8.99 set 8.99 set
A9756K Pointed Tip K1551 K1552 A784896K K1553 Dog Point T A3615K Pointed Tip	5/16"-18 x 1" with washer with Hex Washer Head 5/16"-18 x 3/4" 5/16"-18 x 13/16" 5/16"-18 x 1-1/4" Tip with Hex Washer Head 5/16"-18 x 3/4" 5/16"-18 x 3/4"	8.99 set 8.99 set 8.99 set 8.99 set 8.99 set 6.99 set
A9756K Pointed Tip K1551 K1552 A784896K K1553 Dog Point T A3615K Pointed Tip A15783K	5/16 ⁻ 18 x 1" with washer with Hex Washer Head 5/16 ⁻ 18 x 3/4" 5/16 ⁻ 18 x 13/16" 5/16 ⁻ 18 x 1 1/14" 5/16 ⁻ 18 x 1 1/4" p with Hex Washer Head 5/16 ⁻ 18 x 3/4" with Free Spinning Washer 5/16 ⁻ 18 x 7.8" with washer.	8.99 set 8.99 set 8.99 set 8.99 set 6.99 set 8.99 set
A9756K Pointed Tip K1551 K1552 A784896K K1553 Dog Point T A3615K Pointed Tip A15783K A11109K	5/16 ⁻ 18 x 1" with washer with Her Washer Head 5/16 ⁻ 18 x 3/4" 5/16 ⁻ 18 x 13/16" 5/16 ⁻ 18 x 1-1/4" 5/16 ⁻ 18 x 1-1/4" 1/4"	8.99 set 8.99 set 8.99 set 8.99 set 6.99 set 8.99 set 8.99 set 8.99 set
A9756K Pointed Tip K1551 K1552 A784896K K1553 Dog Point T A3615K Pointed Tip A15783K	5/16 ⁻ 18 x 1" with washer with Hex Washer Head 5/16 ⁻ 18 x 3/4" 5/16 ⁻ 18 x 13/16" 5/16 ⁻ 18 x 1 1/14" 5/16 ⁻ 18 x 1 1/4" p with Hex Washer Head 5/16 ⁻ 18 x 3/4" with Free Spinning Washer 5/16 ⁻ 18 x 7.8" with washer.	8.99 set 8.99 set 8.99 set 8.99 set 6.99 set 8.99 set



GM vehicles. 9/16" Hex with flat tip with oversized free spinning conical washer. Black phosphate coated. B11964 3/8"-16 x 1-3/8" 4 piece .. 7 99 set



Correct replacement hood hinge bolts used on various GM vehicles 1964 and newer, 9/16" Hex with flat tip with 1" free spinning conical washer. Phosphate coated. B4244 3/8"-16 x 13/16" 8 piece 10.99 set





Replacement fender skirt bolts used on various GM

vehicles. 1/2" Hex with pointed tip with 1-1/2" oversized free spinning conical washer. Black phosphate coated. B11600 5/16" x 7/8" 2 piece......





Square Pierce Nut Set

Correct replacement square nut inserts used on various GM vehicles. Fits 5/16"-18 bolts. B10558 6 piece ... 6.99 set



OE Sauare U-Type Clip Nuts


Correct square nut style U-clip nuts used on various GM vehicles. 10 piece set. B11518 fits 5/16"-18 bolts 16.99 set







	o typo one muio	4
Replacement	J-clip nuts used on various GM	I vehicles.
Individual		
A5586	fits 1/4"-20 bolt	1.49 ea
3784845	fits 5/16"-18 bolt	1.79 ca
A5170	fits 3/8"-16 bolt	1.89 ea
10 Piece Sets		
A5586K	fits 1/4"-20 bolts	12.99 set
K1550	fits 5/16"-18 bolts	16.99 set



U-Type Clip Nuts Replacement U-clip nuts used on various GM vehicles.

	Individual	
U-Type Nut		
5571	fits #8 screw	
A2422	fits #10 screw	.99 ca
U-Type Extra	uded Nut	
3982098	fits 1/4"-20 bolts	1.99 ca
A8377	fits 5/16"-18 bolts	1.99 ca
A10055	fits 3/8"-16 bolts	1.99 ca
	10 Piece Sets	
U-Type Nut		
A5571K	fits #8 screw	6.99 set
A2422K	fits #10 screw	6.99 set
U-Type Extra	uded Nut	
3982098K	fits 1/4"-20 bolts	
A8377K	fits 5/16"-18 bolts	15.99 set

Correct high torque style U-clips used on various GM vehicles. Length is 51/64", center of hole to edge 5/16". Green phosphate coated. A14526 fits #8 screw



'-18 Weld Stud Sel

Correct replacement 5/16"-18 x 1-18" weld studs used on various GM vehicles. B11693 4 piece. 5 99 set





Battery Tray Bolt Sei

Correct replacement battery tray bolts used on various GM vehicles 1964 and newer. 1/2" Hex with flat tip with 1-1/8" free spinning conical washer. Black phosphate coated. B13716 5/16"-18 x 5/8" 2 piece...... 4.99 pr



C2005

A3155

C2004



Body Shims

Correct zinc-plated body shims used on various GM vehicles. Available in 10 or 50 piece sets. 1-1/4" x 1-1/8" with 3/8" Bolt Slot 1/16" 10 piece 5.99 set 1/16* 8.99 set 50 piece 6.99 set 10 piece A3156 1/8" 50 piece 12.99 set 1-3/4" x 1-1/4" with Offset 1/2" Bolt Slot A2452 50 piece 50 piece 0 00 set Δ2453 1/8" 12 99 set



External Tooth Lock Washers Correct style external tooth lock washers used on

various GM v	enicies. Zinc-piated.		
Individual			
A5254	1/4" i.d	.39	ca
	3/8" i.d	.39	ca
	7/16" i.d		ca
A5258	1/2" i.d		
A16676	5/8" i.d	.39	ca
10 Piece Sets			
A5254K	1/4" i.d		
A5256K	3/8" i.d	2.99	set
	7/16" i.d		
A5258K	1/2" i.d	2.99	set

5/8" i.d..

A16676K

Boby

15 99 set

A10055K

2.99 set





GM vehicles

10 Piece Sets

Individual A1011

9838109

A10220

A1011K

9838109K

A10220K

4492963

4492963K

Stud Screw



Stud Mounted Plastic Molding Clip 🔥

Correct style plastic stud mounted clips used on various

#4 x 5/8" individual...... #4 x 5/8" 10 piece set.....

Universal Molding Clips Replacement wire tail molding clips used on various

GM vehicles. Nuts sold separately Individual

3/4" long

3/4" long..

1-11/32" long

10 Piece Sets

1-3/4" long

2-1/2" long

1" long

4" long...

#10-24 Thread Size with Sliding Stud 1-5/8" long ..

3/4" long

3/4" long..

1" long..... 1-11/32" long

1-3/4" long

2-1/2" long .

gray ..

grav ..

A2744

A2752

A2789

#8-32 Thread Siz B13145

#10-24 Thread Size

#8-32 Thread Size B13145K

#10-24 Thread Size

A2744

A2752

A19807

A2754

A2744K

A19626K

A2619K

A2752K

A 19807K

A2754K

A19626 A2619



.. 1.79 ca

1.29 ca

9.99 set

6.99 set

0.00 set

99 ca

7.99 set

A2619

.79 ca








Universal Nylon Push-In Molding Clips

Replacement nylon tail style push-in molding clips used on various GM vehicles.

Individual			
A8843	3/4" long	.79	ca
A8398	1" long	.79	ca
A8399	1-1/4" long	.79	ca
A8386	1-3/8" long	.99	ca
A8400	1-3/4" long	.99	ca
10 Piece Sets			
A8843K	3/4" long	5.99	set
A8398K	1" long	5.99	set
A8399K	1-1/4" long	5.99	set
A8386K	1-3/8" long	7.99	set
A8400K	1-3/4" long	7.99	set
	- 6-		_



Universal Metal Push In Molding Clips Replacement metal tail style push in molding clips

used on various GM vehicles.

3917954K	1-1/4"	long, w/top spacer	14.99	set
10 Piece Sets A9965K		long		
A9965 3917954	1-1/4" 1-1/4"	long long, w/top spacer	1.49 1.99	



Universal Break Off Molding Clips

various GM trimmed the	t break off style molding clip vehicles. These clips are desig width of the molding, features off grooves. #10-24 nuts sold s	gned to be prescribed
Individual – A8581	Nylon 3"	1.59 ea
10 Piece Set A8581K	- Nylon 3"	10.99 set
A19378	ad Nut – Metal 3"	1.59 ea



A2561K

A2562K















Replacement molding clip retaining palnuts used on

Mastic sealer washers sold separately.
Individual

#8-32 Thre			
A2555	1/2" washer head	.69	ca
#10-24 Thr	ead Size		
A2557	1/2" washer head	.69	ca
A2558	3/4" washer head	.69	ca
#12-24 Thr	ead Size		
A2560	3/4" washer head	.69	ca
1/4" -20 Th	read Size		
A2561	5/8" washer head	.69	ca
A2562	7/8" washer head	.69	ca
	10 Piece Sets		
#8-32 Thre	ad Size		
A2555K	1/2" washer head	4.99	set
#10-24 Thr	ead Size		
A2557K	1/2" washer head	4.99	set
A2558K	3/4" washer head	4.99	set
#12-24 Thr	ead Size		
A2560K	3/4" washer head	4.99	set
1/4"-20 Th	read Size		



5/8" washer head. 7/8" washer head.

Peri-Keps Hex Nut

Correct replacement self-locking Peri-Keps nuts used on various GM taillight housings, 1/4" panel extensions and #14 stud taillights. 7/16" Hex with 7/8" o.d. toothed washer. 10 piece set. B12030K fits #14 stud size 13.99 set



Serrated Self-Locking Hex Nut Correct replacement self-locking nuts used on various

GM vehicles. Zinc-plated. Individual A14873 #10-24 .69 ca A14874 1/4-20 80 ca 10 Piece Sets A14873K #10-24 ... 4.99 set 1/4-20 A14874K 5 99 set









1 99 es

1.09 ca

1.29 ca

1.29 ca

1.79 ca

2.49 ca

1.79 ca

17 99 set

8.99 set

9.99 set

9.99 set

9.99 set

14.99 set



A19378K



10.99 set

4 99 set

4 99 set





Hex Head

Hex Washer Head

A 3401

A 2896

A10733

Hex Head

SN3403K

A2896K A3405K

A10733K

Individual 11502547

11501047

10 Piece Sets 11502547K

11501047K

A3400K A3401K Hex Washer Head 1/8" stud size



43405

Thread Cutting Nuts Replacement thread cutting pal-nuts used on various

GM vehicles. Hex head and Hex washer head, zinc-plated. Mastic scaler washers sold separately.

Individual

1/8" stud size.....

1/4" stud size

5/16" stud size...

10 Piece Sets

3/16" stud size......

Thread Cutting Nuts with Sealer Replacement thread cutting pal-nuts used on various GM vehicles. Hex washer head with sealer, zinc-plated.

1/8" stud size

Capped Molding Clip Nut

Correct style capped molding clip nut used on various

3/16" stud size

1/4" stud size....

5/16" stud size.

1/8" stud size 1/4" Hex...... 3.99 set 1/8" stud size 5/16" Hex..... 3.99 set

1/8" stud size 1/4" Hex...... 1/8" stud size 5/16" Hex......





49 ca

.49 ca

.49 ca

49 00

49 ca

49 ca

3 99 set 3 99 set

3.99 set

3.99 set

3.99 set

9.99 set

9.99 set

11502547K

1/8" stud size 1.19 ea

3/16" stud size 1.19 ea







RI

A2098 A2100







For 1/8" Emblem Stud

For 5/32" Emblem Stud









Replacement barrel nuts used on various GM vehicles.

A13964	fits 11/64" hole – nylon	.79 ea
MM2267	fits 5/32" hole	.69 ea
11293	fits 3/16" hole with sealer	.69 ea
5195	fits 1/4" hole	.79 ea
For 5/32" E		
8545	fits 7/32" hole	.69 ea
	10 Piece Sets	
For 1/8" Em	blem Stud	
For 1/8" Em A13964K	fits 11/64" hole – nylon	
For 1/8" Em A13964K MM2267K	fits 11/64" hole – nylon fits 5/32" hole	5.99 set
For 1/8" Em A13964K	fits 11/64" hole – nylon fits 5/32" hole	5.99 set 5.99 set

Individual





Individual 39 ea A3545 3/8"-16 .39 ea A3547 7/16"-14 .39 ea 10 Piece Sets .38"-16 2.99 set A3547K 7/16"-14 2.99 set A3547K 7/16"-14 2.99 set	Standard re vehicles. Zi	placement Hex nut used on var nc-plated.	ious GM
A3545K 3/8"-16 2.99 set	A3545		
	A3545K	3/8"-16	







Correct replace on various GM	ement window felt retaining vehicles.	clip used
Individual A18402	style 1	
A977664 A18395	style 2style 3	.79 ea
10 Piece Sets A18402K	style 1	
A977664K A18395K	style 2	6.99 set





Correct style Phillips 7/16" washer head roof rail retainer screw used on various GM vehicles. Also used on convertible top roof rail weatherstrip. Measures 1/2", black phosphate. SW600 individual... 40 ca P1004 24 piece set 4 99 set

36 piece set ..

R1095

B11248K Mastic Sealer Washer Sets

Replacement mastic sealer washers used to seal emblem studs and molding clips to the body on various GM vehicles. Use with molding nuts and thread cutting nuts. 7/16 25 piece...... 4.99 set D11245V B11445K 1/2" 25 piece..... 5.99 set B11248K 5/8" 20 piece. 5.99 set 99 set

13742F 11280F				
0	4	001	Q	•







Push-On I	Flat Nuts
-----------	-----------

Replacement push-on flat nuts used on various GM vehicles. Black phosphate coated. Individual

inaiviauai		
A2098	fits 1/16" stud size	
A2100	fits 3/32" stud size	.59 ea
A2099	fits 1/8" stud size	.59 ea
A2102	fits 5/32" stud size	
A2103	fits 3/16" stud size	
A3138	fits 5/16" stud size	.59 ea
10 Piece Set	5	
A2098K	fits 1/16" stud size	4.99 set
A2100K	fits 3/32" stud size	4.99 set
A2099K	fits 1/8" stud size	
A2102K	fits 5/32" stud size	
A2103K	fits 3/16" stud size	
A3138K	fits 5/16" stud size	4 99 set







Round Push-On Flat Nuts

Replacement push-on round flat nuts used on various GM vehicles. In divide at

A8863	fits 1/8" stud size	.69	ca
WA300	fits 5/32" stud size	.69	ca
A8865	fits 3/16" stud size	.69	ca
10 Piece Sets			
A8863K	fits 1/8" stud size	5.99	set
WA300K	fits 5/32" stud size	5.99	set
A8865K	fits 3/16" stud size	5.99	set
36 Piece Set			
748707	fits 1/8" stud size	12.99	set





Med	8/9
14037	**

14037	

	Pinch Clip	<u> </u>
Correct sty rehicles. A	rle metal pinch clips used on va vailable individually or in a 11 p	rious GM piece set.
14037	individual	1.49 ea
RVP041	11 piece set	11.99 set

Boby

286 **FASTENERS**

1960's GM vehicles.





Chrome Trim Screws

Replacement chrome-plated screws used on various GM vehicles. Sold individually or in 10 piece sets.

#9 Carasa	with Undersized #6 Head	
A1799	#8 x 3/4" with #6 head	79 ca
A1423	#8 x 1-1/4" with #6 head	.79 ca
A1932	#8 x 1-1/2" with #6 head	.79 ea
A1933	#8 x 1-3/4" with #6 head	.79 ea
#8 Screw 1	vith #8 Head	
2710	#8 x 3/4" with #8 head	.69 ea
A2716	#8 x 1-1/4" with #8 head	.79 ea
	10 Piece Sets	
#8 Screw 1	vith Undersized #6 Head	
A1799K	#8 x 3/4" with #6 head	
A1423K	#8 x 1-1/4" with #6 head	
A1932K	#8 x 1-1/2" with #6 head	
A1933K	#8 x 1-3/4" with #6 head	4.99 set
#8 Screw 1	vith #8 Head	
R493	#8 x 3/4" with #8 head	
A2716K	#8 x 1-1/4" with #8 head	4 99 set



Black Trim Screws

10 piece set



SW500K



3.99 set



Washer Head Chrome Trim Screws 🗘

Replacement chrome-plated screws used on various GM vehicles. Sold individually or in 10 piece sets.

	Individual	
	with Flush Free Spinning Wash	
A2774		.59 ca
2751	#8 x 3/4" large washer	.79 ea
	10 Piece Sets	
	with Countersunk Free Spinning	
Pointed Tip A2774K 2751K		3.99 set



Chrome Lens Screws

Replacement lens screws used on various GM vehicles. Available in standard or shouldered. Most 1964 and older vehicles used the standard type, most 1965 and newer vehicles used the shouldered type.

	ated Stainless Steel - 4 Piece Sets
MA2098	
B11620	#8-32 x 1" 7.99
s	houldered Lens Screws
Chrome-Pla	ated Stainless Steel - 4 Piece Sets
B11489	#8-32 x 5/8", 11/32" shoulder 7.99
B11108	#8-32 x 11/16", 3/8" shoulder 7.99
B11493	#8-32 x 11/16", 5/16" shoulder. 7.99
B11495	#8-32 x 3/4", 7/16" shoulder 7.99
B11488	#8-32 x 7/8", 1/2" shoulder 7.99
B10402	#8-32 x 7/8", 9/16" shoulder 7.99
K5241	#8-32 x 1", 5/8" shoulder 5.99
B10403	
B10550	#8-32 x 1-5/16", 15/16" shoulder 7.99
Chrome-Pla	ated Stainless Steel - 6 Piece Set
K5242	#8-32 x 1", 5/8" shoulder 7.99
Chrome-Pla	ated – 4 Piece Sets
	#8-32 x 5/8", 3/8" shoulder 6.99
5960939	#8-32 x 11/16", 3/8" shoulder 5.99
A9400119	#8-32 x 15/16", 5/8" shoulder 4.99
	ated - 8 Piece Set
5962696	#8-32 x 15/16", 1/2" shoulder 9.99





Seat Belt Bolts

Correct replacement seat belt bolts used on various GM vehicles.

	marviadar			
1990	1947-66 - 7/16" -20 Fine Thread			
	FB64 front – chrome	5.99 ca		
ews 🗥	B10193 rear	5.99 ca		
	1967-72 - 1/2"-13 Coarse Thread			
n various	SB193 front with 1/4" shoulder	6.99 ca		
ce sets.	SB194 front with 1/2" shoulder			
	SB195 rear without shoulder	6.99 ca		
sher	1973-93 - 1/2"-13 Torx Coarse Thread -	GM		
.59 ea	G9157 1-3/4" with 3/4" shoulder	19.99 ca		
.79 ea	G4201 1-1/8" without shoulder	5.99 ca		
	8 Piece Bolt Sets			
g Washer	1967-72 - Mounts 4 Seat Belts			
3.99 set	R559 without shoulder belts	42.99 set		
3.99 set	R560 with shoulder belts	42.99 set		





Voltage Regulator Bolt Sets

B10011K	1963-68	3 piece	5.99 set
B4588	1969-72		3.99 set
	-		

Voltage Regulator Well Nut Set



Radiator & AC Mounting Shoulder Bolts Correct replacement shoulder bolts used on various





Door Latch Screws

Cor

scre 1/4 B1:

		oval Phillips head	
		us GM vehicles fron	1965-81.
"-20:	x 5/8". Cadn	iium-plated.	
2527	1965-81	6 piece	5.99 set



Licanca Dista Mut and Conow

	Correct replacement license plate nylon nut insert and
	slotted pan head screw used on various GM vehicles.
42.99 set	K49067 4 piece (2 nuts and 2 screws) 2.99 kit
42.99 set	K49007 10 piece (5 nuts and 5 screws) 4.99 kit











BODY COMPONENTS



Wiring Harness J-Strap Retainer Clip

E322	1-1/2" 3.99
E321	2"
1253527	2-7/8" 9.99



Correct sty various GN	le wiring harness retaining clip I vehicles.	used on
HK206 B10740 B10274	single wire, thin mount single wire, thick mounts for 1/4" hole	4.99 pr 4.99 pr
B10727 152718	multiple wire clips taillight harness clips	4.99 pr





Wiring Harness Retainer Clip Correct style wiring harness retaining clip used on

153128

various GN	I vehicles.		
K0076	2 pin straps	black	4.99 pr
A8900100	1 pin strap-clip 2-3/4"	black	2.99 ca
A8900101	1 pin strap-clip 3-3/4"	black	2.99 ca
MN1216	1 pin strap-clip 3-1/2"	clear	.99 ca
MN1209	1 pin strap-clip 5"	clear	.99 ca
153127	T-clip 1.5"	gray	.99 ca
153128	strap-clip 6"	grav	1.99 ca



8733856

DOOL.	LAILII NUU	IN NAAI, VRIVIIIRI, I	JIIP 🔼
Correct sty various G	le spring ster M vehicles.	el anti-rattle rod clips	used on
B14057	1958-66	4 piece set	5.99 set





Spring	Steel	Rod (Clip	<u> </u>
rod clip	used or	n vario	us GM	vehicles.

Correct style	rod cli	p used on various GM vehicles.
Fits 5/32" B	od Dia	neter
		11/64" i.d 2.99 ea
3962782	RH	11/64" i.d 2.99 ca
Fits 1/4" Re		
		17/64" i.d 1.99 ea
TF700512	RH	17/64" i.d 1.19 ea



Nvlon Rod Clip

Correct st	yle rod c	lip used on various GM vehicles.
Fits 5/32'	Rod Die	
K4013	LH	1/4" hole size 1.99 ea
A20675	RH	1/4" hole size 1.99 ea



Lock Rod Clin

Correct sty GM vehicle	le spring steel rod clips used or	n various
3998009 A1013		2.29 ea 1.49 ea
G11399 7762203	Genuine GM	2.99 ca 2.79 ca
7702203		2.79 ea



Clove Rox Insert Screw Clin

	מוטדט שטא וווטטו ג טטו טוד טווף 🍱
Correct s GM vehi	tyle glove box screw clip used on various cles.
K1101	2 prong style

J-clip style..

11429



Glove Rox Screws

quality r	your missing or damaged screws w eproductions for a correct installat us GM vehicles.	
T1439	1947-66	1.99 set
K553	1967-81	3.99 set



4500027

Door Panel Retaining Clip

Correct style door panel clip used on various GM vehicles. Available in steel or nylon. 1/2" Stem Length, Clip-On

A11774

TF120145	steel pin	26 piece set			
4500027	steel	individual			
748562	steel	12 piece set	9.99 set		
1/2" Stem I	ength, Ster	n Dia: 5/16", Head			
A11774	nylon				
R385	nylon	12 piece set	7.99 set		
R384	nylon	16 piece set	8.99 set		
1" Stem Length, Stem Dia: 5/16", Head Dia: 3/4"					
A1023	nylon	individual	1.29 ca		



Door Panel Clip Plug 🔥	
Correct style door panel clip retaining plug used on various GM vehicles.	
Individual	

Individual 6280765 4853962	nylon plastic		.99 ea 1.29 ea
Sets 6280765K R894	nylon plastic	14 piece 12 piece	9.99 set 9.99 set



Door/Window Handle Retainer Clip 🔥

	nt spring steel retainer clip used o r door and window crank handle		ous
A9886	each	.89	ea
A9886K	10 piece set	5.99	set



Weatherstrip Retainer Clip

Replacement style push in retainer clip used on various GM vehicles. 5/8" Stem Length, 3/16" Stem Diameter 20540336 nylon white 1.79 ea

13/32" Stem Length, 13/64" Stem Diameter

BODY COMPONENTS







Interior Mirror Hardware Replacement interior mirror mounting screw and insert

bushing used on various GM interior mirrors. 565842 chrome screw . 3.99 ea 565801 insert bushing





Firewall Pad Retainer Clips

Correct style firewall pad retainer clips used on various GM vehicles.

		eter x 1-1/2" Lengt		
3868790		individual		
KW272A	rubber	4 piece set	12.99	set
		eter x 1-7/16" Len		
7642589		individual		
K1117		7 piece set		
K1118	plastic	9 piece set		
K1119	plastic	12 piece set	9 99	set





Push-In Retainer Clip Replacement style push in retainer clip used on various

GM vehicles. Head diameter 11/16", stem diameter 5/16", stem length 5/8"

480534 nylon dark gray..... 1.49 ea



Push-In Trim Panel Retainer Clip 🔥

Replacement style push-in trim panel retainer clip used on various GM vehicles. Head diameter 1/2". stem diameter 9/32", stem length 3/4". A1016 nylon black ..



Screw Type Push-In Retainer Clip 🔥 Replacement style push-in retainer clip used on various

GM vehicles. Phillips screw type with closed end. Head diameter 11/16", stem length 7/8". A1027 nylon black



Replacement style push-in retainer clip used on various

GM vehicles. Head diameter 13/32", 1 stem diameter, 9/32", stem length 9/16". 9 piece set. 748621 nylon black





Hose Clamp Sets

R085678

Correct Corbin style pinch clamps and Wittek tower style hose clamps used on 1958-72 GM vehicles. Tower clamps feature: WITTEK MFG, CO, CHICAGO. U.S.A. stamped on each clamp. Kits will also work

on 1973 and	newer vehicles.		
R085677	1958-68	15.99	kit
R085678	1969-72	21.99	ki



Corbin Wire Ring Hose Clamps

Correct style Corbin pinch clamp used on various GM vehicles. Most commonly used on 1955-68 vehicles. AU5354 5/16" i.d. hose 1.49 ea AU5356 3/8" i.d. hose..... 1.49 ca 5/8" i.d. hose 5355 2.69 ca AU5357 3/4" i.d. hose .. 1.99 ca 0852 1-1/2" i.d. hose..... 1.99 ca 1-3/4" i.d. hose.. 0853 1 99 ca



Tower Hose Clamps

0856

2.99 ca

2.99 ca

3 99 ca

332755

0855

2-5/16

Correct style Wittek style tower clamp used on various GM vehicles. Features WITTEK MFG, CO. CHICAGO, U.S.A. stamped on each clamp. 0857 1-1/16" 5/8" hose 2.99 ca 0858 1-3/16 3/4" hose 2.99 ca upper.....











Correct style pinch clamp used on various GM vehicles. Most commonly used on 1961-82 vehicles on fuel

K0052 TF700041	1/4" 5/16"	redyellow		
K0050	3/8"	olive green	1.19	ea
K0051	3/8"	black	.99	ea







Flat Band Side Screw Hose Clamps 🔥

		mmonly used on 1958-72 ve	
power stee		turn and water pump bypa	
23C	3/8*		3.99 p
154221			
154222	3/4"		3.99 e





Worm Gear Side Screw Hose Clamps

Replacement style stainless steel side screw hose clamps used on various GM vehicles. High-quality clamp with extra strength construction. Durable 200 series stainless steel 1/2" band and screw housing. One piece screw housing is interlocked onto band for extra strength. Cadmium-plated.

332010	#10, range:	1/2"-1-1/8"	1.99 ca
332012	#12, range:	1/2"-1-1/4"	1.99 ca
332024		1"-2"	
332028	#28, range:	1-5/16"-2-1/4"	2.49 ea
332032		1-9/16"-2-1/2"	
332040	#40, range:	1-3/4"-3"	2.49 ca



Side Screw T-Bolt Hose Clamps

Replacement stainless steel heavy-duty T-bolt hose clamps. High-quality clamp with extra strength construction. 3/4" band and bolt housing. #28, range: 1-3/4"-2" #32, range: 1-7/8"-2-3/16" 5.99 ca 5.99 ea #40, range: 2-1/8"-2-7/16"









0855 2-1/16

0856 2-1/4

0854